

Public Works (1896) Department.

G.O., No. 1069 J.

DATED 18 December

[Despatch Abstract.]

Breaches: Report from S.E. to Cuth, of
it in the Santarumian Kail and
immediately, what's consequent on the
recent heavy rains, record etc.

7. 19/12

19/12

GOVERNMENT OF MADRAS.
PUBLIC WORKS DEPARTMENT.

Irrigation.

Read—the following papers:—

From M.R.Ry. N. COMARASAWMY ACHARI, Supervisor, Tinnevelly, to the Executive Engineer, Tinnevelly Division, dated 21st November 1896, No. 690.

I beg to report that on account of recent heavy rains, some small breaches have occurred in the undermentioned tanks and channels in my section:—

Tinnevelly Taluk.

- (1) Ninarkulam branch channel, near Tinnevelly town, 40' × 14' × 5'.
- (2) Tinnevelly channel, west of Kupipakurichi supply sluice, 17 feet long 9 feet high.
- (3) Pillayarkulam tank.
- (4) Ponnakudiyan channel, east of Sirusengulam, 45' × 5'.

Sankaranayindarkóvil Taluk.

- (1) Marathoni Periyakulam supply channel, 84 feet long.
- (2) Do. tank, 75 feet long.
- (3) Do. tank, north of surplus weir, 30 feet long.
- (4) Achankulam tank, east of surplus weir, 18 feet long.
- (5) Do. supply channel, 12 feet long.
- (6) Periyur Periyakulam tank, 32' × 12' × 10'.
- (7) Perumbuthur Periyakulam channel, 80' × 15' × 4½'.
- (8) Do. 72' × 15' × 4'.

I have arranged to put the ring bunds in front of the above breaches. Estimates with other informations will be submitted later on, as soon as water subsides.

No. 5050.

Copy forwarded to the Superintending Engineer, VI Circle, for information. It is a matter for regret that these breaches should have occurred at a time when the division is already starved for funds.

29th November 1896.

(Signed) A. JOYCE,
Executive Engineer.

No 1333 T.N.

Copy submitted to the Chief Engineer for Irrigation, in continuation of this office No. 1332 T.N. of the 4th instant.

TRICHINOPOLY,
4th December 1896.

(Signed) O. V. BODDY, Lt.-Col., R.E.,
Superintending Engineer, VI Circle.

No. 237 I.

Submitted to His Excellency the Governor for information. The breaches reported are not serious.

10th December 1896.

(Signed) W. HUGHES,
Chief Engineer for Irrigation.

ORDER—No. 1069 I., dated 18th December 1896.

Recorded.

(True Extract.)

Under Secretary to Government,
Irrigation Branch.

To the Chief Engineer for Irrigation.
" Superintending Engineer, VI Circle.

End. T. K. Narayana Aiyangar.

1111

From Mr. J. V. Comarasamy Achari,
Supervisor, Tinnevely, to the Ex-
-cutive Engineer, Tinnevely, No. 80
of 21 November 1898: -

I beg to report that on ac-
-count of recent heavy rains some
small breaches have occurred in
the undermentioned Tanks & channels
in my section.

Tinnevely Taluk.

1. Dinakulam Branch channel
near Tinnevely town 40' x 14' x 5'
2. Tinnevely channel west of Kupi-
-pahurichi supply sluice 17 ft long
9 feet high
3. Pillayathulam Tank
4. Ponnakudiyam channel east of
Limseengulam 45' x 5'

Sankaranainarkoil Taluk.

1. Marathoni Periyakulam Supply
channel 84 feet long.
2. Marathoni Periyakulam Tank 75 ft.
long.
3. Marathoni Periyakulam Tank north
of surplus weir 30 ft. long.
4. Akankulam Tank east of surplus

meas 18 feet long.

5. Achankulam supply Channel
12 feet long.

6. Periyar Periyakulam Tank 32' x 12' x 10'

7. Perumbuthur Periyakulam Channel
80' x 15' x 4 1/2'

8 — — — 72' x 15' x 4'

I have arranged to put the ring
bunds in front of the above breaches.
Estimates with other informations
will be submitted later on as soon
as water subsides.

No: 5050 dated 24 November 1896.

Copy forwarded to the Super-
intending Engineer, Trichy, for
information. It is a matter for
regret that these breaches should
have occurred at a time when
the Division is already starved for
funds.

Genl. A. Joyce
Executive Engineer

No:

No: 1333-TD

Copy submitted to the Chief
Engineer for Irrigation, in con-
-tinuation of this office No: 1332-TD
of the 4' Embank.

Trichinopoly
4 Dec 1896

4/-

J. V. B. ddy.

Chob. R. B.

Super Engineer, Trichy

[Signature]

CHIEF ENGINEER
FOR IRRIGATION
-- 320.96
106 TIV

Proc. of floods in Dinnelky
Sanbaranamur Co. T. Taluk
Public Works (1896) Department.

CURRENT No. ~~105 TIV~~
11461

Order

From

See Engr's Report
11/12/96

No. 1333 TIV

Dated 4th December 1896.

Received 5th 12 96

Enclosures. 17. 12. 96

Spare copies

SUBJECT.

Floods -
submit report about
the breaches in Dinnelky
& Sanbaranamur co. T. Taluk
Subj -

Sub 5/12/96
Submitted to H.E.
The forerunner for
information. The
breaches reported are
not serious.

6/12/96 W.H.
12/12/96 J.G.

Recorded)

To Mr. Ch. Engineer
Sanbaranamur Co. T. Taluk

Yours
Yours
Yours

1896

5-12-96

D. E. J.

1896

0081
11/12/96

BACK PAPERS.

FURTHER PAPERS.

G.O.	No.	Department.	Date.
R	105	JN	4-12-96

G.O. <i>Receipt</i>	No.	Department.	Date.
R	107	JN	4-12-96
R	108	JN	7-12-96

11-11-96