M.R.O. 14—13,000—27-9-54

MADRAS RECORD OFFICE.

Government of Madras.

Revenue DEPARTMENT.

G.O. No. 1367 Press Mis.

246 246

Dated 18-6- 1867

Not to be folded or roughly handled

Proceedings of the Madras Government, Revenue Department, 18th June 1867.

No. 245. Read the following Proceedings of the Madras Government in the Public Works Department :—

Passing orders on the subject of placing the irrigation works in the Salem District in a proper state of repair from the Budget provision for "Minor tanks and channels." (Here enter 15th June 1867, No. 1,807.)

No. 246. ORDER THEREON, 18th June 1867, No. 1,357.

Miscellaneous. Ordered to be recorded.

(True Extract.)

(Signed) J. GROSE,

Under Secretary to Government.

Ext. S. T. Augustin.

No. 357. Read the following Proceedings of the Board of Revenue, dated 20th May 1867, No. 3,087 :—

Read the following letter from the Collector of Salem, to the Secretary to the Board of Revenue, dated 9th May 1867, No. 105.

With reference to your letter, dated 11th June 1866, No. 3,972, I have the honour to forward, in the prescribed form, a nominal list of important irrigation works which are most urgently in need of repair in this district.

Nominal List of Important Irrigation Works urgently in need of repair in the Salem District.

Talook.	Village.	Name of Irrigation work.	Total registered Nunjah Ayacut.	Tax payable on whole Nunjah Ayacut.	Average tax actually paid from 1840 to 1850.	Average tax actually paid from 1850 to 1860.	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.		Date of last repair.
1		2	3	4	5	6	7	8	9		10
				RS. A. P.	RS. A. P.	RS. A. P.		RS. A. P.		RS. A. P.	
Salem ...	Anoopur	Tank	6 2 15	36 14 0	.....	.....	4 10 8	23 8 3	Earth work	50 0 0	Not repaired for a long time.
									Stone do.	50 0 0	
									Sluice repair	20 0 0	
										120 0 0	
Do. ...	Vadagoothurumputty ...	Do.	10 9 2	60 14 9	.....	24 14 2	12 8 14	50 12 4	Earth work	25 0 0	Do.
Do. ...	Pullipatty	Do.	101 23 14	369 10 8	.....	286 13 2	101 23 14	369 10 8	Earth work	100 0 0	Breach of tank was repaired last year.
									Stone do.	150 0 0	
									Sluice do.	30 0 0	
									Channel do.	20 0 0	
										300 0 0	
Do. ...	Kamanakenputty ...	Pond	4 34 0	21 0 5	.....	.....	4 34 0	21 0 5	Earth work	25 0 0	Not repaired for a long time.
									Stone do.	20 0 0	
										45 0 0	
Do. ...	Paladipuram	Tank	51 17 15	523 4 4	.....	505 10 7	51 17 15	523 4 4	Sluice work	25 0 0	Do.
Do. ...	Mullamoopamputty ...	Do.	29 8 13	174 3 6	.....	128 0 3	29 8 13	174 3 6	Embankment work ...	70 0 0	Not known.
Do. ...	Kamalapuram	Small tank ...	206 17 8	1,372 5 1	.....	1,372 5 1	206 17 8	1,372 5 1	Earth and stone work	200 0 0	Do.
Do. ...	Do.	Large do. ...	172 10 7	1,096 2 9	.....	630 15 3	167 1 2	1,096 2 9	Do. ...	100 0 0	Do.
Do. ...	Veraputty	Anicut channel ...	87 24 12	806 9 6	.....	806 9 6	87 24 12	806 9 6	To remove mound ...	200 0 0	Repaired about 6 years ago.
Do. ...	Do.	Tank	37 20 5	341 11 1	.....	341 11 1	37 20 5	341 11 1	Do. ...	150 0 0	Do. do. 10 do.
Do. ...	Athiputty	Do.	29 0 13	116 1 4	.....	116 1 4	29 0 13	116 1 4	Stone work	70 0 0	Not known when repaired.
Do. ...	Do.	Pond	19 36 14	82 13 7	.....	16 7 6	19 36 14	82 13 7	Sluice work	60 0 0	Do.
Do. ...	Thoppaputty	Tank	270 32 13	1,860 7 5	.....	1,860 7 5	267 36 12	1,813 10 1	Stone work and earth work for channels ...	250 0 0	Do.
Do. ...	Kullagoomby	Do.	93 28 3	866 0 9	.....	623 3 9	93 28 3	866 0 9	Do. ...	100 0 0	Do.
Do. ...	Puttoopolium	Do.	188 0 11	1,446 4 2	.....	995 6 5	188 0 11	1,446 4 2	Sluice work	200 0 0	
									Earth and stone do. ...	100 0 0	Do.
										300 0 0	
Do. ...	Konariputty	Do.	111 25 4	1,014 1 8	.....	1,014 1 8	103 5 8	965 6 11	Stone and plaster work for calingulah ...	100 0 0	Repaired about 10 years ago.
Do. ...	Vadugum	Pond	23 38 15	223 5 11	.....	223 2 8	23 38 15	223 5 11	Sluice work	20 0 0	Not known when repaired.
Do. ...	Do.	Tank	46 29 13	350 15 5	.....	329 2 5	46 29 15	350 15 5	Do.	50 0 0	Do.
Do. ...	Anagalayam	Do.	395 31 14	1,500 15 5	.....	1,500 15 5	339 39 10	1,394 13 3	Earth work	35 0 0	Do.
Do. ...	Eachal	Do.	164 0 8	1,214 8 1	.....	1,214 8 1	164 0 8	1,214 8 1	Earth and stone work...	200 0 0	Stone work raised about 5 or 6 years ago

Nominal List of Important Irrigation Works urgently in need of repair in the Salem District.

Taluck.	Village.	Name of Irrigation work.	Total registered Nunjah Ayacut.	Tax payable on whole Nunjah Ayacut.	Average tax actually paid from 1840 to 1850.	Average tax actually paid from 1850 to 1860.	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.		Date of last repair.
1		2	3	4	5	6	7	8	9		10
				Rs. A. P.	Rs. A. P.	Rs. A. P.		Rs. A. P.		Rs. A. P.	
Salem ...	Ananthakistnaroya Samoodrum.	Tank.	62 6 1	408 1 11	.....	408 1 11	39 31 1	280 12 11	Sluice work	20 0 0	Not known when repaired.
Do. ...	Vaniembady	Do.	84 13 13	438 6 7	.....	376 14 7	84 13 13	438 6 7	Earth work and stone work for anicut channel	250 0 0	Do.
									Sluice work	20 0 0	
										270 0 0	
Do. ...	Pethamputty	Do.	61 2 11	341 11 9	.....	201 5 9	61 2 11	341 11 9	Plaster work for calingulah	50 0 0	Repaired by earth some 5 years ago.
									Earth work for bund ...	50 0 0	
										100 0 0	
Do. ...	Byroji	Anicut channel...	30 26 14	240 5 6	.....	240 5 6	30 26 14	240 5 6	Earth work	100 0 0	Repaired about 7 or 8 years ago.
Do. ...	Do.	Tank	12 33 14	105 12 6	.....	105 12 6	12 33 14	105 12 6	Stone and earth work...	100 0 0	Repaired about 10 years ago.
Do. ...	Mathumputty	Tank channel ...	41 3 6	222 9 1	.....	222 9 1	41 3 6	222 9 1	Do. ...	100 0 0	Do. 5 years ago.
Do. ...	... ...	Tank	37 13 7	278 1 8	.....	239 8 9	37 13 7	278 1 8	Do. ...	50 0 0	Do.
Do. ...	Chemagori	Channel ...	42 10 7	349 8 11	.....	349 8 11	40 7 6	331 8 5	To repair the stone work at the mouth of the channel.	50 0 0	Repaired about 2 years ago.
Do. ...	Do.	Anicut channel ...	96 34 10	777 4 1	.....	777 4 1	96 34 10	777 4 1	Stone work for anicut	25 0 0	Do 5 years ago.
									Earth work for channel	100 0 0	
										125 0 0	
Do. ...	Parumattamungalum ...	Tank	38 36 8	359 13 6	.....	296 4 1	34 14 7	321 14 4	Earth work	50 0 0	Repaired about 5 years ago.
									Sluice bund	25 0 0	
										75 0 0	
Do. ...	Ariyagoundenputty ...	Do.	52 8 4	438 15 6	.....	373 11 2	52 8 4	438 15 6	Earth work and sluice bund work.	100 0 0	Not known when repaired.
Do. ...	Mookoottupoliem ...	Do.	44 14 12	310 8 1	.....	305 0 11	42 19 8	276 10 10	Earth work for bund...	100 0 0	Repaired about 3 years ago.
Do. ...	Savoolliapuram ...	Do.	39 9 3	170 13 1	.....	178 12 8	37 7 5	167 8 7	Stone work for calingulah and earth work for water course	50 0 0	Repaired in Fusly 1269.
Do. ...	Paparaputty	Do.	64 34 12	780 1 7	.....	780 1 7	60 25 4	730 0 8	Earth work	100 0 0	Not repaired for a long time.
Do. ...	Vengamputty ... Mullur ... Annapoliem ...	Anicut for the three tanks.	299 28 7	2,169 12 7	.....	1,989 5 6	272 32 5	1,816 0 10	Stone and lime work for breached anicut	300 0 0	Not known when repaired.
Do. ...	Bulbadra	Anicut.	77 10 1	289 14 8	.....	204 6 8	67 32 8	250 6 0	For anicut repair ...	1,000 0 0	Fusly 1265.
Do. ...	Pannatgoodal	Tank	104 8 4	536 2 3	.....	536 2 3	103 9 0	530 4 4	Earth and stone work to raise the bund ...	200 0 0	Not known when repaired.
Do. ...	Palumattooputty ...	Do.	18 23 8	102 13 7	.....	102 13 7	15 8 2	82 8 10	For sluice	35 0 0	Do.
Do. ...	Do.	Anicut channel ...	56 18 14	281 13 11	.....	281 13 11	52 34 14	260 12 6	Earth work for channel	70 0 0	Do.

Nominal List of Important Irrigation Works urgently in need of repair in the Salem District.

Talook.	Village.	Name of Irrigation work.	Total registered Nunjah Ayacut.	Tax payable on whole Nunjah Ayacut.	Average tax actually *paid* from 1840 to 1850.	Average tax actually paid from 1850 to 1860.	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.		Date of last repair.
1		2	3	4	5	6	7	8	9		10
				Rs. A. P.	Rs. A. P.	Rs. A. P.		Rs. A. P.		Rs. A. P.	
Salem ...	Thisavilaku	Tank	313 25 12	2,126 13 7	.....	2,126 13 7	306 8 12	1,917 11 11	Earth and stone work...	400 0 0	In Fusly 1265.
Do. ...	Thoothamputty ...	Do.	37 0 3	263 8 5	.....	263 8 5	24 3 2	169 12 9	To raise the bund ...	70 0 0	Do. 1266.
Do. ...	Yalaumputty	Do.	94 19 15	594 11 4	.....	352 12 7	69 36 7	393 13 6	Do.	200 0 0	Not known when repaired.
Do. ...	Taramungalum	Do.	134 23 7	962 7 0	.....	831 11 3	110 12 14	885 13 11	To remove the earth on the bed of tank.	300 0 0	In Fusly 1266.
Do. ...	Omalur	Anicut channel...	249 2 13	1,409 0 6	.....	700 12 8	213 18 0	1,049 0 0	To repair channel and breach of anicut.	300 0 0	Not known when repaired.
Do. ...	Puchumputty	Tank	38 13 12	254 2 10	.....	94 12 6	29 32 9	180 3 10	To raise bund	100 0 0	Do.
Do. ...	Naikarapatty ...	Do.	13 6 3	101 0 1	.....	46 0 8	15 32 3	81 3 11	Do.	100 0 0	Do.
Do. ...	Gollaputty	Do.	45 16 6	268 2 3	148 11 5	150 5 2	40 11 9	222 11 3	Sluice work	50 0 0	Not repaired since 20 years.
									Earth work and stone work	70 0 0	
										120 0 0	
Do. ...	Moothuputty	Do.	25 30 6	132 12 9	97 13 8	55 11 10	24 5 14	126 3 10	To repair calingulah ...	70 0 0	Not repaired since 12 years.
									Sluice work	50 0 0	
									Earth work for bund ...	100 0 0	
										220 0 0	
Do. ...	Manathul	Do.	189 6 1	1,729 5 4	1,038 7 3	1,020 15 2	129 12 4	1,278 4 2	To repair calingulah ...	100 0 0	Not known when repaired.
									To plaster sluice ...	50 0 0	
									Stone and earth work ...	100 0 0	
										250 0 0	
Do. ...	Vanavasi	Do.	20 7 9	109 10 1	102 14 10	97 12 3	19 23 9	106 4 3	To level bund	20 0 0	Not repaired since 6 years.
									Stone work	50 0 0	
										70 0 0	
Do. ...	Sunarapatty	Do.	14 12 13	50 13 10	38 9 10	43 3 3	14 12 13	50 13 10	Earth and stone work for bund, stone work for calingulah.	100 0 0	Do.
Do. ...	Dachalumputty	Do.	9 3 14	28 3 10	28 3 10	28 3 10	5 4 1	15 13 6	To repair blocked sluice	15 0 0	Not known when repaired.
Do. ...	Katamputty	Do.	2 36 6	14 0 0	14 0 0	13 4 9	2 36 6	13 4 9	Do.	10 0 0	Do.
									Stone work for bund ...	25 0 0	
										35 0 0	
Do. ...	Rayaroundenputty ...	Do.	16 37 15	122 13 4	69 1 10	59 6 7	10 24 0	67 3 6	Earth and stone work ...	70 0 0	Not repaired since 10 years.
Do. ...	Arayamputty	Do.	12 11 10	102 13 4	27 7 0	35 14 8	1 2 5	8 3 2	Sluice repair	20 0 0	Bund repaired in Fusly 1265.
Do. ...	Salavodi	Anicut	9 3 1	80 4 1	29 5 3	17 3 4	4 6 0	34 9 3	Stone and earth work ...	70 0 0	Not repaired since 10 years.
Do. ...	Verakalputty ...	Tank	1 15 7	11 15 5	11 15 5	11 15 5	1 15 7	11 15 5	Calingulah work ...	10 0 0	Not known when repaired.
									Sluice repair	10 0 0	
										20 0 0	

Nominal List of Important Irrigation Works urgently in need of repair in the Salem District.

Taluk.	Village.	Name of irrigation work.	Total registered Nunjah Ayacut.	Tax payable on whole Nunjah Ayacut.	Average tax actually paid from 1840 to 1850.	Average tax actually paid from 1850 to 1860.	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.		Date of last repair.
1		2	3	4	5	6	7	8	9		10
				Rs. A. P.	Rs. A. P.	Rs. A. P.		Rs. A. P.		Rs. A. P.	
Salem ...	Aurcovaputty	Tank	80 27 10	625 12 6	435 6 5	476 0 4	80 27 10	625 12 6	Sluice repair	50 0 0	
									Level bund	100 0 0	
									To raise calingulah ...	50 0 0	Not known when repaired.
									Stone work for bund ...	70 0 0	
									Earth work	70 0 0	
										340 0 0	
Do. ...	Amakoohutty	Do.	22 33 7	134 15 5	124 4 7	109 3 4	19 3 8	130 15 7	To raise calingulah ...	50 0 0	Do.
Do. ...	Kasoovevadeputty ...	Do. ...	9 31 4	42 1 8	29 4 5	28 11 1	5 23 9	24 9 10	Earth work	20 0 0	Do.
									Stone do.	10 0 0	
										30 0 0	
Do. ...	Mullicoodi	Do.	16 31 9	109 14 4	86 7 2	81 0 4	13 30 10	95 11 3	Earth and stone work...	40 0 0	Do.
Do. ...	Kaligoundenoor ...	Do.	33 26 5	166 9 2	130 11 1	136 9 2	27 2 2	133 8 10	Do. ...	50 0 0	
Do. ...	Tharapuram	Anicut channel...	40 23 15	188 14 6	.....	128 14 1	40 23 15	188 14 6	Plaster work	500 0 0	Do.
Do. ...	Do.	Tank	403 26 11	2,506 7 11	.....	1,174 2 10	403 26 11	2,506 7 11	Earth work	200 0 0	Do.
Attur ...	Vellayur	Do.	79 6 7	1,029 6 6	442 13 2	732 4 5	70 0 10	327 1 1	Stone do.	58 7 0	
									Earth do.	10 15 6	
										69 6 6	
Do. ...	Thadayoor	Do.	501 0 9	5,[illegible] 8 6	3,374 9 2	4,755 14 10	416 1 12	4,399 10 1	Stone work	468 12 0	
									Earth do.	147 10 6	
										616 6 6	
Do. ...	Ponavasal	Do.	222 15 11	2,528 12 8	1,460 2 2	2,013 4 2	205 0 11	2,098 3 11	Earth work	110 10 0	
Do. ...	Sithari	Do.	105 13 3	1,421 9 8	957 3 4	853 7 6	96 8 11	1,145 1 1	Earth do.	91 9 7	
									Stone do.	149 6 0	
										240 15 7	
Do. ...	Poothoor	Do.	120 14 10	273 10 2	[illegible] ...	66 0 0	.....	.....	Earth work	154 0 6	
									Stone do.	150 1 3	
										304 1 9	
Do. ...	Yathapuram ...	Do.	196 2 7	882 5 4	608 1 4	676 1 6	123 5 11	676 1 6	Earth work	147 15 0	Not known.
									Stone do.	49 2 0	
										197 1 0	
Do. ...	Attanvum	Do.	15 6 4	139 11 4	103 15 10	118 0 3	13 7 5	110 7 7	Earth work	7 0 6	Do.
									Sluice do.	25 0 0	
										32 0 6	
Do. ...	Pethmanienpolem ...	Do.	39 12 8	267 7 3	204 6 1	203 14 5	30 13 8	237 6 9	Earth work	24 3 0	
									New stone do. ...	37 8 0	
									Channel do. ...	28 8 0	
									Earth do. ...	137 5 0	
										227 8 0	

Nominal List of Important Irrigation Works urgently in need of repair in the Salem District.

Taluk.	Village.	Name of Irrigation work.	Total registered Nunjah Ayacut.	Tax payable on Whole Nunjah Ayacut.	Average tax actually paid from 1840 to 1850.	Average tax actually paid from 1850 to 1860.	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.		Date of last repair.
1		2	3	4	5	6	7	8	9		10
										Rs. A. P.	
Ahtur ...	Navullur	Tank ...	222 14 6	Rs. A. P. 2,675 4 2	Rs. A. P. 1,132 3 7	Rs. A. P. 1,629 6 6	169 10 5	Rs. A. P. 1,804 13 8	New and old stone work	52 3 0	
									Brick and chunam ...	41 2 0	
										93 5 0	
Do. ...	Veraganoor	Do. ...	257 13 7	3,924 15 10	3,826 9 1	3,630 4 9	240 10 1	2,825 15 2	Old stone work ...	12 4 0	
									Earth do.	34 7 3	
									New stone do.	53 2 0	
										99 13 3	
Do. ...	Ramanaikenpoliem ...	Anicut channel...	72 4 0	480 4 0	330 0 0	390 0 0	55 8 0	309 1 9	New stone work ...	21 0 0	
									Channel do. ...	42 3 0	
									Earth do. ...	11 3 0	
									New stone do. ...	3 15 0	
										78 5 0	
Do. ...	Chinnasamoodrum ...	Anicut	275 7 0	2,537 15 11	1,466 8 0	2,041 11 2	266 2 6	2,273 0 1	New stone work ...	420 0 0	
									Brick and lime ...	120 0 0	
									Stone work	3 6 0	
										543 6 0	
Do. ...	Do. ...	Tank	115 0 0	1,256 0 0	952 11 2	1,075 4 9	98 12 2	792 10 9	Earth work	150 9 0	
									Old stone do.	50 10 0	
									New do. do.	35 10 0	
										236 13 0	
Do. ...	Pariyari	Do. ...	189 1 3	1,507 15 1	1,312 4 10	1,185 15 4	175 5 5	1,295 11 0	Earth work	77 4 4	
									New stone work ...	103 14 0	
									Old do. do. ...	35 15 0	
										217 1 4	
Do. ...	Do.	Anicut channel...	8 4 4	68 8 2	... ...	34 5 10	6 1 5	58 4 4	Channel repair ...	236 11 6	
Do. ...	Auraganoor	Tank	193 6 8	1,667 11 10	1,421 11 0	1,473 8 9	192 2 7	1,548 15 2	Earth work	193 14 8	
									Old stone do.... ...	29 11 0	
									New do.	35 10 0	
									Earth work for channel	11 11 6	
										272 15 2	
Do. ...	Thiaganoor	Do. ...	115 15 0	1,076 2 11	857 0 0	932 4 9	102 11 2	858 1 10	Earth work	154 7 10	
									Old stone do.... ...	62 8 0	
									New do.	243 12 0	
										460 11 10	
Do. ...	Do.	Anicut channel...	67 3 0	578 7 7	376 0 0	322 4 9	43 7 3	325 11 8	Channel repair ...	10 2 0	
Darmapury...	Anaseguram	Tank	291 0 0	1,463 0 0	1,361 0 0	1,340 0 0	268 0 0	1,304 0 0	Earth work	20 0 0	Repaired about 4 years ago.
									Stone do.	30 0 0	
									Bund do.	50 0 0	
										100 0 0	

Nominal List of Important Irrigation Works urgently in need of repair in the Salem District.

Taluk.	Village.	Name of Irrigation work.	Total registered Nunjah Ayacut.	Tax payable on whole Nunjah Ayacut.	Average tax actually paid from 1840 to 1850.	Average tax actually paid from 1850 to 1860.	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.		Date of last repair.
1		2	3	4	5	6	7	8	9		10
				Rs. A. P.	Rs. A. P.	Rs. A. P.		Rs. A. P.		Rs. A. P.	
Darampury	Yendoor	Tank	56 0 0	244 0 0	213 0 0	224 0 0	54 0 0	236 0 0	Earth work	100 0 0	Repaired about 15 years ago.
									Stone do.	100 0 0	
										200 0 0	
Do. ...	Pedammany	Do.	40 0 0	192 0 0	187 0 0	189 0 0	30 0 0	143 0 0	Stone work	70 0 0	Do.
									Earth do.	70 0 0	
										140 0 0	
Do. ...	Kristnaporam	Do.	186 0 0	575 0 0	557 0 0	565 0 0	186 0 0	575 0 0	Earth work	80 0 0	Do.
									Stone do.	20 0 0	
										100 0 0	
Do. ...	Kittayathumbully ...	Do.	7 0 0	34 0 0	2 0 0	2 0 0	7 0 0	34 0 0	Earth work	50 0 0	Repaired about 30 years ago.
									Stone do.	50 0 0	
										100 0 0	
Do. ...	Vengarambully ...	River anicut ...	30 0 0	172 0 0	112 0 0	150 0 0	28 0 0	157 0 0	Stone work	50 0 0	Repaired 15 years ago.
Do. ...	Do. ...	Anicut	9 0 0	37 0 0	22 0 0	23 0 0	8 0 0	33 0 0	Do.	20 0 0	Do.
Do. ...	Koomburahully ...	Tank	1 0 0	6 0 0	4 0 0	6 0 0	1 0 0	6 0 0	Earth work	50 0 0	Repaired about 20 years ago.
									Stone do.	20 0 0	
									Bund do.	10 0 0	
										80 0 0	
Do. ...	Do. ...	New tank ...	4 0 0	14 0 0	12 0 0	14 0 0	4 0 0	14 0 0	Earth work	30 0 0	Do.
									Stone do.	7 0 0	
									Plaster do.	23 0 0	
										60 0 0	
Do. ...	Mallasamudrum ...	Tank	17 0 0	104 0 0	99 0 0	97 0 0	17 0 0	104 0 0	Earth work	50 0 0	Do. 15 years ago.
									Stone do.	20 0 0	
										70 0 0	
Do. ...	Do. ...	Anicut	54 0 0	222 0 0	101 0 0	122 0 0	32 0 0	125 0 0	Stone work	48 12 0	Do.
Do. ...	Taramungalam ...	Tank	63 0 0	326 0 0	169 0 0	176 0 0	45 0 0	207 0 0	Earth do.	70 0 0	Do.
									Stone do.	25 0 0	
									Plaster do.	50 0 0	
										145 0 0	
Do. ...	Thangavadivelly ...	Nullah	16 0 0	65 0 0	61 0 0	62 0 0	16 0 0	65 0 0	Stone work for the breach	16 0 0	Not known.
Do. ...	Sivakallour	Tank	32 9 0	156 0 0	109 0 0	97 0 0	32 0 0	156 0 0	Earth work	10 0 0	Repaired about 4 years ago.
									Stone do.	15 0 0	
									Plaster do.	30 0 0	
										55 0 0	

Nominal List of Important Irrigation Works urgently in need of repair in the Salem District.

Taluk.	Village.	Name of Irrigation work.	Total registered Nunjah Ayacut.	Tax payable on whole Nunjah Ayacut.	Average tax actually paid from 1840 to 1850.	Average tax actually paid from 1850 to 1860.	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.		Date of last repair.
	1	2	3	4	5	6	7	8	9		10
				Rs. A. P.	Rs. A. P.	Rs. A. P.		Rs. A. P.		Rs. A. P.	
Darampury	Pollem	Tank	35 0 0	186 0 0	135 0 0	98 0 0	25 0 0	107 0 0	Earth work	5 0 0	Repaired about 20 years ago.
									Stone do.	5 0 0	
									Plaster do.	20 0 0	
										30 0 0	
Do. ...	Do.	Do.	14 0 0	57 0 0	35 0 0	31 0 0	13 0 0	32 0 0	Earth work	5 0 0	Do.
									Stone do.	5 0 0	
									Plaster do.	20 0 0	
										30 0 0	
Do. ...	Jarithalavoo	Small tank ...	23 0 0	119 0 0	99 0 0	96 0 0	23 0 0	119 0 0	Stone work	88 0 0	Not known when repaired.
Do. ...	Do.	Tank	27 0 0	142 0 0	136 0 0	139 0 0	27 0 0	142 0 0	Do.	15 0 0	Repaired 4 years ago.
Do. ...	Do.	Do.	251 0 0	1,119 0 0	985 0 0	1,096 0 0	250 0 0	1,114 0 0	To raise the bund of the tank	7,000 0 0	Calingulah repaired last year.
Do. ...	Sivady	Do.	16 0 0	81 0 0	40 0 0	46 0 0	9 0 0	42 0 0	Earth work	25 0 0	Repaired 20 years ago.
									Stone do.	10 0 0	
										35 0 0	
Do. ...	... ...	Anicut channel ...	281 0 0	1,667 0 0	819 0 0	1,117 0 0	128 0 0	565 0 0	Earth, stone, and plaster work	2,000 0 0	Repaired last year.
Do. ...	Audiander	Tank	34 0 0	119 0 0	Being Muta tank, no average has been calculated.	101 0 0	34 0 0	119 0 0	Earth work	10 0 0	Not known when repaired.
									Stone do.	30 0 0	
										40 0 0	
Do. ...	Sathianathapuram ...	Do.	24 0 0	83 0 0	Do.	82 0 0	23 0 0	58 0 0	Earth work	95 0 0	Do.
									Stone do.	65 0 0	
										160 0 0	
Namkal ...	Thallaiyapatty ...	Do.	245 8 2	1,656 14 8	1,641 15 3	1,695 15 8	224 6 6	1,578 12 10	Earth work	202 15 6	
									New stone do. ...	124 4 0	
										327 3 6	
Do. ...	Mohadary	Do.	391 9 13	1,472 9 6	591 8 6	1,021 10 0	199 3 12	1,140 8 3	Earth work	713 11 9	
									Old stone	45 15 0	
									New do.	170 10 0	
										930 4 9	
Do. ...	Vaarikary	Large tank ...	89 35 13	239 0 0		40 6 2	18 37 14	41 1 3	Earth work	333 2 0	
									Old stone do.	392 0 0	
									New do. do.	329 14 0	
										1,110 0 0	

Nominal List of Important Irrigation Works urgently in need of repair in the Salem District.

Taluk.	Village.	Name of Irrigation work.	Total registered Nunjah Ayacut.	Tax payable on whole Nunjah Ayacut.	Average tax actually paid from 1840 to 1850.	Average tax actually paid from 1850 to 1860.	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.		Date of last repair.
1		2	3	4	5	6	7	8	9		10
Trippatore...	Odaynuthur ...	Tank	45 29 4	Rs. A. P. 250 3 11	Rs. A. P. 127 8 4	Rs. A. P. 219 4 10	38 0 14	Rs. A. P. 205 12 9	Earth work	Rs. A. P. 100 0 0	
									Stone do.	100 0 0	
									Earth do.	100 0 0	
									Stone do.	150 0 0	
									Sluice do.	50 0 0	
										500 0 0	
Do. ...	Sitary	Do.	41 21 11	210 11 4	163 1 8	210 5 10	40 38 13	207 8 7	Earth work	50 0 0	
									Stone do. for bund ...	150 0 0	
										200 0 0	
Do. ...	Horatee...	Do.	18 14 9	90 5 9	45 0 11	72 3 0	18 9 9	89 12 7	Earth work	150 0 0	
									New bund	50 0 0	
										200 0 0	
Do. ...	Cholarapatty	Do.	61 17 1	274 6 5	186 5 1	181 8 5	55 14 12	245 10 3	Stone work	90 0 0	
									Bund	60 0 0	
									Repair of bund ...	50 0 0	
										200 0 0	
Do. ...	Keelcoppom	Do.	29 13 0	155 13 4	147 6 3	160 0 0	25 34 1	138 11 8	Sluice repair	35 0 0	
									Earth work	50 0 0	
									Stone do.	50 0 0	
										135 0 0	
Do. ...	Kumeenhe	Do.	114 13 1	320 15 0	239 8 8	266 9 1	68 15 12	309 8 8	Earth work	200 0 0	
									Stone do.	400 0 0	
										600 0 0	
Do. ...	Alvempatty	Do.	23 7 13	100 15 0	62 1 6	76 15 6	23 7 13	100 15 0	Earth work	100 0 0	
									Stone do.	100 0 0	
									Sluice do.	50 0 0	
										250 0 0	
Do. ...	Bungarumpuky ...	Do.	82 14 12	517 11 7	305 9 10	360 13 0	62 35 15	373 8 11	Stone work	150 0 0	
									Earth do.	100 0 0	
									Sluice do.	50 0 0	
										300 0 0	Last repaired in 1863.
Do. ...	Kondakindanapally ...	Do.	6 2 0	40 9 2	22 0 2	43 2 11	8 2 0	40 9 2	Earth work	75 0 0	
									Sluice do.	50 0 0	
									Stone do.	18 4 0	
										143 4 0	
Do. ...	Jankalpuram	Pond	21 26 6	80 4 10	.....	62 2 2	21 26 6	80 4 10	Earth work	50 0 0	Not known.
									Stone do.	100 0 0	
									Sluice do.	50 0 0	
										200 0 0	

Nominal List of Important Irrigation Works urgently in need of repair in the Salem District.

Taluk.	Village.	Name of Irrigation work.	Total registered Nunjah Ayacut.	Tax payable on whole Nunjah Ayacut.	Average tax actually paid from 1840 to 1850.	Average tax actually paid from 1850 to 1860.	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.	Date of last repair.
1		2	3	4	5	6	7	8	9	10
				RS. A. P.	RS. A. P.	RS. A. P.		RS. A. P.		
Trippatore ...	Jankalpuram	Tank	31 1 10	92 2 1	.....	90 4 2	31 1 0	92 2 1	Stone work ... ... 150 0 0 Earth do. ... ... 100 0 0 Sluice do. 50 0 0 300 0 0	Not known.
Do. ...	Do.	Fallan Pond ...	16 34 2	60 15 4	.....	40 3 10	16 34 2	60 15 4	New sluice ... ... 50 0 0 Do. calingulah ... 50 0 0 Earth work ... ... 50 0 0 Stone do. 50 0 0 200 0 0	
Do. ...	Umbulur	Tank ...	35 13 3	219 13 1	165 10 4	216 0 2	35 13 3	219 13 1	Earth work ... ... 700 0 0 Stone do. ... ... 324 12 0 Repair of sluice ... 70 0 0 Calingulah 50 8 0 1,145 4 0	
Do. ...	Thoreyarre	Puthu tank ...	19 9 1	61 2 10	.....	63 4 9	19 9 1	61 2 10	Earth work ... ... 57 8 0 Stone do. 122 0 0 179 8 0	
Do. ...	Do.	Pala tank ...	17 21 4	51 12 8	.....	46 8 1	17 21 4	51 12 8	Earth work ... 48 12 0 Stone do. ... 34 0 0 Sluice do. ... 35 0 0 Calingulah ... 20 10 0 133 6 0	
Utengarry...	Komarapatty	Nullah	100 0 0	372 0 0	163 0 0	246 0 0	100 0 0	372 0 0	... ... 300 0 0	
Do. ...	Punnarree	Tank	15 0 0	47 0 0	12 0 0	24 0 0	15 0 0	47 0 0	... ... 200 0 0	
Do. ...	Do.	Do.	13 0 0	41 0 0	20 0 0	13 0 0	8 0 0	27 0 0	... ... 150 0 0	
Do. ...	Kadamodeerpatty ...	Do.	12 0 0	37 0 0	15 0 0	20 0 0	8 0 0	26 0 0	... ... 100 0 0	
Do. ...	Soroveemutty	Do.	10 0 0	30 0 0	18 0 0	21 0 0	8 0 0	27 0 0	... ... 100 0 0	
Do. ...	Muruneepatty ...	Do.	14 0 0	43 0 0	21 0 0	26 0 0	7 0 0	20 0 0	... ... 80 0 0	
Do. ...	Timmeshetty	Tank	8 0 0	23 0 0	11 0 0	19 0 0	5 0 0	17 0 0	... ... 80 0 0	
Do. ...	Nacheemmutty ...	Do.	8 0 0	17 0 0	11 0 0	12 0 0	3 0 0	13 0 0	... ... 80 0 0	
Do. ...	Pudiaputtoora	Nullah	25 0 0	79 0 0	18 0 0	13 0 0	9 0 0	28 0 0	... ... 40 0 0	
Do. ...	Kuttahutty	Anicut	10 0 0	31 0 0	13 0 0	20 0 0	8 0 0	25 0 0	... ... 50 0 0	
Do. ...	Thoppurpetteeyan ...	Pond	5 0 0	15 0 0	1 0 0	8 0 0	4 0 0	13 0 0	... ... 25 0 0	
Do. ...	Vellakarathumputty ...	Tank	52 0 0	287 0 0	32 0 0	83 0 0	31 0 0	167 0 0	... ... 300 0 0	1865-1866.
Do. ...	Thirumuthipoompatty ...	Do.	0 0 0	34 0 0	18 0 0	26 0 0	4 0 0	17 0 0	... ... 70 0 0	
Do. ...	Anulamutty	Do.	0 0 0	59 0 0	46 0 0	46 0 0	8 0 0	45 0 0	... ... 50 0 0	
Do. ...	Varoothoor	Do.	13 0 0	62 0 0	54 0 0	54 0 0	5 0 0	26 0 0	... ... 50 0 0	
Do. ...	Puttavarree	Do.	24 0 0	104 0 0	60 0 0	57 0 0	3 0 0	11 0 0	... ... 300 0 0	
Do. ...	Valampatty	Do.	3 0 0	12 0 0	8 0 0	11 0 0	3 0 0	12 0 0	... ... 50 0 4	
Do. ...	Moundeputty	Pond	1 0 0	2 0 0	2 0 0	2 0 0	1 0 0	2 0 0	... ... 30 0 0	
Do. ...	Theergarakotta ...	Tank	70 0 0	284 0 0	112 0 0	105 0 0	0 0 0	0 0 0	... ... 1,200 0 0	
Do. ...	Baroochem	Do.	34 0 0	125 0 0	123 0 0	123 0 0	31 0 0	125 0 0	... ... 200 0 0	
Do. ...	Kadiramputty ...	Do.	19 0 0	66 0 0	13 0 0	13 0 0	30 0 0	86 0 0	... ... 300 0 0	
Do. ...	Bilvar	Do.	134 0 0	623 0 0	511 0 0	549 0 0	134 0 0	000 0 0	... ... 1,500 0 0	Do.
Do. ...	Do.	Do.	2 0 0	5 0 0	1 0 0	5 0 0	3 0 0	5 0 0	... ... 50 0 0	Do.
Do. ...	Mavareputty	Tank	14 0 0	47 0 0	21 0 0	32 0 0	13 0 0	41 0 0	... ... 100 0 6	
Do. ...	Cherukandum	Sluice	10 0 0	34 0 0	11 0 0	16 0 0	8 0 0	28 0 0	... ... 150 0 3	
Do. ...	Vella Sandiputty ...	Do.	29 0 0	90 0 0	28 0 0	14 0 0	18 0 0	57 0 0	... ... 200 0 0	
Do. ...	Thandikeppum	Do.	9 0 0	41 0 0	15 0 0	24 0 0	0 0 0	0 0 0	... ... 150 0 0	
Do. ...	Vettaputty	Do.	13 0 0	54 0 0	32 0 0	41 0 0	12 0 0	53 0 0	... ... 200 0 0	
Do. ...	Naragamkeppem ...	Do.	14 0 0	58 0 0	29 0 0	27 0 0	13 0 0	52 0 0	... ... 300 0 0	
Do. ...	Thathumputty	Do.	7 0 0	21 0 0	11 0 0	11 0 0	7 0 0	21 0 0	... ... 250 0 0	
Do. ...	Thurgaputty	Tank	10 0 0	33 0 0	16 0 0	23 0 0	7 0 0	19 0 0	... ... 50 0 0	

Nominal List of Important Irrigation Works urgently in need of repair in the Salem District

Taluk.	Village.	Name of Irrigation work.	Total registered Nunjah Ayacut.	Tax payable on whole Nunjah Ayacut.	Average tax actually paid from 1840 to 1850.	Average tax actually paid from 1850 to 1860.	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.	Date of last repair.
1		2	3	4	5	6	7	8	9	10
				Rs. A. P.	Rs. A. P.	Rs. A. P.		Rs. A. P.		
Utengerry ...	Mavareeputty	Tank and sluice.	8 0 0	23 0 0	9 0 0	11 0 0	8 0 0	28 0 0	Rs. A. P. 200 0 0	
Do. ...	Chengulvady	Sluice	21 0 0	70 0 0	25 0 0	40 0 0	20 0 0	55 0 0	... ... 40 0 0	
Do. ...	Chellaputty	Do.	21 0 0	62 0 0	26 0 0	40 0 0	18 0 0	53 0 0	... ... 35 0 0	
Do. ...	Shonumputty	Do.	40 0 0	125 0 0	54 0 0	71 0 0	32 0 0	100 0 0	... ... 40 0 0	
Do. ...	Athakareputty	Tank	61 0 0	234 0 0	11 0 0	35 0 0	16 0 0	78 0 0	... ... 200 9 0	1865-66.
Do. ...	Alamalupuram	Tank and bund of channel.	16 0 0	56 0 0	26 0 0	35 0 0	13 0 0	42 0 0	... ... 200 0 0	
Do. ...	Alapuram	Tank and sluice ...	243 0 0	1,169 0 0	343 0 0	928 0 0	233 0 0	1,082 0 0	... ...	
Do. ...	Do.	Bund of anicut and digging channel.	135 0 0	640 0 0	194 0 0	453 0 0	124 0 0	571 0 0	... ... 600 0 0	
Do. ...	Manushe	Tank and sluice.	28 0 0	83 0 0	9 0 0	31 0 0	24 0 0	14 0 0	... ... 400 0 0	Do.
									30 0 0	
Oossoor ...	Konrasuntherum ...	Anicut	12 0 0	41 0 0	14 0 0	14 0 0	0 0 0	0 0 0	Earth-work ... ... 70 0 0 Stone do. ... ... 100 0 0 Lime do. 30 0 0	1866-67.
									200 0 0	
Do. ...	Salevarum	Tank	14 0 0	53 0 0	32 0 0	24 0 0	7 0 0	28 0 0	Earth-work ... ... 50 0 0 Stone do. ... ... 50 0 0 Bund do. 40 0 0	Never repaired by Circar.
									140 0 0	
Do. ...	Thupsapully	Do.	82 0 0	376 0 0	0 0 0	213 0 0	28 0 0	128 0 0	Earth-work ... ... 500 0 0 Stone do. ... ... 350 0 0 Sluice do. 150 0 0	Fusly 1267.
									1,000 0 0	
Do. ...	Aglakota	Do.	11 0 0	57 0 0	37 0 0	37 0 9	8 0 0	38 0 0	Earth-work ... ... 80 0 0 Stone do. ... ... 60 0 0 Lime do. 60 0 0	Fusly 1239.
									200 0 0	
Do. ...	Madumuttukota ...	Do.	37 0 0	199 0 0	137 0 0	139 0 0	23 0 0	132 0 0	Earth-work ... ... 30 0 0 Stone do. ... ... 20 0 0 Lime do. 40 0 0	Fusly 1234.
									90 0 0	
Do. ...	Polliemkota	Do.	28 0 0	163 0 0	41 0 0	69 0 0	20 0 0	123 0 0	Earth-work ... ... 30 0 0 Stone do. ... ... 20 0 0 Lime do. 30 0 0	Not known to have been repaired by Circar.
									80 0 0	
Do. ...	Thasarepully	Do.	37 0 0	144 0 0	105 0 0	110 0 0	26 0 0	113 0 0	Earth-work ... ... 30 0 0 Stone do. ... ... 50 0 0 Lime do. 50 0 0	Fusly 1239.
									130 0 0	

Nominal List of Important Irrigation Works urgently in need of repair in the Salem District.

Talook.	Village.	Name of Irrigation work.	Total registered Nunjah Ayacut.	Tax payable on whole Nunjah Ayacut.	Average tax actually paid from 1840 to 1850.	Average tax actually paid from 1850 to 1860.	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.		Date of last repair.
1		2	3	4	5	6	7	8	9		10
										RS. A. P.	
Oossoor ...	Tharanabatum	Tank	32 0 0	101 0 0	18 0 0	18 0 0	9 0 0	38 0 0	Earth work	10 0 0	Not under Circar repair.
									Stone do.	15 0 0	
									Lime do.	35 0 0	
										60 0 0	
Do. ...	Do.	Do.	9 0 0	53 0 0	0 0 0	0 0 0	9 0 0	53 0 0	Earth work	20 0 0	Do.
									Stone do.	30 0 0	
									Lime do.	30 0 0	
										80 0 0	
Do. ...	Oshanddee	Do.	13 0 0	48 0 0	0 0 0	0 0 0	0 0 0	0 0 0	Earth work	10 0 0	Do.
									Stone do.	20 0 0	
									Lime do.	50 0 0	
										80 0 0	
Do. ...	Komaranpully	Do.	44 0 0	243 0 0	167 0 0	166 0 0	44 0 0	243 0 0	Earth work	50 0 0	20 years ago.
									Stone do.	40 0 0	
									Lime do.	35 0 0	
										105 0 0	
Do. ...	Do.	Do.	13 0 0	37 0 0	11 0 0	20 0 0	30 0 0	37 0 0	Earth work	50 0 0	Never under Circar repair.
									Stone do.	100 0 0	
									Lime do.	80 0 0	
										180 0 0	
Do. ...	Pethamanagaram ...	Do.	24 0 0	85 0 0	32 0 0	34 0 0	19 0 0	75 0 0	Earth work	80 0 0	Do.
									Stone do.	100 0 0	
									Lime do.	50 0 0	
										230 0 0	
Do. ...	Chenamanagaram ...	Do.	63 0 0	230 0 0	80 0 0	146 0 0	59 0 0	208 0 0	Earth work	100 0 0	10 years ago.
									Stone do.	100 0 0	
									Lime do.	50 0 0	
										250 0 0	
Do. ...	Samatharamabully ...	Do.	22 0 0	131 0 0	93 0 0	100 0 0	16 0 0	96 0 0	Earth work	100 0 0	Fusly 1270.
									Stone do.	100 0 0	
									Lime do.	0 0 0	
										200 0 0	
Do. ...	Bagalagoundahalli ...	Do.	17 0 0	101 0 0	72 0 0	92 0 0	17 0 0	101 0 0	Earth work	20 0 0	Fusly 1265.
									Stone do.	30 0 0	
									Lime do.	50 0 0	
										100 0 0	

Nominal List of Important Irrigation Works urgently in need of repair in the Salem District.

Taluk.	Village.	Name of Irrigation work.	Total registered Nunjah Ayacut.	Tax payable on whole Nunjah Ayacut.	Average tax actually paid from 1840 to 1850.	Average tax actually paid from 1850 to 1860.	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.		Date of last repair.
1		2	3	4	5	6	7	8	9		10
				Rs. A. P.	Rs. A. P.	Rs. A. P.		Rs. A. P.		Rs. A. P.	
Oossoor ...	Moranabulli	Tank	11 0 0	49 0 0	7 0 0	10 0 0	.....	.....	Earth work	70 0 0	Fusly 1272.
									Stone do.	80 0 0	
										150 0 0	
Do. ...	Oossoor	Do.	9 0 0	54 0 0	51 0 0	52 0 0	8 0 0	50 0 0	Earth work	30 0 0	Known to have been repaired by Circar some time ago.
									Stone do.	40 0 0	
									Lime do.	30 0 0	
										100 0 0	
Do. ...	Barakanhalli	Do.	10 0 0	49 0 0	36 0 0	15 0 0	3 0 0	16 0 0	Stone work	80 0 0	About 15 years ago.
Do. ...	Charandaballi	Do.	138 0 0	867 0 0	676 0 0	572 0 0	105 0 0	654 0 0	Earth work	150 0 0	Slightly repaired 10 years ago.
									Stone do.	250 0 0	
									Lime do.	100 0 0	
										500 0 0	
Do. ...	Naralahuddi	Do.	7 0 0	28 0 0	23 0 0	18 0 0	5 0 0	22 0 0	Earth work	60 0 0	Never repaired by Circar.
									Stone do.	80 0 0	
										140 0 0	
Do. ...	Auchitee	Anicut and tank.	55 0 0	273 0 0	51 0 0	57 0 0	9 0 0	12 0 0	Earth work	300 0 0	Repaired in Fusly 1235.
									Stone do.	500 0 0	
										800 0 0	
Do. ...	Thamasumhalli	Tank.	16 0 0	61 0 0	20 0 0	26 0 0	7 0 0	20 0 0	Earth work	20 0 0	Not known to have been repaired by Circar.
									Stone do.	30 0 0	
									Lime do.	30 0 0	
										80 0 0	
Do. ...	Bannikullu	Do.	49 0 0	326 0 0	173 0 0	223 0 0	40 0 0	325 0 0	Earth work	50 0 0	Repaired 5 years ago.
									Stone do.	200 0 0	
									Lime do.	50 0 0	
										300 0 0	
Do. ...	Sonnathur	Do.	32 0 0	250 0 0	225 0 0	222 0 0	23 0 0	233 9 0	Earth work	70 0 0	Repaired 20 years ago.
									Stone do.	80 0 0	
									Lime do.	50 0 0	
										200 0 0	
Do. ...	Anumandapuram ...	Anicut	10 0 0	23 0 0	11 0 0	3 0 0	9 0 0	19 0 0	Earth work	25 0 0	Not known to have been repaired by Circar.
									Stone do.	75 0 0	
										100 0 0	
Do. ...	Timmanhaddi	Tank	12 0 0	69 0 0	13 0 0	11 0 0	4 0 0	22 0 0	Earth work	30 0 0	Slightly repaired 15 years ago.
									Lime do.	25 0 0	
										55 0 0	

Nominal List of Important Irrigation Works urgently in need of repair in the Salem District.

Talook.	Village.	Name of Irrigation work.	Total registered Nunjah Ayacut.	Tax payable on whole Nunjah Ayacut.	Average tax actually paid from 1840 to 1850.	Average tax actually paid from 1850 to 1860.	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.		Date of last repair.
1		2	3	4	5	6	7	8	9		10
				Rs. A. P.	Rs. A. P.	Rs. A. P.	Rs. A. P.	Rs. A. P.		Rs. A. P.	
Oossoor ...	Osahaddi	Tank	25 0 0	110 0 0	57 0 0	75 0 0	21 0 0	97 0 0	Earth work	100 0 0	Slightly repaired 15 years ago.
									Stone do.	150 0 0	
									Lime do.	80 0 0	
										330 0 0	
Do. ...	Bairakundahalli ...	Anicut	17 0 0	98 0 0	89 0 0	95 0 0	3 0 0	18 0 0	Stone work	200 0 0	Do.
									Earth do.	20 0 0	
									Lime do.	200 0 0	
										420 0 0	
Do. ...	Pallaballi	Tank	97 0 0	646 0 0	475 0 0	308 0 0	66 0 0	458 0 0	Earth work	50 0 0	Do.
									Stone do.	50 0 0	
									Lime do.	50 0 0	
										150 0 0	
Do. ...	Upparayanhalli... ...	Do.	69 0 0	407 0 0	167 0 0	162 0 0	17 0 0	101 0 0	Earth work	100 0 0	Do.
									Stone do.	50 0 0	
									Lime do.	100 0 0	
										250 0 0	
Do. ...	Rungapuram	Do.	19 0 0	94 0 0	27 0 0	33 0 0	8 0 0	39 0 0	Earth work	50 0 0	Not known to have been repaired by Circar.
									Stone do.	20 0 0	
									Lime do.	25 0 0	
										95 0 0	
Do. ...	Mullasamudram	Do.	24 0 0	170 0 0	85 0 0	81 0 0	14 0 0	80 0 0	Earth work	100 0 0	Do.
									Stone do.	200 0 0	
										300 0 0	
Do. ...	Pithairadi	Do.	19 0 0	107 0 0	23 0 0	18 0 0	12 0 0	73 0 0	Earth work	150 0 0	Do.
									Lime do.	30 0 0	
										180 0 0	
Do. ...	Adakkam	Do.	9 0 0	39 0 0	3 0 0	.....	.....	.....	Earth work	100 0 0	Do.
									Stone do.	100 0 0	
									Lime do.	50 0 0	
										250 0 0	
Do. ...	Dasirihalli	Do.	28 0 0	131 0 0	74 0 0	92 0 0	9 0 0	41 0 0	Earth work	80 0 0	Repaired about 15 years ago.
									Stone do.	100 0 0	
										180 0 0	
Do. ...	Ullukurnakai	Do.	14 0 0	88 0 0	31 0 0	59 0 0	6 0 0	36 0 0	Earth work	60 0 0	Repaired about 6 years ago.
									Stone do.	60 0 0	
										120 0 0	

Nominal List of Important Irrigation Works urgently in need of repair in the Salem District.

Talook.	Village.	Name of Irrigation work.	Total registered Nunjah Ayacut.	Tax payable on whole Nunjah Ayacut.	Average tax actually paid from 1840 to 1850.	Average tax actually paid from 1850 to 1859.	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.		Date of last repair.
1		2	3	4	5	6	7	8	9		10
										RS. A. P.	
Oossoor ...	Balur	Tank	24 0 0	RS. A. P. 92 0 0	RS. A. P. 50 0 0	RS. A. P. 52 0 0	20 0 0	RS. A. P. 73 0 0	Earth work	50 0 0	Repaired about 20 years ago.
									Stone do.	150 0 0	
									Lime do.	20 0 0	
										220 0 0	
Do. ...	Panjahalli	Do.	212 0 0	890 0 0	241 0 0	302 0 0	6 0 0	31 0 0	Earth work	500 0 0	Do.
									Stone do.	1,000 0 0	
									Lime do.	100 0 0	
										1,600 0 0	
Do. ...	Osapuram	Do.	82 0 0	438 0 0	296 0 0	288 0 0	80 0 0	435 0 0	Earth work	120 0 0	Repaired about 10 years ago.
									Stone do.	200 0 0	
										320 0 0	
Do. ...	Senkarayapuram ...	Do.	27 0 0	134 0 0	132 0 0	134 0 0	17 0 0	86 0 0	Earth work	50 0 0	Repaired some time ago by Circar.
									Stone do.	120 0 0	
									Lime do.	30 0 0	
										200 0 0	
Do. ...	Balikorai	Do.	10 0 0	55 0 0	38 0 0	26 0 0	5 0 0	29 0 0	Earth work	40 0 0	Do.
									Stone do.	60 0 0	
									Lime do.	30 0 0	
										130 0 0	
Do. ...	Doddarayasundram ...	Do.	45 0 0	239 0 0	85 0 0	85 0 0	13 0 0	91 0 0	Earth work	100 0 0	Repaired about 15 years ago.
									Stone do.	100 0 0	
										200 0 0	
Do. ...	Sanjanhulli	Do.	22 0 0	110 0 0	49 0 0	66 0 0	13 0 0	77 0 0	Earth work	50 0 0	Do.
									Lime do.	50 0 0	
										100 0 0	
Do. ...	Andevan	Do.	38 0 0	165 0 0	131 0 0	113 0 0	26 0 0	115 0 0	Earth work	60 0 0	Do.
									Stone and lime work ...	80 0 0	
										140 0 0	
Do. ...	Kandakamhalli	Do.	8 0 0	40 0 0	12 0 0	38 0 0	3 0 0	16 0 0	Earth work	60 0 0	Do.
									Stone do.	100 0 0	
									Lime do.	50 0 0	
										200 0 0	
Do. ...	Do.	Do.	7 0 0	17 0 0	.....	.....	.....	.....	Earth work	60 0 0	Not known to have been repaired by Circar.
									Stone do.	20 0 0	
									Lime do.	20 0 0	
										100 0 0	

Nominal List of Important Irrigation Works urgently in need of repair in the Salem District.

Talook.	Village.	Name of Irrigation work.	Total registered Nunjah Ayacut.	Tax payable on whole Nunjah Ayacut.	Average tax actually paid from 1840 to 1850.	Average tax actually paid from 1850 to 1860.	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.		Date of last repair.
1		2	3	4	5	6	7	8	9		10
				Rs. A. P.	Rs. A. P.	Rs. A. P.		Rs. A. P.		Rs. A. P.	
Oossoor ...	Kandakamhalli... ...	Tank	17 0 0	67 0 0	59 0 0	36 0 0	15 0 0	60 0 0	Earth work	90 0 0	About 20 years ago.
									Stone do.	100 0 0	
									Lime do.	35 0 0	
										225 0 0	
Do. ...	Tandarai	Do.	78 0 0	562 0 0	251 0 0	232 0 0	34 0 0	216 0 0	Earth work	80 0 0	Repaired about 10 years ago.
									Stone do.	120 0 0	
										200 0 0	
Do. ...	Do.	Do.	43 0 0	243 0 0	107 0 0	136 0 0	15 0 0	78 0 0	Stone work	300 0 0	Do.
Do. ...	Mukanur	Do.	14 0 0	72 0 0	60 0 0	54 0 0	13 0 0	65 0 0	Earth work	60 0 0	Repaired about 15 years ago.
									Stone do.	70 0 0	
									Lime do.	50 0 0	
										180 0 0	
Do. ...	Do.	Do.	14 0 0	64 0 0	44 0 0	40 0 0	10 0 0	50 0 0	Earth work	100 0 0	Do.
									Stone do.	100 0 0	
										200 0 0	
Do. ...	Mukasibarandur ...	Do.	30 0 0	239 0 0	194 0 0	209 0 0	34 0 0	234 0 0	Earth work	300 0 0	Do.
									Stone do.	200 0 0	
									Lime do.	100 0 0	
										600 0 0	
Do. ...	Denkenicotta	Do.	58 0 0	247 0 0	139 0 0	195 0 0	46 0 0	210 0 0	Earth work	50 0 0	Repaired about 10 years ago.
									Stone do.	100 0 0	
										150 0 0	
Do. ...	Do.	Do.	10 0 0	44 0 0	34 0 0	29 0 0	7 0 0	11 0 0	Earth work	50 0 0	Do.
									Stone do.	50 0 0	
										100 0 0	
Do. ...	Anjattidrugam	Do.	7 0 0	27 0 0	16 0 0	6 0 0	.....	.....	Earth work	60 0 0	Repaired about 20 years ago.
									Stone do.	40 0 0	
										100 0 0	
Do. ...	Jakkeri...	Do.	23 0 0	120 0 0	73 0 0	83 0 0	18 0 0	90 0 0	Earth work	100 0 0	Do.
									Stone do.	60 0 0	
										160 0 0	
Do. ...	Kaduttanhalli	Do.	4 0 0	25 0 0	5 0 0	11 0 0	3 0 0	18 0 0	Earth work	30 0 0	Do.
									Stone do.	20 0 0	
										50 0 0	

Nominal List of Important Irrigation Works urgently in need of repair in the Salem District.

Talook.	Village.	Name of Irrigation work.	Total registered Nunjah Ayacut.	Tax payable on whole Nunjah Ayacut.	Average tax actually paid from 1840 to 1850.	Average tax actually paid from 1850 to 1860.	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.		Date of last repair.
1		2	3	4	5	6	7	8	9		10
Oossoor ...	Konasamudram	Anicut	37 0 0	Rs. A. P. 216 0 0	Rs. A. P. 205 0 0	Rs. A. P. 180 0 0	.....	Rs. A. P.	Stone work	Rs. A. P. 300 0 0	Repaired about 10 years ago.
									Lime do.	200 0 0	
										500 0 0	
Do. ...	Onnukurikki	Tank	5 0 0	23 0 0	.....	.....	.....	.....	Earth work	100 0 0	Does not appear to have been repaired by Circar.
									Stone do.	150 0 0	
										250 0 0	
Do. ...	Sasivadi	Do.	159 0 0	775 0 0	296 0 0	493 0 0	91 0 0	455 0 0	Earth work	50 0 0	Repaired about 10 years ago.
									Stone do.	200 0 0	
									Lime do.	30 0 0	
										280 0 0	
Do. ...	Mottamaggrarm ...	Do.	8 0 0	26 0 0	16 0 0	16 0 0	4 0 0	9 0 0	Earth work	100 0 0	Do.
									Stone do.	200 0 0	
										300 0 0	
Do. ...	Akaram	Do.	15 0 0	90 0 0	26 0 0	28 0 0	14 0 0	88 0 0	Earth work	50 0 0	Do.
									Stone do.	70 0 0	
									Lime do.	100 0 0	
										220 0 0	
Do. ...	Tokarai	Do.	133 0 0	985 0 0	589 0 0	757 0 0	96 0 0	695 0 0	Earth work	50 0 0	Do.
									Stone do.	100 0 0	
									Lime do.	100 0 0	
										250 0 0	
Do. ...	Do.	Anicut	29 0 0	187 0 0	86 0 0	79 0 0	15 0 0	83 0 0	Stone work	400 0 0	Repaired 20 years ago.
									Lime do.	200 0 0	
										600 0 0	
Do. ...	Tenganhalli	Tank	173 0 0	1,223 0 0	632 0 0	856 0 0	118 0 0	949 0 0	Earth work	50 0 0	Repaired 10 years ago.
									Stone do.	150 0 0	
									Lime do.	150 0 0	
										350 0 0	
Do. ...	Nakondahalli	Do.	28 0 0	148 0 0	119 0 0	126 0 0	17 0 0	99 0 0	Earth work	20 0 0	Repaired 8 years ago.
									Stone do.	30 0 0	
									Lime do.	50 0 0	
										100 0 0	
Do. ...	Dasirihalli	Do.	25 0 0	116 0 0	96 0 0	98 0 0	25 0 0	116 0 0	Earth work	100 0 0	Repaired 20 years ago.
									Stone do.	90 0 0	
									Lime do.	50 0 0	
										240 0 0	

Nominal List of Important Irrigation Works urgently in need of repair in the Salem District.

Talook.	Village.	Name of Irrigation work.	Total registered Nunjah Ayacut.	Tax payable on whole Nunjah Ayacut.	Average tax actually paid from 1840 to 1850.	Average tax actually paid from 1850 to 1860.	Present Cultivatin.	Present Revenue.	Rough estimate of repairs needed.	Date of last repair.
1		2	3	4	5	6	7	8	9	10
				Rs. A. P.	Rs. A. P.	Rs. A. P.		Rs. A. P.		
Oossoor ...	Kongisetti	Tank	9 0 0	56 0 0	55 0 0	.....	.....	.....	Earth work ... ... 50 0 0 Stone do. ... ... 50 0 0 Lime do. 50 0 0 150 0 0	Repaired in Fusly 1255.
Trichengode.	Konasamudrum and Thathapuram.	Two ponds ...	31 0 12	254 12 10	205 2 1	213 13 0	27 9 15	230 15 20	... ... 36 00	
Do. ...	Konasamudrum	Tank	58 8 0	590 10 5	278 8 1	315 0 4	47 31 0	481 6 11	... ... 103 12 0	
Do. ...	Lekkapuram	Do.	27 27 4	199 2 0	80 9 9	100 15 7	18 2 9	136 3 3	... ... 62 13 0	
Do. ...	Hippili	Do.	111 27 5	676 14 7	498 8 4	595 10 3	98 16 12	603 6 9	... ... 413 7 0	
Do. ...	Kakari	Do.	52 15 5	157 5 3	.....	56 14 8	18 30 13	81 15 4	... ... 216 12 0	
Do. ...	Yedanganalai	Do.	23 4 8	135 3 6	59 11 9	69 0 11	16 30 12	102 11 1	... ... 48 2 0	
Do. ...	Sattanpalayam	Do.	23 32 12	112 9 8	44 4 1	75 10 10	16 23 14	77 13 1	... ... 34 12 0	
Do. ...	Konari	Do.	38 13 12	187 10 4	77 6 0	147 7 7	20 18 7	118 12 9	... ... 94 4 0	
Do. ...	Kachaballi	Do.	40 32 13	117 2 8	4 0 2	71 7 3	34 6 6	103 4 2	... ... 91 11 0	
Do. ...	Kottamampatti	Do.	51 30 15	163 3 0	46 1 3	86 6 5	46 13 4	144 10 4	... ... 53 9 0	
Do. ...	Kannandari	Do.	32 13 15	236 8 3	71 5 0	94 15 5	1 18 3	6 12 9	... ... 100 15 0	
Do. ...	Settur	Do.	21 35 6	156 9 6	42 1 8	66 10 7	7 30 5	51 3 1	... ... 45 6 0	
Do. ...	Bandimattan	Do.	78 14 7	324 6 7	268 12 10	277 11 5	59 27 0	250 2 9	... ... 1,470 10 0	
Do. ...	Balur	Do.	339 38 6	2,514 14 6	2,767 2 0	2,692 7 9	289 25 20	2,555 4 10	... ... 378 0 0	
Do. ...	Akaram	Do.	106 17 14	483 0 3	201 4 7	372 5 11	68 9 2	437 5 10	... ... 142 10 0	
Do. ...	Karivappumpatti ...	Do.	39 12 15	272 8 10	179 13 0	295 15 7	36 4 10	247 7 5	... ... 196 14 0	
Do. ...	Vapumpalli	Do.	111 4 3	884 6 2	514 4 6	186 12 10	61 5 5	494 12 8	... ... 93 7 0	
Do. ...	Trichengode	Pond	26 19 3	159 1 3	131 9 2	129 15 5	23 19 7	128 5 2	... ... 59 15 0	
Do. ...	Gummambadi	Tank	54 8 3	452 14 10	289 6 4	270 5 6	32 31 5	305 0 7	... ... 171 5 0	
Do. ...	Dadapuram	Do.	38 32 13	316 15 9	176 5 3	88 6 4	14 33 8	109 5 9	... ... 188 13 0	
Do. ...	Ilippalli	Do.	29 8 0	201 10 9	64 0 3	41 3 2	9 4 7	53 12 6	... ... 233 10 0	

SALEM,
9th May 1867.

(Signed) C. N. POCHIN,
Collector.

Proceedings of the Madras Government, Public Works Department, 15th June 1867.

Ordered that the foregoing letter, with its enclosure, be submitted to Government, with reference to their Order in the Public Works Department, dated 17th May 1866, No. 1,587.

No. 358. ORDER THEREON, 15th June 1867, No. 1,807.

IRRIGATION, No. 18.

1. Ordered that the Statement received with this letter be forwarded to the Superintending Engineer of the 5th Division, for communication to the Range Officers concerned.

2. Measures should be taken for placing as many of the irrigation works as possible in a proper state of repair from the Budget provision of Rupees 26,000 for "Minor tanks and channels" in the Salem District.

(True Extract.)

Colonel, R. E.,
Secretary to Government.

To the Superintending Engineer, 5th Division.
,, Revenue Department.
,, Board of Revenue.

Exd. S. T. Augustin.

Terrence 1867 - Vol
Rec. of Government Documents
Pg. 1557

Proceedings in the
Co. Ct. Jefferson

Dated 15th June
Received 17th June 1867

Pg. 1807

A.D. 1867

RECORDED.

18th January

[illegible]

No. 1,253,216