

7651
Public Works (1896) Department.

G.O., No. 926 J

DATED 5th November 1896

[Despatch Abstract.]

Putlampalli Cherla palli Tank: Querting under
Section 9 of Act IV of 1886, Re & the repairs to the same in the
Andalpet Taluk which affects the Madras Railway be
carried out by Government. The expenditure incurred thereon
being subsequently recovered from the owners under
the provisions of the Act.

T.C. 5/11 5/11

G.O.	No.	Department	Date	G.O.	No.	Department	Date

[illegible]

Government (1896) of Madras.
PUBLIC WORKS.

Spare copies

NOVEMBER.

Directing, under section 9 of Act IV of 1886, that the repairs to the — in the Cuddapah taluk, which affects the Madras Railway, be carried out by Government, the expenditure incurred thereon being subsequently recovered from the owners under the provisions of the Act.

GOVERNMENT OF MADRAS.

PUBLIC WORKS DEPARTMENT.

Irrigation.

Read—the following paper:—

Proceedings of the Board of Revenue (Revenue Settlement, Land Records and Agriculture), Mis. No. 4768, dated 3rd October 1896.

Read—the following letter from the Collector of Cuddapah, dated 11th September 1896, Ref. on Current No. 997 Eng. of 1895:—

Under section 9 of Madras Act IV of 1886, I have the honour to submit the following case for the orders of the Governor in Council.

2. Putlampalli Cherlapalli tank of Cuddapah taluk, a private tank affecting the Madras Railway line, having been reported to be in a state of disrepair, I had plans and estimates for its repair prepared by the Public Works Department. The amount of the estimate is Rs. 260. The statement referred to in section 4 of the Act was

- | | | |
|---|-------------------------|---|
| <ul style="list-style-type: none"> 1. Mulabagala Raja Row, 2. Dharmavaram Balayya, 3. Dharmavaram Subbayya, 4. Desam Gangayya, 5. Yedalla Pitchayya, 6. Patla Kondayya, | } all of Cuddapah town. | recorded and a translation thereof in Telugu affixed to a tree in the public street of the village. An order under section 5 was then issued to the owners of the tank allowing them four months' time to carry out the measures or to show cause why they should not carry them out. |
|---|-------------------------|---|

In following the procedure prescribed in this section, no copy of the plan was, by mistake of a clerk whom I have fined, sent out with the order, though the order mentioned that a copy was enclosed, and the omission was not detected until all the legal formalities were completed. The parties, who acknowledged the receipt of the notice, did not ask for a copy of the plan said to have been enclosed in it and have, up to the present, made no allusion to the omission. The time allowed to the owners expired on 24th March 1896.

3. The owners having neither executed the repairs nor appeared before me to show cause why they should not carry out the same, a written notice under section 7 of the Act was issued to them, informing them that if the measures were not carried out within one month, the matter would be reported to Government under section 9. This period also expired on 4th July 1896.

4. The Tahsildar reports that no work has been done, but that some stones have been collected for constructing revetment. One of the owners (Mulabagala Raja Row) has put in two petitions in which he promises to pay his share of the amount and requests that the other shareholders may be compelled to pay their shares.

5. Records as per list enclosed, are submitted for information and eventual return.

Resolution—Mis. No. 4768, dated 3rd October 1896.

Forwarded, in continuation of Board's Proceedings, No. 3150, dated 25th June 1896, and No. 1667, dated 31st March 1896, to the Chief Engineer for Irrigation, who is requested to take such further action in the matter as he thinks fit with reference to paragraph 5 of G.O. No. 501 W., dated 10th February 1896.

2. The Collector should have sent a copy of the plan to the owners of the tank as soon as the omission to do so was detected. He is requested to do so now.

(True Copy and Extract.)

(Signed) . R. V. SRINIVASIAH,
Secretary.

ORDER—No. 926 I., dated 5th November 1896.

The owners of Putlampalli Cherlapalli tank, in the Cuddapah taluk, having failed to carry out repairs to the tank which affects the Madras Railway and to appear and show cause why they should not carry out the same although the Collector had given them due notice under section 7 of Act IV of 1886, His Excellency the Governor in Council is pleased to direct, under section 9 of the Act, that the repairs be carried out by Government, the expenditure incurred being subsequently recovered from the owners under the provisions of the Act.

(True Extract.)

Under Secretary to Government,
Irrigation Branch.

To the Chief Engineer for Irrigation.
" Superintending Engineer, III Circle, with eight enclosures.
" Examiner, Public Works Accounts.
" Revenue Department.

Ed. T. K. Nanyana Aiyangar.

No. 9269 of 5th November 1916.

PROCEEDINGS OF THE MADRAS GOVERNMENT.



Under date the

Read the following

Proceedings of the Board of Revenue

(Revs: Settlement, Land Records and

Agriculture)----- (H.E. NO: 4768. Miss: d/3rd October/96)

Order thereon:-

The owners of Putlampalli Cherlapalli tank in the Cuddapah taluq having failed to carry out repairs to the tank which affects the Madras railway and to appear and show cause why they should not carry out the same although the Collector had given them due notice under section 7 of ~~the~~ Act IV of 1836, His Excellency the Governor-in-Council is pleased to direct under section 9 of the Act that the repairs be carried out by Government the expenditure incurred thereon being subsequently recovered from the owners under the provisions of the Act.

To

The Chief Engr: for Irrigation

" Sup: Engineer, Third circle.

" Examiner, P.W. Accounts.

" Revenue Department.

with 8 encls.

with 26 encls.

1871 R.S. 27/10/11
H.E. 34/10. S.E. 11

Public Works (189⁶) Department.

CURRENT No. 9651

Order

From
The Board of Revenue
(Revenue Settlement and Revenue Accounts)

No. 4768. Misc

Dated 3. 10. 96

Received 26. 10. 96

Enclosures 2 6+37

Spare copies

SUBJECT.

Railway affecting Land-
Forwarding to the Chief
Engineer for signature
letter from the Collector
Cuddalore reporting
the action taken under
Act IV. of 1886 regarding
certain —

G.O.	No.	Department.	Date.
S.O.	5012	P.W.	10-2-76
"	8629	"	8-11-74

[illegible]

No. *15* **Board of Revenue**
(Revenue Settlement, Land Records
and Agriculture).
MADRAS


Former Case
K 399, II 8-9-6-96
K 208 III 1-4-96

Subject.

Subject.
Railway affecting
land.
Forwarding
to the Chief Engineer
for Irrigation
letter from the
Inspector of Lands
reporting
the action taken
under Act IV
of 1886 of 1886 re-
garding certain

~~Ind~~
17.00

B.



Proceedings of the Board of Revenue
(Revenue Settlement, Land Records and Agriculture),

Dated 3rd October 1896.

No. 1768 Mir.

READ the following letter from
the Collector of Gundlupet
dated 11th September 1896 in
reference on Government
No. 997 of 1895. —
Under Section 9 of Madras
Act IV of 1886, I have the
honour to submit the
following case for the
orders of the Government
in Council.
2. Pullampatti Cherlapatti
tank of Gundlupet Taluk,
a private tank affecting

the Madras Railway lines
 having been reported to
 be in a state of disrepair,
 I had plans and esti-
 mates for its repair
 prepared by the Public
 Works Department. The
 amount of the estimate
 is Rs 2600. The estimate
 referred to in section 4
 of the Act was recorded
 and a translation there-
 of in Telugu affixed to a
 tree in the public street
 of the village. An order
 under section 5 was
 then issued to the owners
 of the tank allowing them
 4 months time to carry
 out the measures or to
 show cause why they
 should not carry them
 out. In following the pro-
 cedure

1. Munkabagala Rangin Rao
2. S. Subramanian Pillai
3. S. Subramanian Pillai
4. S. Subramanian Pillai
5. S. Subramanian Pillai
6. S. Subramanian Pillai

proceeding was made
 in this direction, no copy
 of the plan was, by
 mistake of a clerk to
 whom I have pointed,
 sent out with the order,
 though the order men-
 tioned that a copy was
 enclosed, and the omis-
 sion was not detected
 until all the legal for-
 malities were completed.
 The parties, who ac-
 knowledged the receipt of the
 notice, did not ask for
 a copy of the plan
 said to have been en-
 closed in it and have,
 up to the present, made
 no allusion to the omis-
 sion. The time allowed

H. 11. 1. B. D. D.

to the owners expired
on 24th March 1896.

5.3. The owners having
neither one on board the
repairs nor appeared
before me to show cause
why they should not
carry out the same, a

written notice under
section 7 of the Act was
issued to them, inform-
ing them that if their
repairs were not
carried out within
one month, the matter
would be reported to

Government under
section 9. This period also
expired on 4th July 1896.

6. The Tahildar reports
that no work has been
done; but that some
stones have been col-
lected for constructing
a revetment. One of the
owners

owners Chhota Bagla Raja
Rao has put in a petition
in which he promises
to pay his share of
the amount and requests
that the other share holders
may be compelled to
pay their shares.

5. The cards as per list
enclosed are submit-
ted for information
and eventual return.

Revolution

Forwarded, in con-
tinuation of Board's

Proceedings $\frac{3150}{25/6/96}$
and $\frac{1667}{31/3/96}$ to the Chief

Engineer for Irrigation
who is requested to take
the necessary

such further action in
the matter as he thinks fit
with reference to para
35 of Government Order
501 IV.

10/2/96
2. The collector
should have sent
a copy of the plan to
the owners of the tank
as soon as the omission
to do so was detected.
He is requested to do
so now.

True copy and attached,
R. V. Srinivasan
Secretary
To the Chief Engineer
for Irrigation with enclosures
The Collector of Buddah

25/10/96

1896.
Board of Revenue
(Revenue Settlement, Land Records
and Agriculture),
MADRAS.
No. 322/96

(Sett. 20-2,000-27-11-95.)

To
The Chief Engineer
for Irrigation

Former case
R 2072/1-4-96

D. E. S.
E. S.
Record
30.6.96
No. of Enclosures. 17/9/96
Proceedings, dated 25-6-1896
No. 3150 mis

Subject.
Forwarding to
the Chief Engineer
the collector's
letter reporting
the action taken
under Act IV of
1886 regarding
certain Railway
affecting tanks
in Buddah.

Later case
H 36. CD - 9.7.96
R 5792 - 3.10.96

25/10/96

25/10/96

North Arcot Collectors Office
Chittoor 13-5-1896.
No 763
Aug 29/96.

From

G. E. L. Campbell Esquire
Collector & District Magistrate
of North Arcot.

To,
The collector of
Cuddapah.

Sir,
In reply to your letter
dated 26th November 1895
Ref on C to 575 of 95, I have
the honor to return herewith
the notice received
with the above and to
inform you that of the
3 individuals on whom
the notice has to be served
Srinivasa Chakr of Tiru-
patti declined to sign
the notice as he has no
share in the will a/c
referred to, in your notice
Thiruvathatha Chakr
appears to be suffering
from an attack of para-
lysis and therefore
cannot sign it. The
present whereabouts
of the remaining party



Proceedings of the Board of Revenue

(Revenue Settlement, Land Records and Agriculture)

Dated 25th June 1896.

No. 3150 min.

Read the following letter from
the Collector of Cudd-
dapaah dated 14th
June 1896. Disposal
No. 2232 of 96 -
Rev.

In reply to Board's
Proceedings No 1667-
min dated the 31st
March last, I have
the honor to state
that I did not think a
full report of my action
was required. I wrote
my former letter with
the object of bringing to
notice the fact that
Government was under
a misapprehension in
thinking that no attempt
had been made under
the Act to force private

ing Tirumala Kumara
Kanakamma cannot
be ascertained as
she is reported to be
wandering from one
district to another,
probably with the in-
tention of evading
service of notices.

2. The 3rd statement
received from the Dy
Tahsildar of Tirupati
together with a copy of
his arzi dated 6.5.96
No 10383 of 96 are
herein enclosed for
your information.
I have on.

sd/ S. Ramachandrapur

For Dy Collector

(True copy)

sd/ M. Dale

6.6.96

Collector

(True copy)

G. Minivaram

Secretary.

owners to repair their tanks.

2. The Board having now called for a full report, I have the honor to state that it having been brought to notice that the marginally noted Railway affecting tanks were in need of repairs, estimates and plans were prepared by the Executive Engineer and a statement under sec 4 of Act IV of 1886 was recorded and orders to the owners thereof under section 5 of the Act were issued.

Cherlapalle tank of Pullam - fallen in Cuddapah Taluk.
(2) Jillellapalle tank in Pullam Taluk.

3. The owners of the tank in Cuddapah Taluk, being residents of Cuddapah Town I gave the order served on them. They have neither carried out nor shown cause why they should not carry out the remedial measures within the time prescribed in the said order which expired on the 24th March 96. I have therefore issued a notice

notice to the owners under section 7 of the Act calling upon them to carry out the work as per original order within one month. If the owners still neglect to carry out the measures, a default report will be submitted under section 9 of the Act for orders of the Government.

As regards the tank in Pullampet Taluk the above procedure was observed but the owners being residents of North Arcot District the order under section 5 was sent on 28th November 1895 to the Collector of that District with a request to get it served on the parties concerned and to return the original with the parties signatures. After several reminders the Collector of North Arcot has returned the notice unserved with his letter proposal No 763 of 96 dated 13th May 1896

of which I enclose a copy.

Resolution.

Forwarded
to the Chief Engineer
for Irrigation, in
continuation of Board
Proceedings, dated 31st
March 1896, No 1667 mis.

2. In regard to the
second work referred
to, the Collector will be
requested to take
further steps, as pre-
scribed in the Act and
report the result to the
Chief Engineer for Irrigation
in due course.

(True copy, & extract)

G. Minnam
Secretary

To
The Chief Engineer for Irrigation -
Collector of Cuddapah.

02/9/11



Proceedings of the Board of Revenue
(Revenue Settlement, Land Records and Agriculture).

Dated 31st March 1896.

No. 1667 mis.

READ the following letter from the
Collector of Cuddapah, dated
13th March 1896, No. 993 of 96.

With reference to Board Pro-
ceedings No. 1146 (L. & R.) dated
the 6th inst. I have the honor to
report that the provisions of
Act No. of 1886 are being enforced

1. Cherlopalthe tank
of Pullampalle,
Cuddapah Taluk,
2. Jillella madala
Apasaram tanks,
Pullampet Taluk

in respect of the two marginally
noted tanks in this District.
The time allowed for repairing
the tank in Cuddapah Taluk
will expire on 24th instant

and

if no other.
and the notice issued
in the case of the other
bank has not as yet been
returned by the Collector of Ports
On Coast, & when it was sent in
November last for service on
the owners of the bank who
reside in the District.

Resolution

The Collector's letter will
be forwarded to the Chief
Enquirer for Investigation, with
reference to G.O. dated
10 February 1896, No. 5016.

2. The information furnished
is very meagre and it is not
clear what steps have been
taken by the Collector to enforce
the provisions of Act IV of 1886,
(the Railway Protection Act)
in

in regard to the two banks men-
tioned; whether the notice referred
to is the one under Sec. 7 of the
Act; and, if so, whether the pre-
liminaries prescribed in
Sections 4 & 5 have been duly
observed. It is also observed
that the notice, ^{issued} in one case had
not been returned up to the date
of the Collector's letter; while in
the other, the time fixed had
not expired. The Collector is re-
quested to submit a full report.

(True copy and Extract,

*Myraatun,
Secretary*

The Chief Enquirer for Investigation
Collector of Cuddapah.

1896

Board of Revenue

(Revenue Settlement, Land Records
and Agriculture)

MADRAS

No. 1667

The Chief Engineer for
Irrigation

No. of Enclosures.

Proceedings, dated 31-3-1896

No. 1667

Subject.

Act IV of 1886 (Railway

Production Act)

applying the provisions
of the two tanks
in the Cuddalore District

Later fees
R 399 m - 20.6.96
R 36.00 - 7.7.96
R 579 m - 3.10.96

21.5.3
5651/96

21/5/96

li