

Revenue (1897) Department.

ROUTINE SERIES.

G.O., No. 250

DATED 3^d Feb'y

[Despatch Abstract.]

Disposing under para 2 of Circular, the letter
of Gaidhya Linga Sambiran, Tiruktuvalai,
Nagapattinam Taluk, complaining about the
defects in irrigation.

BACK PAPERS.

G.O.	No.	Department.	Date.	G.O.	No.	Department.	Date.

FURTHER PAPERS.

G.O.	No.	Department.	Date.	G.O.	No.	Department.	Date.

Revenue (1897) Department.

CURRENT No. 778

From Vythilinga Lambirani
Swami Ithanikam of
Sri Tyagaraja Swami temple
Tirukkuvalai, Nagapatnam Taluk.

Order

Transferred to the
Public Works Department.

No.

Dated 28-12-96.

Received 15th January 1897.

Registered 26th

Enclosures

Spare copies

SUBJECT,

Complaining about the defective
irrigation.

G.O. R. no: 250 d/30 Feb 1897.
Para 2 of C Rules.

List
(R.
13 Feb 97)


255 clerk
28/1/97

BACK PAPERS.

G.O.	No.	Department.	Date.

FURTHER PAPERS.

G.O.	No.	Department.	Date.



28-12-96
 28-12-96

L = 2000 ft. in depth
 K = 1000 ft. in depth
 I = 1000 ft. in depth
 H = 1000 ft. in depth
 G = 1000 ft. in depth
 F = 1000 ft. in depth
 E = 1000 ft. in depth
 D = 1000 ft. in depth
 C = 1000 ft. in depth
 B = 1000 ft. in depth
 A = 1000 ft. in depth

VELLAYAR
 M

U

W. B. M.

K
 9
 H
 I


28-12-96
 18-12-96

PETITION

50

REVENUE DEPT.

TO



The Honorable Governor in
 Council
 Madras

The petition of Vythilinga Tambiran Swami Sthanikam
 of Sri Tyagaraja Swami temple, Tirukkuvalai,
 Nagapatam Taluq.

1. The abovesaid temple owns about 1,000 acres of land in Tirukkuvalai and other villages, paying to the Government an assessment of about Rs. 6,000.
2. The irrigating channel for the said 1,000 acres of land takes its rise in Chinna Iyyangudi village on the right side of the river Vellayar at the place marked G in the sketch herewith annexed.
3. Considerable damage and loss is being sustained by the said Tirukkuvalai and other villages, by water not easily flowing the said irrigating channel, on account of the following defects in the system of irrigation:—
 - (a) The nanjai lands of the said villages being about 4 or 5 feet higher in level than the bed of the river Vellayar.
 - (b) The drainage channel that branches at H from the irrigation channel of Peria Kargudi falling into the said Tirukkuvalai irrigation channel at P and thus causing obstruction to the said Tirukkuvalai irrigation channel as well as raising its bed, by the discharge of sand and silt into it.
 - (c) The head of the channel being very near to the said villages.
 - (d) The calingala at K which was originally designed for regulating the water in the river, having fallen into disuse, by its being covered with earth.
4. By reason of the said defects in irrigation, considerable loss is caused to the said temple, every year, by there not being sufficient water, available for the cultivation of all the lands, and by water not sufficiently irrigating the cultivated portions. On account of the said loss, the income from the lands, not being sufficient, to meet the Government demand, establishment charges, the temple puja, and yearly festivals, portions of the land had to be sold in revenue sale, in some years, and the Government had also to make a remission of its kist in some years, as will be clear from the records in the Taluq Cutchery.
5. The temple has also borrowed about Rs. 25,000, from the Dharma-puram Adhinam for the temple puja and the cultivation charges.
6. That at the recent settlement, the Government kist was raised from Rs. 4,500 to 6,000, but no attention whatever was paid to the complaints about the defects in the irrigation.

5
 157

28-12-96-

Handwritten: 58-15-69

When given for copying _____
 When copied _____
 When examined _____
 When signed _____

189

READ AGAIN G.O., No.
 189

DATED

CURRENT No.

ENCLOSURES TO C. No.

ORDER OF GOVERNMENT

A A A A A A A

LETTER OF GOVERNMENT

STATEMENT WITH DITTO

PAPERS NOT FILLED UP, BRING WANT FOR DESPATCH
 IN ORIGINAL

N.B.—
 A = Copy in full.
 B = Not to be copied.
 P = Copy abstract only.
 Q = Copy heading only.

Handwritten: 96