

Revenue

(189

Record-keeper
Department.

MISCELLANEOUS SERIES.

G.O., No. 4793

DATED 2nd December 78

[Despatch Abstract.]

Coming to the aid of your Proge of the
I do so with remark that the
to the bank affecting the
East Coast of the Indian Ocean
be carried out by the expenditure
being relieved from the
with the same amount

...taken out of the Records and the charge of the Record-keeper.

IRRIGATION

Government (1898) of Madras.
PUBLIC WORKS.

FURTHER PAPERS.

[illegible]

Recd

Reqd

30/11

1898

Enclosures

Spare copies

G.O., No. 880 I., 10th November 1898.

NOVEMBER.

141. *See* no 473372 - *See*
Communicated to
the Board of Revenue.

$$\frac{M_2}{2a-1}$$

hint.

16 To the Board of Adv. (H. Govt)
RS
 1-12-98
 5-12-98

Timmaraza Tank

Directing, with remark, that the repairs to—, affecting the East Coast Railway in the Gôdâvari district, be carried out by Government, the expenditure being subsequently recovered from the mokhasadars concerned.

No 880 0TH NOVEMBER 1898.

GOVERNMENT OF MADRAS.
PUBLIC WORKS DEPARTMENT

Irrigation

Read—the following papers —

Endorsement of the Assistant Chief Engineer for Irrigation, Tank Restoration Scheme, dated
16th July 1898, No 1642 T
To the Board of Revenue (Revenue Settlement, Land Records and Agriculture), dated 29th
July 1898 No 237 M
Proceedings of the Board of Revenue (Revenue Settlement, Land Records and Agriculture),
Mis No 5010, dated 19th August 1898
Proceedings of the Board of Revenue (Revenue Settlement, Land Records and Agriculture),
Mis No 6012, dated 8th October 1898.

No 268 I

Note by the Chief Engineer for Irrigation

The Board of Revenue (Revenue Settlement, Land Records and Agriculture) brings to notice that as the Timmaraza tank of Yonampalam village in the Rajahmundry taluk, Godavari district, threatens the safety of the East Coast Railway, the three mokhasadars concerned were served by the Collector with notices, under sections 5 and 7 of Act IV of 1886, to carry out the necessary repairs to the tank which are estimated to cost Rs. 1,100. It would appear that one of the mokhasadars has offered to pay his one third share of the cost of the repairs, but as the other two have declined to contribute, the Board proposes that the tank should be repaired at Government expense in the first instance, the cost being recovered thereafter by filing a civil suit. The proposal may be approved.

18th October 1898

(Signed) W. HUGHES,
Chief Engineer for Irrigation.

ORDER—No 880 I, dated 10th November 1898

The mokhasadars of Yerrampalam village in Raichmundra Taluk, Godavari district, having failed to carry out the repairs to the Timmaraza tank which affects the East Coast Railway, although the Collector had served them with notices under sections 5 and 7 of Act IV of 1886, His Excellency the Governor in Council is pleased to direct, under section 9 of the Act, that the work be carried out by Government, the expending incurred thereon being subsequently recovered from the mokhasadars under the provisions of the Act.

2 The Collector will take care that the procedure laid down in the Act is strictly followed before undertaking the execution of the repairs

(True Extract)

Under Secretary to Government,
Irrigation Branch.

To the Chief Engineer for Irrigation
 " Superintending Engineer, I Circle.
 " Examiner, Public Works Accounts.
 " Revenue Department

Field 1 R. N. 10th, 10th, 10th, 10th, 10th

When examined
When signed.

READ AGAIN G O, No.
189

DATA

A General Note

Memorandum to C. Ho

ORDER OF GOVERNMENT

Letter of Government

RESTRAINT WITH DIET

PAPER NOT WILD UP, BEING MEANT FOR DESTROY
 IN ORIGINAL

A = Copy in full.
B = Not to be copied.
C = Copy abstract only.
D = Copy heading only.