

Revenue (1898) Department.

MISCELLANEOUS SERIES.

G.O., No. 4009

DATED 7th Octr 98.

[Despatch Abstract.]

Sanctioning, with remarks, the
estimate for ~~construction~~ ^{repairs} to the minor irrigation
works Spring channel. Cuddalore DC.

BACK PAPERS.

G.O.	No.	Department.	Date.	G.O.	No.	Department.	Date.

FURTHER PAPERS.

G.O.	No.	Department.	Date.	G.O.	No.	Department.	Date.

Revenue (1898) Department.

CURRENT No. 1113.

Order mis

4009 of 7th oct 98

From

The Board of Revenue,
Revenue Settlement,
Land Records & Agri.

Madras

No. 5189 Mis.

Sanctioned with the remark
that if the execution of Kudis-
maramat had been regularly at-
tended to in the past years
the first two of the estimates
for clearing sand at head springs and
reclamation on the channel banks
would probably have been
unnecessary.

Dated 29th August 1898.

Received 2nd Sept

Registered 2nd Sept

Enclosures 4.

Spare copies

SUBJECT.

Minor Irrigation Works, Guadara Dt.
Submitting with the Board's recom-
mendation estimate &c of a -----
for the sanction of Government with
reference to G.O. No. 339 Ld/R-5-98

To Messrs (Setts)
Rs 5-10-98

* 2 A 881

are the heading note
in the office account
of the spring 6/10/98

The office note specified the above
items first - there are numbered 1 + 4
in the estimate which numbers have
been given

Rs 6-10-98

in the estimate
"constructing a post-kitter" it is also (iv) in the office
note.

Not in the office
note - in the
estimate which
is in the office


BACK PAPERS.

G.O.	No.	Department.	Date.

FURTHER PAPERS.

G.O.	No.	Department.	Date.

(Sett. 12-2,000-23-5-8.)



Proceedings of the Board of Revenue

(Revenue Settlement, Land Records and Agriculture),

Dated 29th August 1898

189th.

No. 5189 Mis.

Read again the following Proceedings of the Board of Revenue, No.

2184 Mis. dated 30th March 1898:—

Read letter from ^{E. L. Vaylankar} the Collector of Cuddarah, dated 21st February 1898, Ref. on G.No. 57/Pd1. of 1898, submitting a detailed list of Minor Irrigation Works proposed for execution during the ensuing official year in the district.

Resolution No. 2184 Mis. 334-3-98

X X X

2. The estimates for items Nos. 3, 4, & 28 should be forwarded to the Executive Engineer for approval, as advised by the Chief Engineer for Irrigation, T. P. S. A detailed estimate for item No. 17 should be submitted to the Board through the Chief Engineer for Irrigation, T. P. S. in view to the sanction of Government being obtained therefor under rule 3 of the rules printed in G.O. No. 399 I, dated 2nd May 1893, Communicated with B.F. No. 2644 Mis., dated 21st June 1893.

^{Copy to the Collector of Cuddarah} X ^{Copy to the Collector of Cuddarah} X ^{Copy to the Collector of Cuddarah} X

Read also the following letter from the Collector of Cuddarah, dated 5th August 1898 Ref. on G.No. 57/pd1. of 1898.

With reference to para 2 of Board's Proceedings No. 2184 Mis. dated 30th March 1898, I have the honour to submit herewith the detailed estimate with an application for allotment of funds required for repairing Devarajupalli spring channel of Pedda-

-cheppalli in Cuddapa Taluk for obtaining the sanction of Government under rule 3 of the rules printed in G.O. No. 399 I dated 2nd May 1893 communicated with B.P. No. 3634 Mis. dated 21st June 1893. The estimate was forwarded to the Executive Engineer and has been scrutinized by the Public Works Department.


Endorsement of the Chief Engineer for Irrigation, dated 20th August 1898 No. 2007 I.

Forwarded. Under the circumstances stated, the estimate may be approved and submitted for sanction of Government.

Resolution.

The papers read above will be submitted to Government, with the Board's recommendation that sanction may be accorded under rule 3 of the rules printed in G.O. No. 399 I., dated 2nd May 1893 for the estimate amounting to Rs 1050, for the repairs of the Devarajopalli spring channel, Peddacheppalli village, Cuddapa Taluk. It is reported that the channel has not been repaired for a very long time. The estimate has been scrutinized by the Public Works Department.

(True Copies & Extract)


Dy. Director of L.R. & Agri.

To,

The Secretary to Government, Revenue Department,

with the sketch and estimate to be returned
Copy to the Collector of Cuddapa.

*Encl
2/25*

Read B. P. 5189 Mis (lett) of 29. 8. 98.

(Cus 6113)

Note

with reference to rule 3 of the rules for the execution of repairs to spring channels, printed in G.O. No. 399 I dated 2. 5. 93, the Board of Revenue recommends sanction to an estimate amounting to Rs 1050 for the following repairs to the Devarajopalli spring channel, Peddacheppalli village, Cuddapa Taluk :-

(i) Removing heap of sand around the head spring, ~~and~~ further off so as to prevent the sand falling into the spring by the action of rain, wind, cattle &c.

Amount of estimate - Rs 443-39.

(ii) Excavation of either bank up to about three feet ~~above~~ above water-level so as to form a bench for the villagers to throw the channel silt upon.

Amount of estimate - Rs 468-49.

(iii) Constructing a tunnel

at a place where carts cross.

Amount of estimate - Rs 63-0-6.

(IV) Constructing a porulakatta or waste weir. Amount of estimate - Rs 46-14-0.

2. Items (III) and (IV) are masonry works, the cost of which may be borne by Govt. with reference to rules (I) and (II) in G.O. 3999 of 2.5.93, but the works comprising items (I) and (II) appear to be of a kind which should properly be done by the interested ryots. It is not explained in the papers before Govt., why these persons should not be made to execute these works which form the major portion of the estimate. But as the sanction to the estimate is recommended by both by the Chief Engineer for Irrigation and the Board of Revenue, it may perhaps be presumed that these authorities have satisfied themselves that the works should not be left to be done by the interested ryots.

Orders are requested.

To the S.

Please see Report to accompany the estimate, which describes the four items of work to be done. The removal ^{to a distance} of the heap of sand ~~near~~ round the head spring will effect a permanent improvement to the channel, and cannot fairly be thrown upon the ryots.

The excavation of a bench on either bank for throwing silt on is a convenience that may also be provided by Govt. It is submitted that all the items may be sanctioned.

Rs
25-9-98

Sey

For order.

2. No doubt some collection would have got the work done {
Kudumaramat.

17/8/98

H.24.

Yes: an efficient folk or
but the work has no
doubt been allowed to
remain undone year
after year till it had become a heavy
burden on the ryots

J. A.

3/10/98

May be sanctioned with
the remark that if the execution
of Kudumaramat had been
regularly attended to in past
years the estimates under (i) & (ii)

would probably have been
unnecessary.

S.H.

4/10/78

Yes
RA
4.10.98

When given for copying _____
When copied _____
When examined _____
When signed _____ } 189

READ AGAIN G.O., No
189

DATED

CURRENT No.

ENCLOSURES TO G. No.

ORDER OF GOVERNMENT ... A A A A A A A

LETTERS OF GOVERNMENT.

STATEMENT WITH DUTY.

PAPERS NOT FILED UP, BEING AHEAD FOR DISPATCH
IN ORIGINAL.

N.B.—

A = Copy in full.
B = Not to be copied.
P = Copy abstract only.
Q = Copy heading only.