

(1) Number of pages 1

(2) Date of repair _____

(3) Initials of the Referencer _____

MADRAS RECORD OFFICE.

Government of Madras.

Public Works DEPARTMENT.

G.O. No. 1807

Press
Mis.

357-358

Dated 15. 6. 1867.

Not to be folded or roughly handled

9

Proceedings of the Madras Government, Public Works Department.
15th June 1867.

No. 357. Read the following Proceedings of the Board of Revenue, dated 20th May 1867, No. 3,087 :—

Read the following letter from the Collector of Salem, to the Secretary to the Board of Revenue, dated 9th May 1867, No. 105.

With reference to your letter, dated 11th June 1866, No. 3,972, I have the honour to forward, in the prescribed form, a nominal list of important irrigation works which are most urgently in need of repair in this district.

Nominal List of Important Irrigation Works urgently

Talook.	Village.	Name of Irrigation work.	Total registered Nunnah Ayacut.	Tax payable on whole Nunnah Ayacut.	Average tax actually paid from 1840 to 1850.
1	2	3	4	5	
Salem	Anoopur	Tank	6 2 15	RS. A. P. 36 14 0	RS. A. P.
Do.	Vadagothurumpetty	Do.	10 9 2	60 14 9	
Do.	Pullipetty	Do.	101 23 14	369 10 8	
Do.	Kamanakenputty	Pond	4 34 0	21 0 5	
Do.	Paladipuram	Tank	51 17 15	523 4 4	
Do.	Mullamoopumpetty	Do.	29 8 13	174 3 6	
Do.	Kamalapuram	Small tank	206 17 8	1,372 5 1	
Do.	Do.	Large do.	172 10 15	1,136 1 1	
Do.	Verapandy	Anicut channel	87 24 12	806 9 6	
Do.	Do.	Tank	37 20 5	341 11 1	
Do.	Athipetty	Do.	29 0 13	116 1 4	
Do.	Do.	Pond	19 36 14	82 13 7	
Do.	Thoppapetty	Tank	276 22 13	1,860 7 5	
Do.	Kullagoomby	Do.	93 28 3	866 0 9	
Do.	Puttoopoliem	Do.	188 0 11	1,446 4 2	
Do.	Konaripetty	Do.	111 25 4	1,014 1 8	
Do.	Vadugum	Pond	23 38 15	223 5 11	
Do.	Do.	Tank	46 29 13	350 15 5	
Do.	Anagalayam	Do.	395 31 14	1,500 15 5	
Do.	Eachal	Do.	164 0 8	1,214 8 1	

Works Department, 15th June 1867.

in need of repair in the Salem District.

Average tax actually paid from 1850 to 1860.	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.	Date of last repair.
6	7	8	9	10
RS. A. P.		RS. A. P.		
.....	4 10 8	23 8 3	Earth work Stone do. Sluice repair	Not repaired for a long time.
24 14 2	12 8 14	50 12 4	Earth work Stone do. Sluice do. Channel do.	Do.
286 13 2	101 23 14	369 10 8	Earth work Stone do. Sluice do. Channel do.	Breach of tank was repaired last year.
.....	4 34 0	21 0 5	Earth work Stone do.	Not repaired for a long time.
505 10 7	51 17 15	523 4 4	Sluice work	Do.
128 0 3	29 8 13	174 3 6	Embankment work	Not known.
1,372 5 1	206 17 8	1,372 5 1	Earth and stone work	Do.
630 15 3	167 1 2	1,096 2 9	Do.	Do.
806 9 6	87 24 12	806 9 6	To remove mound	Repaired about 6 years ago.
341 11 1	37 20 5	341 11 1	Do.	Do. do. 10 do.
116 1 4	29 0 13	116 1 4	Stone work	Not known when repaired.
16 7 6	19 36 14	82 13 7	Sluice work	Do.
1,860 7 5	267 36 12	1,813 10 1	Stone work and earth work for channels	Do.
623 3 9	93 28 3	866 0 9	Do.	Do.
995 6 5	188 0 11	1,446 4 2	Sluice work Earth and stone do.	Do.
1,014 1 8	103 5 8	965 6 11	Stone and plaster work for calingulah	Repaired about 10 years ago.
223 2 8	23 38 15	223 5 11	Sluice work	Not known when repaired.
329 2 5	46 29 13	350 15 5	Do.	Do.
1,500 15 5	339 39 10	1,394 13 3	Earth work	Do.
1,214 8 1	164 0 8	1,214 8 1	Earth and stone work...	Stone work raised about 5 or 6 years ago

Proceedings of the Madras Government, Public

Nominal List of Important Irrigation Works urgently

Talook.	Village.	Name of Irrigation work.	Total registered Nunjah Ayacut.	Tax payable on whole Nunjah Ayacut.	Average tax actually paid from 1840 to 1850.
1	2	3	4	5	
Salem ...	Ananthakistnaroya Sa-	Tank. ...	62 6 1	RS. A. P. 408 1 11	
Do. ...	Vaniembady ...	Do. ...	84 13 13	438 6 7	
Do. ...	Pethamputty ...	Do. ...	61 2 11	341 11 9	
Do. ...	Byroji ...	Anicut channel...	30 26 14	240 5 6	
Do. ...	Do. ...	Tank ...	12 33 14	105 12 6	
Do. ...	Mathamputty ...	Tank channel ...	41 3 6	222 9 1	
Do. ...	...	Tank ...	37 13 7	278 1 8	
Do. ...	Chemageri ...	Channel ...	42 10 7	349 8 11	
Do. ...	Do. ...	Anicut channel ...	96 34 10	777 4 1	
Do. ...	Paranattamungalum ...	Tank ...	38 36 8	359 13 0	
Do. ...	Ariyagoundenputty ...	Do. ...	52 8 4	438 15 6	
Do. ...	Mookcettupoliem ...	Do. ...	44 14 12	310 8 1	
Do. ...	Savoothapuram ...	Do. ...	39 9 3	179 13 1	
Do. ...	Papraputty ...	Do. ...	64 34 12	780 1 7	
Do. ...	Vengamputty ...	Anicut for the three tanks.	299 28 7	2,169 12 7	
Do. ...	Mullur ...				
Do. ...	Amapoliem ...	Anicut.	77 10 1	289 14 8	
Do. ...	Bulbacki ...				
Do. ...	Pannargoodal ...	Tank ...	164 8 4	586 2 3	
Do. ...	Palumattooputty ...	Do. ...	18 23 8	102 13 7	
Do. ...	Do. ...	Anicut channel...	56 18 14	281 13 11	

Works Department, 15th June 1867.

Need of repair in the Salem District.

Average tax actually paid from 1850 to 1860.	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.	Date of last repair.
6	7	8	9	10
RS. A. P. 408 1 11	39 31 1	RS. A. P. 280 12 11	Sluice work ...	Not known when repaired.
376 14 7	84 13 13	438 6 7	Earth work and stone work for anicut channel	Do.
			Sluice work ...	
			250 0 0	
			20 0 0	
			270 0 0	
201 5 9	61 2 11	341 11 9	Plaster work for calingulah	Repaired by earth some 5 years ago.
			Earth work for bund ...	
			50 0 0	
			50 0 0	
			100 0 0	
240 5 6	30 26 14	210 5 6	Earth work ...	Repaired about 7 or 8 years ago.
105 12 6	12 33 14	105 12 6	Stone and earth work...	Repaired about 10 years ago.
222 9 1	41 3 6	222 9 1	Do. ...	Do. 5 years ago.
239 8 9	37 13 7	278 1 8	Do. ...	Do.
349 8 11	40 7 6	331 8 5	To repair the stone work at the mouth of the channel.	Repaired about 2 years ago.
777 4 1	96 34 10	777 4 1	Stone work for anicut	Do. 5 years ago.
			Earth work for channel	
			25 0 0	
			100 0 0	
			125 0 0	
296 4 1	34 14 7	321 14 4	Earth work ...	Repaired about 5 years ago.
			Sluice bund ...	
			50 0 0	
			25 0 0	
			75 0 0	
373 11 2	52 8 4	438 15 6	Earth work and sluice bund work. ...	Not known when repaired.
305 0 11	42 19 8	276 10 10	Earth work for bund...	Repaired about 3 years ago.
178 12 8	37 7 5	167 8 7	Stone work for calingulah and earth work for water course	Repaired in Fusly 1269.
780 1 7	60 25 4	730 0 8	Earth work ...	Not repaired for a long time.
1,989 5 6	272 32 5	1,816 0 10	Stone and lime work for breached anicut	Not known when repaired.
204 6 8	67 32 8	250 6 0	For anicut repair ...	Fusly 1265.
586 2 3	103 9 0	580 4 4	Earth and stone work to raise the bund ...	Not known when repaired.
102 13 7	15 8 2	82 8 10	For sluice ..	Do.
281 13 11	52 34 14	260 12 6	Earth work for channel	Do.
			70 0 0	

Nominal List of Important Irrigation Works urgently

Talook.	Village.	Name of Irrigation work.	Total registered Nannah Ayacut.	Tax payable on whole Nannah Ayacut.	Average tax actually paid from 1850 to 1860.
1	2	3	4	5	6
Salem	Thiruvilaku	Tank	313 25 12	RS. A. P. 2,126 13 7	RS. A. P. 2,126 13 7
Do.	Thoothamputty	Do.	37 0 3	263 8 5	263 8 5
Do.	Yalaumputty	Do.	94 19 13	594 11 4	352 12 7
Do.	Taramungalum	Do.	134 23 7	962 7 0	831 11 3
Do.	Omalar	Anicut channel	249 2 13	1,409 0 6	700 12 8
Do.	Puchamputty	Tank	38 16 12	234 2 10	94 12 6
Do.	Naikaraputty	Do.	18 6 3	101 0 1	46 0 8
Do.	Gollaputty	Do.	45 16 6	268 2 3	150 5 2
Do.	Moothuputty	Do.	25 30 6	139 12 9	55 11 0
Do.	Manathul	Do.	189 6 1	1,729 5 4	1,020 15 2
Do.	Vamavasi	Do.	20 7 9	109 10 1	97 12 3
Do.	Senaraputty	Do.	14 12 13	50 13 10	45 3 3
Do.	Eachalumputty	Do.	9 3 14	28 3 10	28 3 10
Do.	Katamputty	Do.	2 36 6	14 0 0	13 4 9
Do.	Rajagoundenputty	Do.	16 37 15	122 13 4	59 6 7
Do.	Ariyamputty	Do.	12 11 10	102 13 4	35 14 8
Do.	Sulavoodi	Anicut	9 3 1	80 4 1	17 3 4
Do.	Verakulputty	Tank	1 15 7	11 15 5	11 15 5

in need of repair in the Salem District.

Average tax actually paid from 1850 to 1860.	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.	Date of last repair.
6	7	8	9	10
RS. A. P. 2,126 13 7	306 8 12	RS. A. P. 1,917 11 11	Earth and stone work... 400 0 0	In Fusly 1265.
263 8 5	24 3 2	169 12 9	To raise the bund ... 70 0 0	Do. 1266.
352 12 7	69 36 7	393 13 6	Do. ... 200 0 0	Not known when repaired.
831 11 3	110 12 14	885 13 11	To remove the earth on the bed of tank. 300 0 0	In Fusly 1266.
700 12 8	213 18 0	1,049 0 0	To repair channel and breach of anicut. 300 0 0	Not known when repaired.
94 12 6	29 32 9	180 3 10	To raise bund ... 100 0 0	Do.
46 0 8	15 32 3	81 3 11	Do. ... 100 0 0	Do.
150 5 2	40 11 9	222 11 3	Sluice work ... 50 0 0	Not repaired since 20 years.
			Earth work and stone work 70 0 0	
			120 0 0	
55 11 0	24 5 14	126 3 10	To repair calingulah ... 70 0 0	Not repaired since 12 years.
			Sluice work ... 50 0 0	
			Earth work for bund ... 100 0 0	
			220 0 0	
1,020 15 2	129 12 4	1,278 4 2	To repair calingulah ... 100 0 0	Not known when repaired.
			To plaster sluice ... 50 0 0	
			Stone and earth work ... 100 0 0	
			250 0 0	
97 12 3	19 23 9	106 4 3	To level bund ... 20 0 0	Not repaired since 6 years.
			Stone work ... 50 0 0	
			70 0 0	
45 3 3	14 12 13	50 13 10	Earth and stone work for bund, stone work for calingulah. 100 0 0	Do.
28 3 10	5 4 1	15 13 6	To repair blocked sluice 15 0 0	Not known when repaired.
13 4 9	2 36 6	13 4 9	Do. ... 10 0 0	Do.
			Stone work for bund ... 25 0 0	
			35 0 0	
59 6 7	10 24 0	67 3 6	Earth and stone work ... 70 0 0	Not repaired since 10 years.
35 14 8	1 2 5	8 3 2	Sluice repair ... 20 0 0	Band repaired in Fusly 1265.
17 3 4	4 6 0	34 9 3	Stone and earth work ... 70 0 0	Not repaired since 10 years.
11 15 5	1 15 7	11 15 5	Calingulah work ... 10 0 0	Not known when repaired.
			Sluice repair ... 10 0 0	
			20 0 0	

Proceedings of the Madras Government, Public

Nominal List of Important Irrigation Works urgently

Talook.	Village.	Name of irrigation work.	Total registered Nungal Ayaat.	Tax payable on whole Nungal Ayaat.	Average tax actually paid from 1840 to 1850.
1	2	3	4	5	6
Salem ...	Auroovaputty ...	Tank ...	80 27 10	RS. A. P. 625 12 6	RS. A. P. 435 6 5
Do. ...	Amakoothutty ...	Do. ...	22 33 7	134 15 5	124 4 7
Do. ...	Kasooevadeputty ...	Do. ...	9 31 4	42 1 8	29 4 5
Do. ...	Mullicoodi ...	Do. ...	16 31 9	109 14 4	86 7 2
Do. ...	Kaligoundencoor ...	Do. ...	33 26 5	166 9 2	139 11 1
Do. ...	Tharapuram ...	Anicut channel...	40 23 15	188 14 6	
Do. ...	Do. ...	Tank ...	403 26 11	2,506 7 11	
Ahtur ...	Vellayur ...	Do. ...	79 6 7	1,029 6 6	442 13 2
Do. ...	Thadavoor ...	Do. ...	501 0 9	5,845 8 6	4,374 9 2
Do. ...	Ponavasal ...	Do. ...	222 15 11	2,528 12 8	1,460 2 2
Do. ...	Sithari ...	Do. ...	105 13 3	1,421 9 8	957 3 4
Do. ...	Poothoor ...	Do. ...	120 14 10	273 10 2	
Do. ...	Yathapuram ...	Do. ...	196 2 7	882 5 4	508 1 4
Do. ...	Abnavum ...	Do. ...	15 6 4	139 11 4	103 15 10
Do. ...	Pethmarkenpoliem ...	Do. ...	33 12 8	267 7 2	204 6 1

Works Department, 15th June 1867.

in need of repair in the Salem District.

Average tax actually paid from 1850 to 1860.	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.	Date of last repair.
6	7	8	9	10
RS. A. P. 476 0 4	80 27 10	RS. A. P. 625 12 6	Sluice repair ... 50 0 0 Level bund ... 100 0 0 To raise calingulah ... 50 0 0 Stone work for bund ... 70 0 0 Earth work ... 70 0 0 340 0 0	Not known when repaired.
109 3 4	19 3 8	130 15 7	To raise calingulah ... 50 0 0	Do.
23 11 1	5 23 9	24 9 10	Earth work ... 20 0 0 Stone do. ... 10 0 0 30 0 0	Do.
81 0 4	13 30 10	95 11 3	Earth and stone work... 40 0 0	Do.
136 9 2	27 2 2	133 8 10	Do. ... 50 0 0	Do.
123 14 1	40 23 15	188 14 6	Plaster work ... 500 0 0	Do.
1,174 2 10	403 26 11	2,506 7 11	Earth work ... 200 0 0	Do.
732 4 5	70 0 10	327 1 1	Stone do. ... 58 7 0 Earth do. ... 10 15 6 69 6 6	
4,755 14 10	416 1 12	4,399 10 1	Stone work ... 468 12 0 Earth do. ... 147 10 6 616 6 6	
2,013 4 2	205 0 11	2,098 3 11	Earth work ... 110 10 0	
853 7 6	96 8 11	1,145 1 1	Earth do. ... 91 9 7 Stone do. ... 149 6 0 240 15 7	
66 0 0			Earth work ... 154 0 6 Stone do. ... 150 1 3 304 1 9	
676 1 6	123 5 11	676 1 6	Earth work ... 147 15 0 Stone do. ... 49 2 0 197 1 0	Not known.
118 0 3	13 7 5	110 7 7	Earth work ... 7 0 6 Sluice do. ... 25 0 0 32 0 6	Do.
203 14 5	30 13 8	237 6 9	Earth work ... 24 3 0 New stone do. ... 37 8 0 Channel do. ... 23 8 0 Earth do. ... 137 5 0 227 8 0	

Proceedings of the Madras Government, Public

Nominal List of Important Irrigation Works urgently

Taluk.	Village.	Name of Irrigation work.	Total registered Numb. of Ayacut.	Tax payable on whole Numb. of Ayacut.	Average tax actually paid from 1840 to 1850.
1	2	3	4	5	6
Ahtur ...	Navallur ...	Tank ...	222 14 0	RS. A. P. 2,675 4 2	RS. A. P. 1,132 3 7
Do. ...	Veraganoor ...	Do. ...	257 13 7	3,924 15 10	3,826 9 1
Do. ...	Ramanaikenpoliem ...	Anicut channel...	72 4 0	480 4 0	330 0 0
Do. ...	Chinnasamoodrum ...	Anicut ...	275 7 0	2,537 15 11	1,466 8 0
Do. ...	Do. ...	Tank ...	115 0 0	1,256 0 0	952 11 2
Do. ...	Pariyari ...	Do. ...	189 1 3	1,507 15 1	1,312 4 10
Do. ...	Do. ...	Anicut channel...	6 4 4	68 8 2	...
Do. ...	Auraganoor ...	Tank ...	193 6 8	1,567 11 10	1,421 11 9
Do. ...	Thinganoor ...	Do. ...	115 15 0	1,076 2 11	857 0 0
Do. ...	Do. ...	Anicut channel...	57 3 0	578 7 7	376 0 0
Darampury...	Anasagarum ...	Tank ...	291 0 0	1,463 0 0	1,361 0 0

Works Department, 15th June 1867.

in need of repair in the Salem District.

Average tax actually paid from 1850 to 1860.	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.	Date of last repair.
6	7	8	9	10
RS. A. P. 1,629 6 6	169 10 5	RS. A. P. 1,804 13 8	New and old stone work ... 52 3 0 Brick and chunam ... 41 2 0 93 5 0	
3,630 4 9	240 10 1	2,825 15 2	Old stone work ... 13 4 0 Earth do. ... 34 7 3 New stone do. ... 53 2 0 99 13 3	
590 0 0	55 8 0	309 1 9	New stone work ... 21 0 0 Channel do. ... 42 3 0 Earth do. ... 11 2 0 New stone do. ... 3 15 0 78 5 0	
2,041 11 2	266 2 6	2,273 0 1	New stone work ... 420 0 0 Brick and lime ... 120 0 0 Stone work ... 3 6 0 543 6 0	
1,075 4 9	98 12 2	792 10 9	Earth work ... 150 9 0 Old stone do. ... 50 10 0 New do. do. ... 35 10 0 236 13 0	
1,185 15 4	175 5 5	1,295 11 0	Earth work ... 77 4 4 New stone work ... 105 14 0 Old do. do. ... 35 15 0 217 1 4	
34 5 10	6 1 5	58 4 4	Channel repair ... 236 11 6	
475 8 9	192 2 7	1,548 15 2	Earth work ... 195 14 8 Old stone do. ... 29 11 0 New do. ... 35 10 0 Earth work for channel 11 11 6 272 15 2	
932 4 9	102 11 2	853 1 10	Earth work ... 154 7 10 Old stone do. ... 62 8 0 New do. ... 213 12 0 460 11 10	
322 4 9	43 7 3	325 11 8	Channel repair ... 10 2 0	
340 0 0	268 0 0	1,304 0 0	Earth work ... 20 0 0 Stone do. ... 30 0 0 Bund do. ... 50 0 0 100 0 0	Repaired about 4 years ago.

Proceedings of the Madras Government, Public

Nominal List of Important Irrigation Works urgently

Talook.	Village.	Name of irrigation work.	Total registered Nampah Ayalam.	Tax payable on whole Nampah Ayalam.	Average tax actually paid from 1850 to 1859.
1	2	3	4	5	6
Darampury	Yendeor	Tank	53 0 0	244 0 0	213 0 0
Do.	Pedamanary	Do	40 0 0	192 0 0	187 0 0
Do.	Kristnapuram	Do	133 0 0	573 0 0	537 0 0
Do.	Kittayathumhully	Do	7 0 0	34 0 0	2 0 0
Do.	Vengaramhully	River ancient	30 0 0	112 0 0	112 0 0
Do.	Do.	Ancient	9 0 0	37 0 0	22 0 0
Do.	Koombarahully	Tank	1 0 0	6 0 0	4 0 0
Do.	Do.	New tank	4 0 0	14 0 0	12 0 0
Do.	Mullasamudrum	Tank	17 0 0	104 0 0	99 0 0
Do.	Do.	Ancient	54 0 0	223 0 0	101 0 0
Do.	Taramungalum	Tank	61 0 0	326 0 0	169 0 0
Do.	Thasagoundenhully	Nullah	16 0 0	65 0 0	61 0 0
Do.	Snookalloor	Tank	32 0 0	156 0 0	100 0 0

Works Department, 15th June 1867.

in need of repair in the Salem District.

Average tax actually paid from 1850 to 1859.	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.	Date of last repair.
6	7	8	9	10
RS. A. P. 224 0 0	54 0 0	RS. A. P. 236 0 0	Earth work ... 100 0 0 Stone do. ... 100 0 0 200 0 0	Repaired about 15 years ago.
189 0 0	30 0 0	143 0 0	Stone work ... 70 0 0 Earth do. ... 70 0 0 140 0 0	Do.
565 0 0	186 0 0	575 0 0	Earth work ... 80 0 0 Stone do. ... 20 0 0 100 0 0	Do.
2 0 0	7 0 0	34 0 0	Earth work ... 50 0 0 Stone do. ... 50 0 0 100 0 0	Repaired about 30 years ago.
150 0 0	28 0 0	157 0 0	Stone work ... 50 0 0	Repaired 15 years ago.
23 0 0	8 0 0	33 0 0	Do. ... 20 0 0	Do.
6 0 0	1 0 0	6 0 0	Earth work ... 50 0 0 Stone do. ... 20 0 0 Bund do. ... 10 0 0 80 0 0	Repaired about 20 years ago.
14 0 0	4 0 0	14 0 0	Earth work ... 30 0 0 Stone do. ... 7 0 0 Plaster do. ... 23 0 0 60 0 0	Do.
97 0 0	17 0 0	104 0 0	Earth work ... 50 0 0 Stone do. ... 20 0 0 70 0 0	Do. 15 years ago.
122 0 0	32 0 0	125 0 0	Stone work ... 48 12 0	Do.
176 0 0	45 0 0	207 0 0	Earth do. ... 70 0 0 Stone do. ... 25 0 0 Plaster do. ... 50 0 0 145 0 0	Do.
62 0 0	16 0 0	65 0 0	Stone work for the breach 16 0 0	Not known.
97 0 0	32 0 0	156 0 0	Earth work ... 10 0 0 Stone do. ... 15 0 0 Plaster do. ... 30 0 0 55 0 0	Repaired about 4 years ago.

Proceedings of the Madras Government, Public

Nominal List of Important Irrigation Works urgently

Talook.	Village.	Name of Irrigation work.	Total registered Nampah Aynat.	Tax payable on whole Nampah Aynat.	Average tax actually paid from 1840 to 1860.
	1	2	3	4	5
Darampury.	Poliem...	Tank ...	55 0 0	RS. A. P. 156 0 0	RS. A. P. 125 0 0
Do.	Do.	Do.	14 0 0	37 0 0	35 0 0
Do.	Jarithalavoo	Small tank	43 0 0	119 0 0	99 0 0
Do.	Do.	Tank	27 0 0	142 0 0	136 0 0
Do.	Do.	Do.	251 0 0	1,119 0 0	985 0 0
Do.	Sivady...	Do.	16 0 0	81 0 0	40 0 0
Do.	...	Anicut channel...	221 0 0	1,667 0 0	819 0 0
Do.	Anthanoor	Tank	34 0 0	119 0 0	Being Muta tank, no average has been calculated.
Do.	Sathianathapuram	Do.	34 0 0	89 0 0	Do.
Namkul	Thathayarputty	Do.	245 8 2	1,666 14 8	1,641 15 3
Do.	Mahadary	Do.	301 9 13	1,472 9 6	591 8 6
Do.	Voorakary	Large tank	89 35 13	280 0 9	

Works Department, 15th June 1867.

in need of repair in the Salem District.

Average tax actually paid from 1850 to 1860.	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.	Date of last repair.
6	7	8	9	10
RS. A. P. 98 0 0	25 0 0	RS. A. P. 107 0 0	Earth work ... Stone do. ... Plaster do. ... 30 0 0	Repaired about 20 years ago.
31 0 0	13 0 0	32 0 0	Earth work ... Stone do. ... Plaster do. ... 30 0 0	Do.
96 0 0	23 0 0	119 0 0	Stone work ... Do. ...	Not known when repaired. Repaired 4 years ago.
1,096 0 0	250 0 0	1,114 0 0	To raise the bund of the tank ... Earth work ... Stone do. ... 35 0 0	Calingulah repaired last year. Repaired 20 years ago.
1,117 0 0	128 0 0	565 0 0	Earth, stone, and plaster work ... Earth work ... Stone do. ... 40 0 0	Repaired last year. Not known when repaired.
82 0 0	23 0 0	58 0 0	Earth work ... Stone do. ... 160 0 0	Do.
1,695 15 8	224 6 6	1,578 12 10	Earth work ... Newstone do. ... 327 3 6	
1,021 10 0	199 3 12	1,140 8 3	Earth work ... Old stone ... New do. ... 930 4 9	
40 6 2	18 37 14	41 1 3	Earth work ... Old stone do. ... New do. do. ... 1,110 0 0	

Proceedings of the Madras Government, Public

Nominal List of Important Irrigation Works urgently

Talook.	Village.	Name of irrigation work.	Total registered Nunjah Ayacut.	Tax payable on whole Nunjah Ayacut.	Average tax actually paid from 1840 to 1850.
1	2	3	4	5	6
Namkul ...	Karoompully ...	Tank ...	339 3 3	Rs. A. P. 340 15 10	Rs. A. P. 202 15 9
Do. ...	Pellathori ...	Do. ...	183 6 5	638 3 5	616 9 1
Do. ...	Sarookoody ...	Do. ...	93 37 9	481 8 4	271 2 1
Do. ...	Samboomadi ...	Do. ...	156 6 10	315 14 3	93 2 5
Do. ...	Paramathy ...	Do. ...	29 22 7	169 5 8	170 0 0
Do. ...	Yecombunkolum ...	Do. ...	225 3 4	2,738 10 11	598 8 1
Do. ...	Malsathamboor ...	Ancient ...	101 13 15	395 2 5	242 4 2
Tripatore ...	Paroomapattu ...	Tank ...	99 14 10	557 7 5	494 10 2
Do. ...	Jadayanoor ...	Do. ...	53 28 10	315 5 2	316 2 7
Do. ...	Nasarcopum ...	Do. ...	88 16 12	179 1 9	200 0 6

Works Department, 15th June 1867.

in need of repair in the Salem District.

Average tax actually paid from 1850 to 1860.	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.	Date of last repair.
6	7	8	9	10
Rs. A. P. 256 11 11	118 37 1	Rs. A. P. 337 12 7	Earth work ...	Rs. A. P. 261 4 0
607 2 7	127 28 11	613 2 11	Earth work ...	141 1 6
			Old stone ...	43 12 0
			New do. ...	75 4 0
				260 1 6
329 11 5	27 33 1	269 5 5	Earth work ...	135 11 3
			Old stone ...	426 8 0
			New do. ...	170 10 0
				732 13 3
157 14 11	105 8 2	228 4 0	Earth work ...	257 13 0
			New stone ...	328 2 0
				585 15 0
128 10 4	29 22 7	169 5 8	New stone ...	70 8 0
			Brick work ...	52 14 0
				123 6 0
591 12 11	161 21 9	1,933 7 0	Earth work ...	74 2 0
			Old stone do. ...	265 10 0
			New do. ...	192 6 0
			Brick do. ...	52 8 0
				584 10 6
279 13 1	72 7 1	263 10 7	Old stone work ...	13 0 6
			Brick work ...	137 10 0
				150 10 6
587 7 3	99 14 10	557 7 5	Sluice work ...	50 0 0
			Earth work for bund...	100 0 0
			Stone work ...	100 0 0
			Calingulah do. ...	50 0 0
				300 0 0
322 11 9	53 93 10	315 5 2	Sluice work ...	50 0 0
			Bund do. ...	50 0 0
				100 0 0
191 4 6	36 9 4	163 2 1	Calingulah work ...	25 0 0
			Earth do. ...	5 8 0
			To raise bund ...	6 4 0
				36 12 0

Proceedings of the Madras Government, Public

Nominal List of Important Irrigation Works urgently

Talook.	Village.	Name of Irrigation work.	Total registered Nuziah Ayacut.	Tax payable on whole Nuziah Ayacut.	Average tax actually paid from 1840 to 1850.
1	2	3	4	5	6
Trippatore...	Odaynuthur	Tank	45 29 4	RS. A. P. 250 3 11	RS. A. P. 197 8 4
Do.	Sitary	Do.	41 21 14	210 11 4	163 1 8
Do.	Koratee...	Do.	18 14 9	90 5 9	45 0 11
Do.	Chelaraputty	Do.	61 17 1	274 6 5	186 5 1
Do.	Keelkuppem	Do.	29 18 0	135 13 4	147 6 3
Do.	Kumecche	Do.	114 13 1	320 15 0	239 3 8
Do.	Aluvempetty	Do.	23 7 13	100 15 0	62 1 6
Do.	Bungarumpetty	Do.	82 14 12	517 11 7	295 9 10
Do.	Kondakindanapully	Do.	8 2 0	40 9 2	22 0 2
Do.	Jankalpuram	Pond	21 26 6	80 4 10	

Works Department, 15th June 1867.

n need of repair in the Salem District.

Average tax actually paid from 1850 to	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.	Date of last repair.
7	8	9	10	
RS. A. P. 219 4 10	38 0 14	RS. A. P. 205 12 9	Earth work ... 100 0 0 Stone do. ... 100 0 0 Earth do. ... 100 0 0 Stone do. ... 150 0 0 Sluice do. ... 50 0 0 500 0 0	
210 5 10	40 33 13	207 8 7	Earth work ... 50 0 0 Stone do. for bund ... 150 0 0 200 0 0	
72 3 0	18 9 9	89 12 7	Earth work ... 150 0 0 New bund ... 50 0 0 200 0 0	
181 8 5	55 14 12	245 10 3	Stone work ... 90 0 0 Bund ... 60 0 0 Repair of bund ... 50 0 0 200 0 0	
160 0 0	25 34 1	138 11 3	Sluice repair ... 35 0 0 Earth work ... 50 0 0 Stone do. ... 50 0 0 135 0 0	
266 9 1	63 15 12	309 8 8	Earth work ... 200 0 0 Stone do. ... 40 0 0 60 0 0 0	
76 15 6	23 7 13	100 15 0	Earth work ... 100 0 0 Stone do. ... 100 0 0 Sluice do. ... 50 0 0 250 0 0	
360 13 0	62 35 15	373 8 11	Stone work ... 150 0 0 Earth do. ... 100 0 0 Sluice do. ... 50 0 0 300 0 0	Last repaired in 1835.
43 2 11	8 2 0	40 9 2	Earth work ... 75 0 0 Sluice do. ... 50 0 0 Stone do. ... 18 4 0 143 4 0	Not known.
62 2 2	21 26 6	80 4 10	Earth work ... 50 0 0 Stone do. ... 100 0 0 Sluice do. ... 50 0 0 200 0 0	

Proceedings of the Madras Government, Public

Nominal List of Important Irrigation Works urgently

Talook.	Village.	Name of Irrigation work.	Total registered Nunnah Ayacut.	Tax payable on whole Nunnah Ayacut.	Average tax actually paid from 1850 to 1855.
	1	2	3	4	5
Trippa-tore	Jankalpuram ...	Tank ...	31 1 10	RS. A. P. 92 2 1	
Do.	Do.	Pallan Pond ...	16 34 2	60 15 4	
Do.	Umbulur ...	Tank ...	35 13 3	219 13 1	165 10 4
Do.	Thorayaree ...	Puthu tank ...	19 9 1	61 2 10	
Do.	Do.	Pala tank ...	17 21 4	51 12 8	
Utengerry...	Komeraputty ...	Nullah ...	100 0 0	372 0 0	133 0 0
Do.	Puonaree ...	Tank ...	15 0 0	47 0 0	12 1 9
Do.	Do.	Do.	13 0 0	41 0 0	20 0 0
Do.	Kadamadeeputty ...	Do.	12 0 0	37 0 0	1 0 0
Do.	Soreyempetty ...	Do.	10 0 0	34 0 0	18 0 0
Do.	Muruporeputty ...	Do.	14 0 0	43 0 0	21 0 0
Do.	Thimmeshetty ...	Tank ...	8 0 0	28 0 0	11 0 0
Do.	Nachempetty ...	Do.	3 0 0	17 0 0	11 0 0
Do.	Puthenuthum ...	Nullah ...	25 0 0	79 0 0	13 0 0
Do.	Katupetty ...	Anicut ...	10 0 0	34 0 0	13 0 0
Do.	Thoppunputty ...	Pond ...	5 0 0	15 0 0	1 0 0
Do.	Venkatatathampetty ...	Tank ...	52 0 0	237 0 0	32 0 0
Do.	Thurpunnthippumpetty...	Do.	9 0 0	34 0 0	13 0 0
Do.	Analamputty ...	Do.	9 0 0	59 0 0	46 0 0
Do.	Varegamoor ...	Do.	13 0 0	62 0 0	34 0 0
Do.	Puttavanoor ...	Do.	22 0 0	104 0 0	60 0 0
Do.	Valampetty ...	Do.	3 0 0	12 0 0	8 0 0
Do.	Munthepetty ...	Pond ...	1 0 0	2 0 0	2 0 0
Do.	Thengerkota ...	Tank ...	70 0 0	284 0 0	112 0 0
Do.	Pyrenatham ...	Do.	31 0 0	123 0 0	123 0 0
Do.	Nashionampetty ...	Do.	39 0 0	86 0 0	13 0 0
Do.	Hurur ...	Do.	134 0 0	628 0 0	511 0 0
Do.	Do.	Do.	3 0 0	5 0 0	1 0 0
Do.	Mavareepetty ...	Pond ...	14 0 0	47 0 0	21 0 0
Do.	Chemakupura ...	Sluice ...	10 0 0	34 0 0	11 0 0
Do.	Yellapaddiputty ...	Do.	29 0 0	90 0 0	23 0 0
Do.	Thundakuppem ...	Do.	9 0 0	41 0 0	15 0 0
Do.	Vedaputty ...	Do.	13 0 0	54 0 0	22 0 0
Do.	Narayandikuppem ...	Do.	14 0 0	53 0 0	29 0 0
Do.	Thathampetty ...	Do.	7 0 0	21 0 0	11 0 0
Do.	Tharunaputty ...	Tank ...	10 0 0	25 0 0	16 0 0

Works Department, 15th June 1867.

in need of repair in the Salem District.

Average tax actually paid from 1850 to 1855.	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.	Date of last repair.
6	7	8	9	10
RS. A. P. 90 4 2	31 1 0	RS. A. P. 92 2 1	Stone work ... 150 0 0 Earth do. ... 100 0 0 Sluice do. ... 50 0 0 300 0 0	Not known.
40 3 10	16 34 2	60 15 4	New sluice ... 50 0 0 Do. calingulah ... 50 0 0 Earth work ... 50 0 0 Stone do. ... 50 0 0 200 0 0	
216 0 2	35 13 3	219 13 1	Earth work ... 700 0 0 Stone do. ... 324 12 0 Repair of sluice ... 70 0 0 Calingulah ... 50 8 0 1,145 4 0	
63 4 9	19 9 1	61 2 10	Earth work ... 57 8 0 Stone do. ... 122 0 0 179 8 0	
46 8 1	17 21 4	51 12 8	Earth work ... 43 12 0 Stone do. ... 34 0 0 Sluice do. ... 35 0 0 Calingulah ... 20 10 0 133 6 0	
246 0 0	100 0 0	372 0 0	300 0 0	1865-1866.
24 0 0	15 0 0	47 0 0	200 0 0	
18 0 0	8 0 0	27 0 0	150 0 0	
20 0 0	8 0 0	26 0 0	100 0 0	
21 0 0	8 0 0	27 0 0	100 0 0	
26 0 0	7 0 0	20 0 0	50 0 0	
19 0 0	5 0 0	7 0 0	30 0 0	
12 0 0	3 0 0	17 0 0	50 0 0	
13 0 0	9 0 0	28 0 0	40 0 0	
20 0 0	8 0 0	25 0 0	50 0 0	
8 0 0	4 0 0	13 0 0	25 0 0	
88 0 0	31 0 0	167 0 0	300 0 0	
26 0 0	4 0 0	17 0 0	70 0 0	
46 0 0	8 0 0	45 0 0	50 5 0	
54 0 0	5 0 0	26 0 0	50 0 0	
57 0 0	3 0 0	11 0 0	300 0 0	Do. Do.
11 0 0	3 0 0	12 0 0	50 0 4	
2 0 0	1 0 0	2 0 0	30 0 0	
05 0 0	0 0 0	0 0 0	1,200 0 0	
23 0 0	34 0 0	123 0 0	2,000 0 0	
13 0 0	30 0 0	86 0 0	300 0 0	
549 0 0	134 0 0	600 0 0	1,500 0 0	
5 0 0	3 0 0	5 0 0	50 0 0	
32 0 0	12 0 0	41 0 0	100 0 0	
16 0 0	8 0 0	28 0 0	150 0 3	
14 0 0	18 0 0	57 0 0	200 0 0	
21 0 0	0 0 0	0 0 0	150 0 0	
41 0 0	12 0 0	53 0 0	200 0 0	
27 0 0	13 0 0	52 0 0	300 0 0	
11 0 0	7 0 0	21 0 0	250 0 0	
23 0 0	7 0 0	19 0 0	50 0 0	

Proceedings of the Madras Government, Public

Nominal List of Important Irrigation Works urgently

Talook.	Village.	Name of Irrigation work.	Total registered Nannajah Ayacut.	Tax payable on whole Nannajah Ayacut.	Average tax actually paid from 1810 to 1850.
1	2	3	4	5	6
Trippa tore	Jankalpuram	Tank	31 1 10	RS. A. P. 92 2 1	
Do.	Do.	Pallan Pond	16 34 2	60 15 4	
Do.	Umbalur	Tank	33 13 3	219 13 1	165 10 4
Do.	Thorayarco	Puthu tank	19 9 1	61 2 10	
Do.	Do.	Pala tank	17 21 4	51 12 8	
Utengerri...	Komeraputty	Nullah	100 0 0	372 0 0	153 0 0
Do.	Puonaree	Tank	15 0 0	47 0 0	12 0 0
Do.	Do.	Do.	13 0 0	41 0 0	20 0 0
Do.	Kadameduputty	Do.	12 0 0	37 0 0	1 0 0
Do.	Soreyempetty	Do.	10 0 0	30 0 0	8 0 0
Do.	Muraporeputty	Do.	14 0 0	43 0 0	21 0 0
Do.	Thimmesetty	Tank	8 0 0	28 0 0	11 0 0
Do.	Nachempetty	Do.	3 0 0	17 0 0	11 0 0
Do.	Lathenathum	Nullah	25 0 0	79 0 0	13 0 0
Do.	Katuputty	Anicut	10 0 0	31 0 0	13 0 0
Do.	Thoppuputty	Pond	5 0 0	15 0 0	1 0 0
Do.	Venkatatathamputty	Tank	52 0 0	237 0 0	32 0 0
Do.	Thirupanthippumpetty	Do.	9 0 0	31 0 0	13 0 0
Do.	Analamputty	Do.	9 0 0	59 0 0	46 0 0
Do.	Vareganoor	Do.	13 0 0	62 0 0	54 0 0
Do.	Putravanoor	Do.	22 0 0	104 0 0	60 0 0
Do.	Valamputty	Do.	3 0 0	12 0 0	8 0 0
Do.	Munthuputty	Pond	1 0 0	2 0 0	2 0 0
Do.	Thengerkota	Tank	70 0 0	284 0 0	112 0 0
Do.	Pyeenathum	Do.	31 0 0	123 0 0	123 0 0
Do.	Nashempetty	Do.	39 0 0	86 0 0	13 0 0
Do.	Murur	Do.	134 0 0	628 0 0	511 0 0
Do.	Do.	Do.	3 0 0	5 0 0	1 0 0
Do.	Mavareepetty	Pond	14 0 0	47 0 0	21 0 0
Do.	Chemakupma	Sluice	10 0 0	34 0 0	11 0 0
Do.	Yellapaddiputty	Do.	29 0 0	90 0 0	23 0 0
Do.	Kandakuppem	Do.	9 0 0	41 0 0	15 0 0
Do.	Yallaputty	Do.	13 0 0	54 0 0	32 0 0
Do.	Narayandikuppem	Do.	14 0 0	53 0 0	29 0 0
Do.	Thathamputty	Do.	7 0 0	21 0 0	11 0 0
Do.	Thuramputty	Tank	10 0 0	25 0 0	16 0 0

Works Department, 15th June 1867.

in need of repair in the Salem District.

Average tax actually paid from to 9.	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.	Date of last repair.
6	7	8	9	10
RS. A. P. 90 4 2	31 1 0	RS. A. P. 92 2 1	Stone work ... 150 0 0 Earth do. ... 100 0 0 Sluice do. ... 50 0 0 300 0 0	Not known.
40 3 10	16 34 2	60 15 4	New sluice ... 50 0 0 Do. calingulah ... 50 0 0 Earth work ... 50 0 0 Stone do. ... 50 0 0 200 0 0	
216 0 2	35 13 3	219 13 1	Earth work ... 700 0 0 Stone do. ... 324 12 0 Repair of sluice ... 70 0 0 Calingulah ... 50 8 0 1,145 4 0	
63 4 9	19 9 1	61 2 10	Earth work ... 57 8 0 Stone do. ... 122 0 0 179 8 0	
46 8 1	17 21 4	51 12 8	Earth work ... 43 12 0 Stone do. ... 34 0 0 Sluice do. ... 35 0 0 Calingulah ... 20 10 0 133 6 0	
246 0 0	100 0 0	372 0 0	...	1865-1866.
24 0 0	15 0 0	47 0 0	...	
18 0 0	8 0 0	27 0 0	...	
20 0 0	8 0 0	26 0 0	...	
21 0 0	8 0 0	27 0 0	...	
26 0 0	7 0 0	20 0 0	...	
19 0 0	5 0 0	7 0 0	...	
12 0 0	3 0 0	17 0 0	...	
13 0 0	9 0 0	28 0 0	...	
20 0 0	8 0 0	25 0 0	...	
8 0 0	4 0 0	13 0 0	...	
88 0 0	31 0 0	167 0 0	...	
26 0 0	4 0 0	17 0 0	...	
46 0 0	8 0 0	45 0 0	...	
51 0 0	5 0 0	26 0 0	...	
57 0 0	3 0 0	11 0 0	...	
11 0 0	3 0 0	12 0 0	...	
2 0 0	1 0 0	2 0 0	...	
105 0 0	0 0 0	0 0 0	...	
23 0 0	34 0 0	123 0 0	...	
13 0 0	30 0 0	86 0 0	...	
49 0 0	134 0 0	600 0 0	...	
5 0 0	3 0 0	5 0 0	...	
32 0 0	12 0 0	41 0 0	...	
16 0 0	8 0 0	28 0 0	...	
14 0 0	18 0 0	57 0 0	...	
21 0 0	0 0 0	0 0 0	...	
41 0 0	12 0 0	53 0 0	...	
27 0 0	13 0 0	52 0 0	...	
11 0 0	7 0 0	21 0 0	...	
23 0 0	7 0 0	19 0 0	...	

Proceedings of the Madras Government, Public

Nominal List of Important Irrigation Works urgently

Talook.	Village.	Name of Irrigation work.	Total registered Nunjah Ayacut.	Tax payable on whole Nunjah Ayacut.	Average tax actually paid from 1841 to 1850.
1	2	3	4	5	6
				RS. A. P.	RS. A. P.
Utengerry ...	Mavareepully ...	Tank and sluice.	8 0 0	23 0 0	9 0 0
Do. ...	Chengulvady ...	Sluice ...	21 0 0	70 0 0	25 0 0
Do. ...	Chellapully ...	Do. ...	21 0 0	62 0 0	26 0 0
Do. ...	Shonumpully ...	Do. ...	40 0 0	125 0 0	54 0 0
Do. ...	Athakarepully ...	Tank ...	61 0 0	234 0 0	11 0 0
Do. ...	Alamalupuram ...	Tank and bund of channel.	16 0 0	56 0 0	26 0 0
Do. ...	Alapuram ...	Tank and sluice ...	243 0 0	1,169 0 0	343 0 0
Do. ...	Do. ...	Bund of anicut and digging channel.	135 0 0	640 0 0	194 0 0
Do. ...	Manushe ...	Tank and sluice.	28 0 0	83 0 0	9 0 0
Oosoor ...	Konrasuntherum ...	Anicut ...	12 0 0	41 0 0	14 0 0
Do. ...	Salevarum ...	Tank ...	14 0 0	53 0 0	32 0 0
Do. ...	Thupsapully ...	Do. ...	82 0 0	376 0 0	0 0 0
Do. ...	Aglakota ...	Do. ...	11 0 0	57 0 0	37 0 0
Do. ...	Madumuthukota ...	Do. ...	37 0 0	199 0 0	137 0 0
Do. ...	Polliemkota ...	Do. ...	28 0 0	163 0 0	41 0 0
Do. ...	Thasarepully ...	Do. ...	37 0 0	144 0 0	105 0 0

Works Department, 15th June 1867.

in need of repair in the Salem District.

Average tax actually paid from 1850 to 1860.	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.	Date of last repair.
6	7	8	9	10
RS. A. P.		RS. A. P.	RS. A. P.	
11 0 0	8 0 0	23 0 0	...	...
40 0 0	20 0 0	55 0 0	...	...
40 0 0	18 0 0	53 0 0	...	...
71 0 0	32 0 0	100 0 0	...	...
35 0 0	16 0 0	78 0 0	...	...
35 0 0	13 0 0	42 0 0	...	...
928 0 0	233 0 0	1,082 0 0	...	...
433 0 0	124 0 0	571 0 0	...	...
31 0 0	24 0 0	14 0 0	...	...
14 0 0	0 0 0	0 0 0	...	...
...	...	...	Earth-work ...	...
...	...	...	Stone do. ...	...
...	...	...	Lime do. ...	...
...	...	...	...	...
24 0 0	7 0 0	28 0 0	...	...
...	...	...	Earth-work ...	...
...	...	...	Stone do. ...	...
...	...	...	Bund do. ...	...
...	...	...	...	...
213 0 0	28 0 0	128 0 0	...	...
...	...	...	Earth-work ...	...
...	...	...	Stone do. ...	...
...	...	...	Sluice do. ...	...
...	...	...	...	...
37 0 9	8 0 0	38 0 0	...	...
...	...	...	Earth-work ...	...
...	...	...	Stone do. ...	...
...	...	...	Lime do. ...	...
...	...	...	...	...
139 0 0	23 0 0	132 0 0	...	...
...	...	...	Earth-work ...	...
...	...	...	Stone do. ...	...
...	...	...	Lime do. ...	...
...	...	...	...	...
69 0 0	20 0 0	123 0 0	...	...
...	...	...	Earth-work ...	...
...	...	...	Stone do. ...	...
...	...	...	Lime do. ...	...
...	...	...	...	...
110 0 0	26 0 0	113 0 0	...	...
...	...	...	Earth-work ...	...
...	...	...	Stone do. ...	...
...	...	...	Lime do. ...	...
...	...	...	...	...

Proceedings of the Madras Government, Public

Nominal List of Important Irrigation Works urgently

Talook.	Village.	Name of Irriga- tion work.	Total regis- tered Nun- jah Ayacut.	Tax payable on whole Nunjah Ayacut.	Average tax actually paid from
1	2	3	4		
Oosoor ...	Tharanabatum ...	Tank ...	32 0 0	RS. A. P. 101 0 0	RS. A. P. 18 0 0
Do. ...	Do. ...	Do. ...	9 0 0	53 0 0	0 0 0
Do. ...	Oshanddee ...	Do. ...	13 0 0	48 0 0	0 0 0
Do. ...	Komaranpully ...	Do. ...	44 0 0	243 0 0	167 0 0
Do. ...	Do. ...	Do. ...	13 0 0	37 0 0	11 0 0
Do. ...	Pethamanagaram ...	Do. ...	24 0 0	85 0 0	32 0 0
Do. ...	Chenamanagaram ...	Do. ...	63 0 0	230 0 0	80 0 0
Do. ...	Samatharanabully ...	Do. ...	22 0 0	131 0 0	95 0 0
Do. ...	Bagalagoundahalli ...	Do. ...	17 0 0	101 0 0	72 0 0

Works Department, 15th June 1867.

in need of repair in the Salem District.

Average tax actually paid from 1850 to	Present Cul- tivation.	Present Revenue.	Rough estimate of repairs needed.	Date of last repair.
6	7	8	9	10
RS. A. P. 18 0 0	9 0 0	38 0 0	Earth work ... Stone do. ... Lime do. ... RS. A. P. 10 0 0 15 0 0 35 0 0	Not under Circar repair.
0 0 0	9 0 0	53 0 0	Earth work ... Stone do. ... Lime do. ... RS. A. P. 20 0 0 30 0 0 30 0 0	Do.
0 0 0	0 0 0	0 0 0	Earth work ... Stone do. ... Lime do. ... RS. A. P. 10 0 0 20 0 0 50 0 0	Do.
166 0 0	41 0 0	243 0 0	Earth work ... Stone do. ... Lime do. ... RS. A. P. 30 0 0 40 0 0 35 0 0	20 years ago.
20 0 0	30 0 0	37 0 0	Earth work ... Stone do. ... Lime do. ... RS. A. P. 50 0 0 100 0 0 50 0 0	Never under Circar repair.
34 0 0	19 0 0	75 0 0	Earth work ... Stone do. ... Lime do. ... RS. A. P. 80 0 0 100 0 0 50 0 0	Do.
146 0 0	59 0 0	268 0 0	Earth work ... Stone do. ... Lime do. ... RS. A. P. 100 0 0 100 0 0 50 0 0	10 years ago.
100 0 0	16 0 0	96 0 0	Earth work ... Stone do. ... Lime do. ... RS. A. P. 100 0 0 100 0 0 0 0 0	Fusly 1270.
82 0 0	17 0 0	101 0 0	Earth work ... Stone do. ... Lime do. ... RS. A. P. 20 0 0 30 0 0 50 0 0	Fusly 1265.

Proceedings of the Madras Government, Public

Nominal List of Important Irrigation Works urgently

Talook.	Village.	Name of Irrigation work.	Total registered Nunjah Ayacut.	Tax payable on whole Nunjah Ayacut.	Average tax actually
1	2	3	4	5	6
Oosoor ...	Moranabulli ...	Tank ...	11 0 0	RS. 49 0 0	A. 7 0 0
Do. ...	Oosoor ...	Do. ...	9 0 0	54 0 0	51 0 0
Do. ...	Barakanhalli ...	Do. ...	10 0 0	49 0 0	36 0 0
Do. ...	Charandaballi ...	Do. ...	133 0 0	867 0 0	676 0 0
Do. ...	Naralahuddi ...	Do. ...	7 0 0	28 0 0	23 0 0
Do. ...	Auchiteo ...	Anicut and tank.	55 0 0	273 0 0	51 0 0
Do. ...	Thamasunhalli ...	Tank. ...	16 0 0	61 0 0	20 0 0
Do. ...	Bannikullu ...	Do. ...	49 0 0	326 0 0	173 0 0
Do. ...	Sennathur ...	Do. ...	32 0 0	250 0 0	225 0 0
Do. ...	Anumandapuram ...	Anicut ...	10 0 0	23 0 0	11 0 0
Do. ...	Timmanhaddi ...	Tank ...	12 0 0	69 0 0	13 0 0

Works Department, 15th June 1867.

in need of repair in the Salem District.

Average tax actually paid from	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.	Date of last repair.
6	7	8	9	10
RS. 10 0 0			Earth work ... Stone do. ... Lime do. ...	Fusly 1272.
52 0 0	8 0 0	50 0 0	Earth work ... Stone do. ... Lime do. ...	Known to have been repaired by Circar some time ago.
15 0 0	3 0 0	16 0 0	Stone work ...	About 15 years ago.
572 0 0	105 0 0	654 0 0	Earth work ... Stone do. ... Lime do. ...	Slightly repaired 10 years ago.
18 0 0	5 0 0	22 0 0	Earth work ... Stone do. ...	Never repaired by Circar.
57 0 0	2 0 0	12 0 0	Earth work ... Stone do. ...	Repaired in Fusly 1236.
26 0 0	7 0 0	20 0 0	Earth work ... Stone do. ... Lime do. ...	Not known to have been repaired by Circar.
223 0 0	49 0 0	326 0 0	Earth work ... Stone do. ... Lime do. ...	Repaired 8 years ago.
222 0 0	29 0 0	233 0 0	Earth work ... Stone do. ... Lime do. ...	Repaired 20 years ago.
3 0 0	9 0 0	19 0 0	Earth work ... Stone do. ...	Not known to have been repaired by Circar.
11 0 0	4 0 0	22 0 0	Earth work ... Lime do. ...	Slightly repaired 15 years ago.

Proceedings of the Madras Government, Public

Nominal List of Important Irrigation Works urgently

Talook.	Village.	Name of Irrigation work.	Total registered Nunjah Ayacut.	Tax payable on whole Nunjah Ayacut.	Average tax actually
1	2	3	4		
				RS. A. P.	RS. A. P.
Oosoor ...	Osahaddi ...	Tank ...	25 0 0	110 0 0	57 0 0
Do. ...	Bairakundahalli ...	Anicut ...	17 0 0	98 0 0	89 0 0
Do. ...	Pallaballi ...	Tank ...	97 0 0	646 0 0	475 0 0
Do. ...	Upparayanahalli...	Do. ...	69 0 0	407 0 0	167 0 0
Do. ...	Rungapuram ...	Do. ...	19 0 0	94 0 0	27 0 0
Do. ...	Mallasamudram...	Do. ...	24 0 0	170 0 0	85 0 0
Do. ...	Pitharandi ...	Do. ...	19 0 0	107 0 0	23 0 0
Do. ...	Adakkam ...	Do. ...	9 0 0	39 0 0	3 0 0
Do. ...	Dasirihalli ...	Do. ...	28 0 0	131 0 0	74 0 0
Do. ...	Ullukurnakai ...	Do. ...	14 0 0	88 0 0	31 0 0

Works Department, 15th June 1867.

in need of repair in the Salem District.

Average tax actually paid from	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.	Date of last repair.
5	7	8	9	10
RS. A. P.		RS. A. P.	RS. A. P.	
75 0 0	21 0 0	97 0 0	Earth work ... 100 0 0 Stone do. ... 150 0 0 Lime do. ... 80 0 0 330 0 0	Slightly repaired 15 years ago.
95 0 0	3 0 0	18 0 0	Stone work ... 200 0 0 Earth do. ... 20 0 0 Lime do. ... 200 0 0 420 0 0	Do.
308 0 0	66 0 0	458 0 0	Earth work ... 50 0 0 Stone do. ... 50 0 0 Lime do. ... 50 0 0 150 0 0	Do.
162 0 0	17 0 0	101 0 0	Earth work ... 100 0 0 Stone do. ... 50 0 0 Lime do. ... 100 0 0 250 0 0	Do.
33 0 0	8 0 0	39 0 0	Earth work ... 50 0 0 Stone do. ... 20 0 0 Lime do. ... 25 0 0 95 0 0	Not known to have been repaired by Circular.
81 0 0	14 0 0	80 0 0	Earth work ... 100 0 0 Stone do. ... 200 0 0 300 0 0	Do.
18 0 0	12 0 0	73 0 0	Earth work ... 150 0 0 Lime do. ... 30 0 0 180 0 0	Do.
.....			Earth work ... 100 0 0 Stone do. ... 100 0 0 Lime do. ... 50 0 0 250 0 0	Do.
92 0 0	9 0 0	41 0 0	Earth work ... 80 0 0 Stone do. ... 100 0 0 180 0 0	Repaired about 15 years ago.
58 0 0	6 0 0	36 0 0	Earth work ... 60 0 0 Stone do. ... 60 0 0 120 0 0	Repaired about 6 years ago.

Proceedings of the Madras Government, Public

Nominal List of Important Irrigation Works urgently

Talook.	Village.	Name of Irrigation work.	Total registered Nunjah Ayacut.	Tax payable on whole Nunjah Ayacut.	Average tax actually
1	2	3	4		
Oosoor ...	Balur ...	Tank ...	24 0 0	RS. A. P. 92 0 0	RS. A. P. 50 0 0
Do. ...	Panjahalli ...	Do. ...	212 0 0	890 0 0	241 0 0
Do. ...	Osapuram ...	Do. ...	82 0 0	438 0 0	296 0 0
Do. ...	Senkarayapuram ...	Do. ...	27 0 0	134 0 0	132 0 0
Do. ...	Balikorai ...	Do. ...	10 0 0	55 0 0	38 0 0
Do. ...	Doddarayasandram ...	Do. ...	45 0 0	239 0 0	85 0 0
Do. ...	Sanjanhulli ...	Do. ...	22 0 0	110 0 0	49 0 0
Do. ...	Andevan ...	Do. ...	38 0 0	165 0 0	131 0 0
Do. ...	Kandakamhalli ...	Do. ...	8 0 0	40 0 0	12 0 0
Do. ...	Do. ...	Do. ...	7 0 0	17 0 0	

Works Department, 15th June 1867.

in need of repair in the Salem District.

Average tax actually paid from	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.	Date of last repair.
7	8	9	10	
RS. A. P. 52 0 0	20 0 0	RS. A. P. 73 0 0	Earth work ... Stone do. ... Lime do. ... 220 0 0	Repaired about 20 years ago.
302 0 0	6 0 0	31 0 0	Earth work ... Stone do. ... Lime do. ... 1,000 0 0	Do.
288 0 0	80 0 0	435 0 0	Earth work ... Stone do. ... 320 0 0	Repaired about 10 years ago.
134 0 0	17 0 0	86 0 0	Earth work ... Stone do. ... Lime do. ... 200 0 0	Repaired some time ago by Circar.
26 0 0	5 0 0	29 0 0	Earth work ... Stone do. ... Lime do. ... 130 0 0	Do.
85 0 0	18 0 0	91 0 0	Earth work ... Stone do. ... 200 0 0	Repaired about 15 years ago.
66 0 0	13 0 0	77 0 0	Earth work ... Lime do. ... 100 0 0	Do.
118 0 0	26 0 0	115 0 0	Earth work ... Stone and lime work ... 140 0 0	Do.
38 0 0	3 0 0	16 0 0	Earth work ... Stone do. ... Lime do. ... 200 0 0	Do.
.....			Earth work ... Stone do. ... Lime do. ... 100 0 0	Not known to have been repaired by Circar.

Proceedings of the Madras Government, Public

Nominal List of Important Irrigation Works urgently

Talook.	Village.	Name of Irrigation work.	Total registered Nannah Ayacut.	Tax payable on whole Nannah Ayacut.	Average tax actually
1	2	3	4		
				RS. A. P.	RS. A. P.
Oosoor ...	Kandakamhalli...	Tank ...	17 0 0	67 0 0	59 0 0
Do. ...	Tandarai ...	Do. ...	78 0 0	562 0 0	251 0 0
Do. ...	Do. ...	Do. ...	43 0 0	243 0 0	107 0 0
Do. ...	Mukanur ...	Do. ...	14 0 0	72 0 0	60 0 0
Do. ...	Do. ...	Do. ...	14 0 0	64 0 0	44 0 0
Do. ...	Mukasibarandur ...	Do. ...	39 0 0	239 0 0	194 0 0
Do. ...	Denkenicotta ...	Do. ...	58 0 0	247 0 0	139 0 0
Do. ...	Do. ...	Do. ...	10 0 0	44 0 0	34 0 0
Do. ...	Anjattidrugam...	Do. ...	7 0 0	27 0 0	16 0 0
Do. ...	Jakkeri...	Do. ...	23 0 0	120 0 0	73 0 0
Do. ...	Kaduttanhalli ...	Do. ...	4 0 0	25 0 0	5 0 0

Works Department, 15th June 1867.

in need of repair in the Salem District.

Average tax actually	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.	Date of last repair.
5	7	8	9	10
RS. A. P.		RS. A. P.	RS. A. P.	
36 0 0	15 0 0	60 0 0	Earth work ... 90 0 0 Stone do. ... 100 0 0 Lime do. ... 35 0 0 225 0 0	About 20 years ago.
232 0 0	34 0 0	216 0 0	Earth work ... 80 0 0 Stone do. ... 120 0 0 200 0 0	Repaired about 10 years ago.
136 0 0	15 0 0	78 0 0	Stone work ... 300 0 0	Do.
54 0 0	13 0 0	65 0 0	Earth work ... 60 0 0 Stone do. ... 70 0 0 Lime do. ... 50 0 0 180 0 0	Repaired about 15 years ago.
40 0 0	10 0 0	50 0 0	Earth work ... 100 0 0 Stone do. ... 100 0 0 200 0 0	Do.
209 0 0	34 0 0	224 0 0	Earth work ... 300 0 0 Stone do. ... 200 0 0 Lime do. ... 100 0 0 600 0 0	Do.
195 0 0	46 0 0	210 0 0	Earth work ... 50 0 0 Stone do. ... 100 0 0 150 0 0	Repaired about 10 years ago.
29 0 0	7 0 0	11 0 0	Earth work ... 50 0 0 Stone do. ... 50 0 0 100 0 0	Do.
6 0 0			Earth work ... 60 0 0 Stone do. ... 40 0 0 100 0 0	Repaired about 20 years ago.
83 0 0	18 0 0	90 0 0	Earth work ... 100 0 0 Stone do. ... 50 0 0 150 0 0	Do.
11 0 0	3 0 0	18 0 0	Earth work ... 30 0 0 Stone do. ... 20 0 0 50 0 0	Do.

Proceedings of the Madras Government, Public

Nominal List of Important Irrigation Works urgently

Talook.	Village.	Name of Irrigation work.	Total registered Nunjah Ayacut.	Tax payable on whole Nunjah Ayacut.	Average tax
1	2	3	4		
Oosoor ...	Konasamudram...	Anicut ..	37 0 0	RS. A. P. 216 0 0	RS. A. P. 206 0 0
Do. ...	Onnukurikki ...	Tank ...	5 0 0	23 0 0	
Do. ...	Sasivadi ...	Do. ...	159 0 0	775 0 0	296 0 0
Do. ...	Mottamaggrarm ...	Do. ...	8 0 0	26 0 0	16 0 0
Do. ...	Akaram...	Do. ...	15 0 0	90 0 0	26 0 0
Do. ...	Tokarai ...	Do. ...	133 0 0	985 0 0	539 0 0
Do. ...	Do. ...	Anicut ...	29 0 0	187 0 0	86 0 0
Do. ...	Tenganhalli ...	Tank ...	173 0 0	1,223 0 0	632 0 0
Do. ...	Nakondahalli ...	Do. ...	28 0 0	148 0 0	119 0 0
Do. ...	Dasirihalli ...	Do. ...	25 0 0	116 0 0	96 0 0

Works Department, 15th June 1867.

in need of repair in the Salem District.

Average tax actually	Present Cultivation.	Present Revenue.	Rough estimate of repairs needed.	Date of last repair.
	7	8	9	10
RS. A. P. 180 0 0		RS. A. P.	Stone work ... Lime do.	Repaired about 10 years ago.
.....			Earth work ... Stone do.	Does not appear to have been repaired by Circular.
493 0 0	91 0 0	455 0 0	Earth work ... Stone do. ... Lime do. ...	Repaired about 10 years ago.
16 0 0	4 0 0	9 0 0	Earth work ... Stone do.	Do.
28 0 0	14 0 0	88 0 0	Earth work ... Stone do. ... Lime do. ...	Do.
757 0 0	96 0 0	695 0 0	Earth work ... Stone do. ... Lime do. ...	Do.
79 0 0	15 0 0	83 0 0	Stone work ... Lime do.	Repaired 20 years ago.
856 0 0	118 0 0	949 0 0	Earth work ... Stone do. ... Lime do. ...	Repaired 10 years ago.
126 0 0	17 0 0	99 0 0	Earth work ... Stone do. ... Lime do. ...	Repaired 8 years ago.
98 0 0	25 0 0	116 0 0	Earth work ... Stone do. ... Lime do. ...	Repaired 20 years ago.

Proceedings of the Madras Government, Public

Nominal List of Important Irrigation Works urgently

Talook.	Village.	Name of Irrigation work.	Total registered Nunnah Ayacut.	Tax payable on whole Nunnah Ayacut.	Average tax
1	2	3	4		
Oosoor ...	Kongiseti ...	Tank ...	9 0 0	56 0 0	56 0 0
Trichengode.	Konasamudrum and Thapapuram.	Two ponds ...	31 0 12	254 12 10	205 2 1
Do. ...	Konasamudrum ...	Tank ...	58 8 0	590 10 5	278 8 1
Do. ...	Lekkapuram ...	Do. ...	27 27 4	199 2 0	80 9 9
Do. ...	Ilippili ...	Do. ...	111 27 5	676 14 7	498 8 4
Do. ...	Kakari ...	Do. ...	52 15 5	157 5 3	
Do. ...	Yedangausalai ...	Do. ...	23 4 8	135 3 6	59 11 9
Do. ...	Sattanpalayam ...	Do. ...	23 32 12	112 9 8	44 4 1
Do. ...	Konari ...	Do. ...	38 13 12	187 10 4	77 6 0
Do. ...	Kachaballi ...	Do. ...	40 32 13	117 2 8	4 0 2
Do. ...	Kottanampatti ...	Do. ...	51 30 15	163 3 0	46 1 3
Do. ...	Kannadani ...	Do. ...	32 13 15	236 8 3	71 5 0
Do. ...	Settur ...	Do. ...	21 35 6	156 9 6	42 1 8
Do. ...	Bandinattan ...	Do. ...	78 13 7	324 6 7	268 12 10
Do. ...	Balur ...	Do. ...	539 38 6	2,514 14 6	2,767 2 9
Do. ...	Akaram ...	Do. ...	106 17 14	483 0 3	201 4 7
Do. ...	Karivappumpatti ...	Do. ...	59 12 15	272 8 10	179 13 0
Do. ...	Vapumpalli ...	Do. ...	111 4 3	884 6 2	513 4 6
Do. ...	Trichengode ...	Pond ...	26 19 3	159 1 3	131 9 2
Do. ...	Gunnambadi ...	Tank ...	54 8 3	452 14 10	219 6 4
Do. ...	Dadapuram ...	Do. ...	38 32 13	316 15 9	116 5 3
Do. ...	Ilippalli ...	Do. ...	29 3 0	201 10 9	64 0 3

SALEM,
9th May 1867.

Works Department, 15th June 1867.

in need of repair in the Salem District.

Average tax actually	Present Cultivatn.	Present Revenue.	Rough estimate of repairs needed.	Date of last repair.
.....	7	8	9	10
.....		RS. A. P.	Earth work RS. A. P.	Repaired in Fusly 1255.
			Stone do. 50 0 0	
			Lime do. 50 0 0	
			150 0 0	
213 13 0	27 9 15	230 15 20	...	36 00
315 0 4	47 31 0	481 6 11	...	103 12 0
100 15 7	18 2 9	136 3 3	...	62 13 0
595 10 3	98 16 12	603 6 9	...	413 7 0
56 14 8	18 30 13	81 15 4	...	216 12 0
69 0 11	16 30 12	102 11 1	...	48 2 0
75 10 10	16 23 14	77 13 1	...	34 12 0
147 7 7	20 18 7	118 12 9	...	94 4 0
71 7 3	34 6 6	103 4 2	...	91 11 0
86 6 5	46 13 4	144 10 4	...	53 9 0
94 15 5	1 18 3	6 12 9	...	100 15 0
66 10 7	7 30 5	51 3 1	...	45 6 0
277 11 5	59 27 0	250 2 9	...	1,470 10 0
2,692 7 9	289 25 20	2,555 4 10	...	378 0 0
372 5 11	68 9 2	437 5 10	...	142 10 0
235 15 7	36 4 10	247 7 5	...	196 14 0
186 12 10	61 5 5	494 12 8	...	98 7 0
129 15 5	23 19 7	128 5 2	...	59 15 0
270 5 6	32 31 5	305 0 7	...	171 5 0
88 6 4	14 33 8	109 5 9	...	188 13 0
41 3 2	9 4 7	53 12 6	...	233 10 0

(Signed) C. N. FOCHIN,
Collector.

*Proceedings of the Madras Government, Public Works Department,
15th June 1867.*

Ordered that the foregoing letter, with its enclosure, be submitted to Government, with reference to their Order in the Public Works Department, dated 17th May 1866, No. 1,587.

No. 358.

ORDER THEREON, 15th June 1867, No. 1,807.

IRRIGATION, No. 13.

1. Ordered that the \$
received with this letter be forwarded
the Superintending Engineer of the 5th
Officers concerned.

2. Measures should be taken for placing as many of the irrigation works as possible in a proper state of repair from the Budget provision of Rupees 26,000 for "Minor tanks and channels" in the Salem District.

(True Extract.)

Colonel, R. E.,

Secretary to Government.

To the Superintending Engineer, 5th Division.
 „ Revenue Department.
 „ Board of Revenue.

Exd. S. T. Augustin.

Name of Irrigation work	Total regis-tered Acreage on who	Tax payed	Average tax actually paid from	Average tax actually paid from	Present cultiva-tion	Present revenue	Present estimate of repairs needed	Date of last repair
	Aryaen	8 muga	40 to 1850	from 1860				
	Aryaen			5-1860				
2	3	4	5	6	7	8	9	10

Dr. Kinnaman's fully Paid

3 rd	Pachydermus	Small	81	17 15	523
3 rd	Knathamapungu	Gr.	27	8 13	174
3 rd	Knathamapungu	Small Gr.	208	17 8 13	572
3 rd	Gr.	Large Gr.	172	10 15	1136
3 rd	Vasapandy	Arriest channel	87	24 12	806
3 rd	Gr.	Trunk	37	25 5	341
3 rd	Althapandy	Gr.	29	13	116
3 rd	Gr.	Pond	19	36 14	82
3 rd	Thoppapandy	Trunk	276	22 13	1560

93	283	863
188	11	1446

[illegible]

Salem	Vadugam	Pond	23 38 15	223 5
Dr.	Dr.	Tank	41 29 13	350 18
Dr.	Anajalayam	Dr.	395 31 14	1500 10
Dr.	Eachal	Dr.	164 " 8	1214 8

Dr.	Ananthakistur	Dr.	62 6 1	408 1
	roya Somasundram			
Dr.	Vinnambady	Dr.	84 13 13	438 1

Dr.	Pethampatty	Dr.	61 2 11	341 11
-----	-------------	-----	---------	--------

Dr.	Bogri	Ancient Channel	30 26 14	240 5
-----	-------	-----------------	----------	-------

Dr.	Madurai	Tank	12 38 14	115 12
-----	---------	------	----------	--------

Dr.	Nathamputty	Tank Channel	41 3 6	222 9
-----	-------------	--------------	--------	-------

Dr.		Tank	27 13 7	278 18
-----	--	------	---------	--------

Dr.	Chinnai	Channel	42 10 7	349 8 11
-----	---------	---------	---------	----------

	Ancient Channel		96 34 10	777 4 1
--	-----------------	--	----------	---------

"	228 2 8	23 38 15	223 5 11	Stone work	20 " "	80th year when repaired
"	329 2 5	41 29 13	350 15 5	Dr.	50 " "	Dr.
"	1500 15 5	339 39 10	1394 13 3	South work	35 " "	Dr.
"	1214 8 1	164 " 8	1214 8 1	South work	200 " "	Stone work raised about 5 or 6 yrs ago

"	408 1 11	39 31 1	280 12 11	Stone work	20 " "	80th year when repaired
---	----------	---------	-----------	------------	--------	-------------------------

"	376 14 7	84 13 13	438 1 7	South work	20 " "	Dr.
				Stone work for	200 " "	
				ancient		
				channel		

				Stone work	20 " "	
					270 " "	

"	201 5 9	61 2 11	341 11 9	Plaster work	50 " "	Repaired by south some 5 years ago
				for Calingala		
				South work for	50 " "	
				Gravel	100 " "	

"	240 5 6	30 26 14	240 5 6	South work	110 " "	Repaired about 10 yrs ago
---	---------	----------	---------	------------	---------	---------------------------

"	105 12 6	12 33 14	105 12 6	Stone work	100 " "	Repaired about 10 yrs ago
				work		

"	222 9 1	41 3 6	222 9 1	Dr.	100 " "	Dr. 5 yrs ago
"	239 8 9	37 13 7	278 1 8	Dr.	50 " "	Dr.

"	349 8 11	40 7 6	331 8 5	Stone work	50 " "	Repaired about 2 years ago
				to mouth of		
				the channel		

"	777 4 1	96 34 10	777 4 1	Stone work	25 " "	Dr. 5
				for Ancient		

				South work	100 " "	10 years ago
				Channel		
					125 " "	

Saravali Sarammangalam Tank

38 34 8 329 12

Dr. Ariyagounderputty Dr.

52 8 4 158 12

Dr. Moskottupolam Dr.

44 14 12 310 81

Dr. Sarvathapuranam Dr.

39 9 3 179 13

Dr. Paparaputty Dr.

14 34 12 780 17

Dr. Vengamputty

Ancient for the three tanks

299 28 7 2169 127

Dr. Annapoliem

Dr. Bulbachi

Ancient

77 10 1 289 148

Dr. Pannogodal Tank

104 8 4 586 23

Dr. Palammattuputty Dr.

18 23 8 102 137

Dr. Ancient Channel

56 18 14 281 13 11

Dr. Shisavilaku Tank

313 25 12 212 6 137

Dr. Shrothamputty Dr.

37 " 8 263 8 5

Dr. Yalamamputty Dr.

94 19 15 594 11 2

Dr. Sarammangalam Dr.

134 23 7 962 7

Dr. Annam Ancient Channel

249 2 13 1409 " 14

4 14

296 4 1 34 14 7 321 14 4

Repaired

Since built 25 " about 5 years ago

373 11 2 52 8 4 438 15 4

Not known

Since built 100 " when repaired work

305 " 11 42 19 8 276 10 10

Repaired about

100 " 3 yrs ago

178 12 8 37 1 5 167 8 7

Repaired in

Calingula 50 " Freshly 69

for water carried

780 1 7 60 25 4 730 " 8

Not repaired for long time

1989 5 6 272 32 5 1816 " 10

Not known

work for 300 " when repaired

204 6 8 17 32 8 250 6 " 7

Freshly 1265

1000 " repair

586 2 3 103 9 " 580 4 6

Not known

stone work 200 " when repaired

102 13 7 15 8 2 82 8 10

Dr.

281 13 11 52 34 14 260 12 8

Dr.

for channel 70 " 4/11

212 13 7 306 8 12 1917 11 11

In July 1265

stone work 4/11

263 5 5 24 3 2 119 12 9

Dr. 1266

land 70 " 7/11

852 12 7 19 34 7 393 13 6

Not known when repaired

200 " 8/11

831 11 3 110 12 4 885 13 11

In July 1266

stone work 8/11

700 12 8 283 15 " 1069 " "

Not known

to repair channel

4/11 " when repaired

Salem Puchampatty Janki

58 11 12 254

D^r. Naikharapatty D^r.

18 6 3 111

D^r. Gollapatty D^r.

45 14 4 218

D^r. Mosthanpatty D^r.

25 30 1 139

D^r. Manathul D^r.

189 6 1 1729

D^r. Vannavase D^r.

20 7 9 109

D^r. Sannarapatty D^r.

14 12 13 50

D^r. Chahampatty D^r.

9 3 14 28

" " 94 12 1 29 32 9 180 3 10 to raise

land 100

Not known when repaired

" " 45 11 8 15 32 3 81 3 11 D^r 100

148 11 5 150 5 2 40 11 9 222 11 3 Shice work 50

earthwork 70

stone work 120

Not repaired since 20 years

94 13 8 55 11 10 24 5 14 126 3 10 to repair

calingula 70

Not repaired since 12 yrs

Shice work 50

earthwork 100

for land 220

1038 7 3 1020 15 2 129 12 4 1278 4 2 to repair

Kalingula 110

to plaster 50

Shice 111

stone & earth work 250

Not known when repaired

102 14 10 97 12 3 19 23 9 106 4 3 to level

land 20

stone work 50

70

Not repaired since 6 years

38 9 10 45 3 3 14 12 13 50 13 10 earth &

stone work

for land 100

stone work

for Kalingula

D^r.

28 3 10 28 3 10 5 4 1 15 13 1 to repair

blocked 15

Shice

Not known when repaired

76/10

Salem Hattampatty Tank

2 36 8

14

14

13 4 9

2 36 6

13 4 9

to repair blocked

Not known

since - 10 " " when repaired

Dr. Rajagondampatty Dr.

14 37 15

122 134

69 1 10

59 6 7

10 24 "

67 3 6

cut 10 "

Not repaired

since 10 years

Dr. Aringampatty Dr.

12 11 10

102 134

27 7 "

35 14 8

1 25 8

3 2

since repair 20 "

Not repaired

since 10 years

Dr. Salavandi Ancient

9 3 1

80 41

29 5 3

17 3 4

4 6 "

34 9 8

Stone &

Not repaired

since 10 years

Dr. Verakulputty Tank

1 15 7

11 13 3

11 15 5

11 15 5

1 15 7

11 15 5

Kalingula

Not known

when repaired

Dr. Anuvapatty Dr.

80 27 10

425 12 6

435 6 5

476 " 4

80 27 10

425 12 5

since repair 50 "

Not known

when repaired

Dr. Amakoshaty Dr.

22 33 7

134 15 5

124 4 7

109 3 4

19 3 8

130 15 7

Tornise

Not known

when repaired

Dr. Kasuvandapatty Dr.

9 31 4

42 1 8

29 4 5

28 11 1

5 23 9

24 9 10

cut 10 "

Not repaired

since 10 years

Dr. Mullicon Dr.

16 31 9

109 14 6

86 7 2

81 " 4

13 30 10

95 11 3

cut 10 "

Not known

when repaired

Dr. Kalingam Dr.

33 26 5

166 9 2

39 11 1

136 9 2

27 2 2

133 8 10

Dr. 511 "

Not known

when repaired

Dr. Thovaparam Ancient channel

40 23 15

188 14 6

" " 128 14 1

40 23 15

188 14 6

Plastic work 500 "

Not known

when repaired

since 10 years

Dr. Dr. Tank

403 26 11

2506 7 11

" " 1174 2 10

403 26 11

2506 7 11

cut 10 "

Not known

when repaired

since 10 years

Abhin Vellayam Tomb

79 6 7 1029 11 662 15 2 7324 5 70 " 10 3271 1 Stone work 58 7 "
earth 9 10 15 6
69 6 6

D^r Thadavoor D^r

501 " 9 5845 11 4374 9 2 4755 14 10 416 1 12 4399 10 1 Stone work 468 12 "
earth 8 147 10 6
116 6 6

D^r Ponnavasal D^r

232 15 11 2528 12 1 1460 2 2 2013 4 2 205 " 11 2098 3 11 earth work 110 10 "

D^r Sithani D^r

105 13 3 1421 9 1 987 3 4 853 7 6 96 8 11 1145 1 1 earth work 96 9 7
Stone 8 149 6 0
240 15 7

D^r Poothoor D^r

120 14 10 273 10 2 " " " 66 " " " " earth work 154 " 1
Stone 8 150 1 3
304 1 9

D^r Yathapannur D^r

196 2 7 882 5 4 508 1 6 676 1 6 123 5 11 676 1 6 earth work 147 15 " 804 11 11 11 11
Stone 8 49 2 "
197 1 "

D^r Abnawur D^r

15 6 4 139 11 4 103 15 10 118 " 3 13 7 5 110 7 7 earth work 7 " 6 D^r
Shrine 8 25 " "
32 " 6

D^r Pithamakkuppalam D^r

33 12 8 267 7 1 204 6 1 203 14 5 30 13 8 237 6 9 earth work 24 3 "
sun stone 8 37 8 "
Chommb 8 28 8 "
earth 8 137 5 "
227 8 "

D^r Navullur D^r

222 14 6 2675 4 2 1132 3 7 1129 6 6 119 10 5 1804 13 8 Stone work } 52 3 "
brick & chommb 41 2 "
93 5 "

Abdun Verragamon Tomb

257 13 7 3924 150

3826 9 1 5130 4 9 240 10 1 2825 15 2

stone work 12 4 "

earthwork 34 7 3

new stone 84 53 2 "

Dr. Pannamankuppalam Ancient Channel

72 4 480 4

330 " " 390 " " 55 8 " 3091 9

stone work 21 " "

channel 84 42 3 "

earthwork 11 8 "

new stone 84 3 15 "

78 5 "

Dr. Chinnasamudram Ancient

275 7 " 2837 15 11

1466 8 " 2041 11 2 266 2 6 2273 "

stone work 420 " "

brick 2 lines 20 " "

stone work 3 1 "

543 6 "

Dr. Dr. Dr. Tomb

115 " " 1256 "

952 11 2 1075 4 9 98 12 2 792 10 9

earthwork 150 9 "

stone 84 50 10 "

new 84 35 10 "

236 13 "

Dr. Pariyani Dr.

189 1 3 1507 15 1

1312 4 10 1185 15 4 173 5 5 1295 11 "

earthwork 77 4 4

new stone work 88 14 "

stone 84 35 15 "

217 1 4

Dr. Dr. Ancient Channel

6 4 4 18 8 2

" " 34 5 10 6 1 5 58 4 4

Dr. Aranganore Tomb

193 6 8 1567 11 10

1421 11 9 1475 8 9 192 2 7 1548 15 2

earthwork 195 14 8

stone 84 29 11 "

new 84 35 10 "

earthwork 11 11 6

for channel 272 15 2

Dr. Thiraganore Dr.

115 15 " 1076 2 11

857 " " 932 4 9 112 11 2 858 1 10

earthwork 154 7 10

stone 84 12 8 "

new 84 243 12 "

460 11 10

Dr. Ancient Channel

57 3 " 578 7 7

376 " " 322 4 9 43 7 3 325 11 8

channel 10 2 "

repair 1308 2 5 11

G. arampally Anicuttam		271	1463	1361	1340	248	1304	earth work 20	Repaired about
								Stone 8 30	4 years ago
								Brick 8 50	
								100	
D. Yendur		56	244	218	224	54	236	earth work 100	Repaired
								Stone 8 100	about 15 years
								200	ago
D. Pedannamang		40	192	187	189	30	143	Stone work 70	ago
								earth 8 70	
								140	
D. Kristnapuram Sank		186	575	557	545	186	575	earth work 80	D.
								Stone 8 20	
								100	
D. Kittayattumbully		7	34	2	2	7	34	earth work 50	Repaired about
								Stone 8 50	30 years ago
								100	
D. Vangorambully River Anicut		30	172	112	150	28	157	Stone work 50	Repaired 15-80 ago
D. Anicut		9	37	22	23	8	33	D. 20	D.
D. Kumbharabully Sank		1	1	4	6	1	1	earth work 50	Repaired about
								Stone 8 20	20 years ago.
								brick 8 10	
								80	
D. New Sank		4	14	12	14	4	14	earth work 30	D.
								Stone 8 7	
								Plaster 8 23	
								100	
D. Mulasamudram Sank		17	104	99	99	17	104	earth work 50	D. 15 years
								Stone 8 20	ago
								70	
D. Anicut		54	222	101	122	32	125	Stone work 48	12
D. Saramangalam Sank		61	326	169	196	45	207	earth work 70	
								Stone 8 25	
								Plaster 8 50	
								145	

124/190/11

mamphun/hazamombully Ballah			45	
Dr	Installation	Small	32	156
Dr	Poliam	Dr	35	180
Dr	Dr	Dr	14	37
Dr	Jamethabara	Small Tomb	23	119
Dr	Dr	Small	27	142
Dr	Dr	Dr	251	1119
Dr	Sivady	Dr	14	81
Dr	Amicet Channel		281	1007
Dr	Authomoss	Small	34	119
Dr	Suthravallapamam	Dr	34	89

101	102	10	105	Stone work for to bench	16	Not known
150	97	32	156	earthwork	10	Repaired
				Stone Dr	15	about 4 years
				Plaster Dr	30	ago
					55	
135	98	25	107	earthwork	5	Repaired
				Stone Dr	5	about 20
				Plaster Dr	20	years ago
					30	
35	31	13	32	earthwork	5	Dr
				Stone Dr	5	
				Plaster Dr	20	
					30	
99	96	23	119	Stone work	88	Not known when repaired
134	139	27	142	Dr	15	Repaired 4 yrs ago
985	1094	250	1114	To raise the		Kalingula repaired
				length of the link	2000	last year
40	46	9	42	earthwork	25	Repaired 20
				Stone Dr	10	years ago
					35	
819	1117	128	585	earthwork		Repaired
				Plaster work	2000	last year
Bring Muta	101	34	119	earthwork	10	Not known
Tomtomooange				Stone Dr	30	when repaired
known calculated					40	
Dr	32	23	58	earthwork	95	
				Stone Dr	15	Dr
					100	

Sum of all the changes made

248 8 2

100

1441 153 1495 158 224 66 1578 210

earthwork 208 15 6

Stone Dr 124 4

327 3 1

Dr. Voraahony Large Tank

89 35 13 220 " 9

Dr. Haroorprampally Tank
Dr. Pallathoni Dr.

339 3 3 340 15 20
183 6 5 135 8 5

Dr. Sarookaddy Dr.

93 37 9 481 8 4

Dr. Sombomadi Dr.

156 6 10 315 14 3

Dr. Paramathy Dr.

29 22 7 169 5 8

Dr. Yombomkolam Dr.

225 3 4 2738 10 1

Dr. Malathambor Ancient

101 13 15 395 2 3

591 8 6 1021 10 199 3 12 11408 3 south work 713 11 9

old stone 45 15 "

new stone 170 10 "

930 4 9

" " " 40 6 2 18 37 14 41 1 3 south work 888 2 "

old stone 8 392 "

new 8 829 14 "

1110 " "

202 15 9 256 11 11 118 37 1 337 12 7 south work 244 4 "

110 9 1 107 2 7 127 28 11 113 2 11 south work 141 1 6

old stone 43 12 "

new 8 75 4 "

260 1 6

271 2 1 329 11 5 27 33 1 219 5 5 south work 135 4 3

old stone 426 8 "

new 8 170 10 "

732 13 3

43 2 5 157 14 11 105 8 2 228 1 " south work 257 13 "

new stone 328 2 "

585 15 "

170 " " 128 10 4 29 22 7 169 5 8 new stone 70 8 "

brick work 52 14 "

123 6 "

598 8 1 591 12 11 164 31 9 1932 7 " south work 76 2 6

old stone 8 265 10 "

new 8 192 6 "

brick 8 52 8 "

584 10 6

242 4 2 279 13 1 72 7 1 213 10 7 old stone work 13 " 6

brick work 137 10 "

150 10 6

28731 6 11

Sanjapalove Taromafuthe Sank

44 14 10

557 7 5

494 10 2

387 7 3

99 14 10

557 7 5

Shine work 30 " "

earth work
for bond } 100 " "

Stone work 100 " "

Calingula 50 " "

300 " "

Dr. Jadayamoor

Dr.

53 28 10

315 5 2

316 2 7

322 11 9

53 98 10

315 5 2

Shine work 50 " "

bond Dr. 50 " "
100 " "

Dr. Nasaroesprum

Dr.

88 16 12

177 1 9

200 " 6

191 4 6

36 9 4

188 2 1

Calingula work 25 " "

earth Dr. 5 8 " "

Stone bond 1 4 "
3 1 12 "

Dr. Polayamuttan

Dr.

45 29 14

250 3 11

197 8 14

219 4 10

38 " 14

205 12 7

earth work 100 " "

Stone Dr. 100 " "

earth Dr. 100 " "

Stone Dr. 150 " "

Shine Dr. 50 " "
500 " "

Dr. Sitang

Dr.

41 21 14

210 11 4

163 1 8

210 5 10

40 38 13

207 8 7

earth work 50 " "

Stone Dr. 150 " "
bond
200 " "

Dr. Horatue

Dr.

18 14 9

90 5 9

45 " 11

72 3 "

18 9 9

89 12 7

earth work 150 " "

Stone bond 50 " "
200 " "

Dr. Chelarasputty

Dr.

61 17 1

274 6 5

186 5 1

181 8 5

55 14 12

245 10 3

Stone work 90 " "

Bond 40 " "
Repair of bond 50 " "
200 " "

122

30268 2 1

Toppaloo Shrivangama		Puttur Tunk	19 9 1	61 2 10	63 4 9	19 9 1	61 2 10	Southworth 67 8
								Stone 122
								179 8
De		De	Pala Tunk	17 21 4	51 12 8	46 8 1	17 21 4	Southworth 43 12
								Stone 84
								Stone 85
								Calingula 20 10
								133 8

Wanganay Komraputty	Nallak	100	372	163	246	100	372	300
De	Pannavore	15	47	12	24	15	47	200
De	De	13	41	20	18	8	27	150
De	Kadamodeputty	12	37	15	20	8	26	100
De	Soreyempetty	10	30	18	21	8	27	100
De	Murraponeputty	14	43	21	26	7	20	50
De	Thimmarachetty	8	28	11	19	5	7	30
De	Kachanamputty	3	17	11	12	3	17	30
De	Putthanthamm	25	79	13	13	9	28	40
De	Katuputty	10	37	13	20	8	25	50
De	Shoppuruputty	5	15	1	8	4	13	25
De	Venkatathammputty	52	287	32	88	31	167	300 1815-1816
De	Thurupur Chappuruputty	9	34	18	26	4	17	70
De	Ammalamputty	9	59	46	46	8	45	50
De	Varigannoor	13	62	54	54	5	26	50
De	Puttavannoor	22	144	60	57	3	11	300
De	Valamputty	3	12	8	11	3	12	50
De	Munthepetty	1	2	2	2	1	2	30
De	Peringaralota	70	284	112	105			1200
De	Byamuttam	34	123	123	123	34	128	200
De	Kachanamputty	39	86	13	13	30	86	300
De	Hinnu	134	628	571	549	134	600	1500
De	De	3	3	1	5	3	5	50
De	Mannaruputty	14	47	21	32	12	41	100
De	Chinnamakuram	10	34	11	16	8	28	150
De	Yelchappadiaputty	29	90	28	14	18	57	200
De	Thundikupam	9	41	15	24			150
De	Vellaputty	13	54	32	41	12	53	200
De	Narayandikupam	14	53	29	27	13	62	300

utensory thalium putty sluice	7	21
D. Thiruvanniputhy Tank	10	25
D. Manavanniputhy Tank & sluice	8	23
D. Chingulwady sluice	21	70
D. Chellaputhy D.	21	62
D. Thiruvanniputhy D.	40	125
D. Athokkareputty Tank	11	234
D. Alomalapuram Tank & bend of channel	11	56
D. Alapuram Tank & sluice	243	1167
D. D. Bend of ancient & digging channel	135	640
D. Manasse Tank & sluice	28	83

11	11	7	21	250
11	23	7	19	50
9	11	8	23	200
25	40	20	85	40
26	40	18	53	85
54	71	32	100	40
11	35	16	78	200
26	35	13	42	200
343	728	233	1082	600
194	433	124	571	400
9	31	24	14	30

D. Kuvraantharam Ancient	12	41
D. Salavaram Tank	14	53
D. Thirupaputhy D.	82	376
D. Agalakota D.	11	57
D. Madamuthukota D.	37	199
D. Polliankota D.	28	163
D. Thiruvanniputhy D.	37	144
D. Thiruvanniputhy D.	32	101

14	14	70	1866/67
		Stone 8 1/2 100	
		Lime 8 30	
		200	
32	24	7	28
		Stone 8 50	8 over repairs
		Lime 8 40	by circus
		140	
"	213	28	128
		Stone 8 350	12.17 July
		Lime 8 150	
		1000	
37	37	8	38
		Stone 8 60	1239 July
		Lime 8 60	
		200	
107	139	23	132
		Stone 8 20	July 1234
		Lime 8 40	
		90	
41	69	20	123
		Stone 8 20	Not known to
		Lime 8 30	have been repaired
		80	by circus
105	110	26	113
		Stone 8 50	1239
		Lime 8 50	
		130	
18	18	9	38
		Stone 8 15	Not under
		Lime 8 35	circus repair
		50	
		440	

at 05000 Narasabattam Same	9	53	9	53	earth work 20 "	Never under			
					Stone 80 "				
					Line 30 "	circum repair			
					80 "				
Dr. Shanabdar	Ja	13	48		earth work 20 "	30			
					Stone 20 "				
					Line 50 "	Ja			
					80 "				
Dr. Kommanipally	Ja	44	223	167	166	44	263	earth work 30 "	
								Stone 40 "	
								Line 35 "	20 years ago
								105 "	
Ja	Ja	18	37	11	20	30	37	earth work 50 "	Never under
								Stone 100 "	
								Line 30 "	circum repair
Dr. Pothannagaram	Ja							180 "	
		24	85	82	34	19	75	earth work 80 "	
								Stone 100 "	
								Line 50 "	Ja
								230 "	
Dr. Chennamangalam	Ja	13	230	80	141	59	208	earth work 100 "	
								Stone 100 "	
								Line 50 "	10 years ago
								250 "	
Dr. Somathiramanabally	Ja	22	131	95	100	16	96	earth work 100 "	
								Stone 100 "	
								Line 30 "	Family 1270
								200 "	
Dr. Bagalagondahalli	Ja	17	101	72	82	17	101	earth work 20 "	
								Stone 30 "	
								Line 50 "	Family 1265
								100 "	
Dr. Moramballi	Ja	11	49	7	10			earth work 70 "	Family 1272
								Stone 80 "	
								150 "	
Dr. Popur	Ja	9	54	57	52	8	50	earth work 30 "	Known to here
								Stone 40 "	
								Line 30 "	been repaired
								100 "	by circum sometimes
Dr. Bara Kankhalli	Ja	10	49	36	15	3	16	Stone work 80 "	about 15 years ago
Dr. Chennandahalli	Ja	138	867	676	572	105	654	earth work 150 "	Slightly
								Stone work 150 "	
								Line 100 "	repaired 10
								500 "	years ago
Dr. Saralahalli	Ja	7	28	23	18	5	22	earth work 60 "	Never repaired
								Stone 80 "	
								140 "	by circum

Open Archite Ancient and tank

Jr. Thammabhatti Tank

Jr. Bannikhatti Jr.

Jr. Sannathur Jr.

Jr. Annamandapam Ancient

Jr. Sannamhatti Tank

Jr. Bannhatti Jr.

Jr. Bannamhatti Ancient

Jr. Pallabhatti Tank

Jr. Upparayanhalli Jr.

Jr. Pannapam Jr.

16 " 61 "

49 " 326 "

32 " 250 "

10 " 28 "

12 " 69 "

25 " 110 "

17 " 98 "

97 " 646 "

69 " 407 "

19 " 94 "

57 " 57 " 2 " 12 " earth work 300 " " Repaired
Stone & 500 " " in 1286

20 " 21 " 7 " 20 " earth work 20 " " Not known
Stone & 30 " " to have been
lime & 30 " "

73 " 223 " 49 " 326 " earth work 50 " " repaired &
Stone & 200 " " years ago
lime & 50 " "

225 " 222 " 29 " 233 " earth work 70 " " Repaired 20
Stone & 80 " " years ago
lime & 50 " "

11 " 8 " 9 " 19 " earth work 25 " " Not known to
Stone & 75 " " have been

13 " 11 " 4 " 22 " earth work 30 " " slightly
lime & 25 " " repaired 15

57 " 75 " 21 " 97 " earth work 100 " " 35 " " years ago

57 " 75 " 21 " 97 " earth work 100 " " Jr.
Stone & 150 " "
lime & 80 " "

89 " 95 " 3 " 18 " earth work 200 " " Jr.
lime & 200 " "

475 " 308 " 66 " 438 " earth work 50 " " Jr.
Stone & 50 " "
lime & 50 " "

167 " 162 " 17 " 101 " earth work 100 " " Jr.
Stone & 50 " "
lime & 100 " "

27 " 33 " 8 " 39 " earth work 50 " " Not known to
Stone & 20 " " have been
lime & 25 " " repaired by civic

offen Mallasammudram Lank

24 . . 170 . . 85 . . 81 . . 14 . . 80 . . earth work 100 . . 8 P. known
Stone to 200 . . I have seen

Je. Pitthanadi Je.

19 . . 107 23 . . 18 . . 12 . . 73 . . southbank 150 . .
 drive 8 = 30 . .
180 . . J. H.

J. Adak Korm J.

[illegible]

Dr. Joesirihalli

28 . . . 131 . . . 74 . . . 92 . . . 9 . . . 41 . . . earth with 80 . . . Repaired about
stone & $\frac{150}{180}$. . . 15 years ago

D. Ullmannskai D.

76 " " 88 " " 31 " " 58 " " 6 " " 36 " " south end 10 " " Repaired about 6
 Stone Dr. 60 " " years ago.
 120 " "

J. Balur J.

24 " 72 " 30 " 52 " 20 " 78 " earth with 52 " " repaired about
stone = 150 " " 20 yrs ago.
drives = 20 "

220 "

Fr. Panjaballi. Sonke

212 . . . 870 . . . 241 . . . 302 . . . 11 . . . 81 . . . eastward 500 . . . Repaired about
Stone Dr 1000 . . .
Drined 100 . . . 20 years ago
1000
~~1000~~ . . .

Dr. Hermann Dr.

82 . . . 438 . . . 296 . . . 288 . . . 82 . . . 435 . . . can't work 120 . . . Repaired about
 time $\frac{200}{10}$ years ago
 320 . . .

Dr. Senkavayaprivanu Dr.

27 . . 134 . . 182 . . 132 . . 17 . . 86 . . embankment 50 . . Repaired some
stone or 20 : : time ago by
Lime 30 : :
207 . . across

Fr. Balikoran Fr.

10	55	38	24	5	29	cutt work 40	
						Stone 30	
						Lime 30	90
						130	

Dr. Taddariya sandham Dr.

45 " . 239 " . 85 " . 85 " . 18 " . 91 " . south west 100 " . Reported about
Stone & 100 " .
200 " . 15 years ago.

Dr. Sanyamballi Dr.

22 " " 110 " " 49 " " 66 " " 13 " " 77 " " south west 50 " " Dr.
 Drive 8 " 50 " "
 100 " "

Fr. Androm Fr.

38 " " 165 " " 181 " " 118 " " 26 " " 115 " " south west ho " "

Time & 80 " D
Lined }
140 " "

Dr. Kanda Kumballi Sank

8 " " 40 "

12 " " 38 "

8 " " 18 "

south wall 50 " " Repaired
Stone 84 100 " " about 15 years
Lime 84 50 " " 200 " " ago

Dr. Dr. Dr.

7 " " 17 "

south wall 60 " " not known
Stone 84 20 " " to have been
Lime 84 20 " " 100 " " repaired by owner

Dr. Dr. Dr.

17 " " 17 "

59 " " 36 " " 15 " " 60 " " south wall 90 " " about 20
Stone 84 100 " " years ago
Lime 84 35 " " 225 " "

Dr. Sandarai Dr.

78 " " 542 "

251 " " 232 " " 34 " " 246 " " south wall 80 " " Repaired about
Stone 84 120 " " 10 years ago
200 " "

Dr. Dr.

Dr. Mankarun Dr.

43 " " 243 "
14 " " 72 "

107 " " 136 " " 15 " " 78 " " Stone wall 300 " " Dr.
60 " " 54 " " 13 " " 45 " " south wall 60 " " Repaired:
Stone 84 70 " " about 15
Lime 84 50 " " 180 " " years ago

Dr. Dr.

14 " " 64 "

44 " " 40 " " 10 " " 50 " " south wall 100 " " Dr.
Stone 84 100 " " 200 " "

Dr. Mankasivarandur Dr.

39 " " 239 "

194 " " 209 " " 34 " " 224 " " south wall 300 " " Dr.
Stone 84 200 " " Dr.
Lime 84 100 " " 500 " "

Dr. Jankuricotta Dr.

58 " " 247 "

139 " " 195 " " 46 " " 240 " " south wall 50 " " Repaired
Stone 84 100 " " about 10
150 " " years ago

Dr. Dr.

10 " " 44 "

34 " " 29 " " 7 " " 11 " " south wall 50 " " Dr.
Stone 84 50 " " 100 " "

Dr. Anjattolugam Dr.

7 " " 27 "

16 " " 11 " " " " " " south wall 60 " " Repaired
Stone 84 40 " " about 20
1111 " " years ago

Dr. Jakkani Dr.

23 " " 120 "

73 " " 33 " " 18 " " 90 " " south wall 100 " " Dr.
Stone 84 50 " " 150 " "

Dr. Kanda Kumballi Dr.

4 " " 25 "

8 " " 11 " " 3 " " 18 " " south wall 30 " " Dr.
Stone 84 20 " " 50 " "

Dr. Kondakomballi Sank

40

Dr. Dr. Dr.

7 17

Dr. Dr. Dr.

17 17

Dr. Sandorai Dr.

78 562

Dr. Dr. Dr. Mankann Sank

68 243
14 72

Dr. Dr. Dr.

14 64

Dr. Mankasibavandur Dr.

39 239

Dr. Jankinicolta Dr.

58 247

Dr. Dr. Dr.

10 44

Dr. Arjattobragam Dr.

7 27

Dr. Jakkani Dr.

23 120

Dr. Kaduttomballi Dr.

4 25

231

12 38 3 11 south wall 30 " " Repaired
Stone 3 100 " " about 45 years
Lime 3 50 " " ago
200 " "

" " " " " " south wall 50 " " Not known
Stone 3 20 " " to have been
Lime 3 20 " " 100 " " repaired by circon

59 36 15 60 south wall 90 " " About 20
Stone 3 100 " " years ago
Lime 3 85 " " 225 " "

151 232 36 266 south wall 80 " " Repaired about
Stone 3 120 " " 10 years ago
200 " "

107 136 15 78 Stone wall 300 " " Dr.
110 54 13 65 south wall 60 " " Repaired:
Stone 3 70 " " about 15
Lime 3 50 " " years ago
180 " "

44 60 10 50 south wall 100 " " Dr.
Stone 3 100 " " 200 " "

194 209 34 224 south wall 300 " " Dr.
Stone 3 200 " " Dr.
Lime 3 100 " " 500 " "

139 195 41 210 south wall 50 " " Repaired
Stone 3 100 " " about 10
150 " " years ago

34 29 7 11 south wall 50 " " Dr.
Stone 3 50 " " 100 " "

16 16 " " " " south wall 100 " " Repaired
Stone 3 40 " " about 20
110 " " years ago

73 83 18 90 south wall 100 " " Dr.
Stone 3 50 " " 150 " "

5 11 3 18 south wall 30 " " Dr.
Stone 3 20 " " 50 " "

5556, 811

Open	Kimacammudram	Ancient	37	216	206	180	Stone work 300	Repaired		
							Drine 200	about 10 years		
							500	ago		
D ^r	Orumammakki	Tank	5	23			earth work 100	Does not appear		
							Stone 150	to have been		
							250	repaired by circuit		
D ^r	Saciradi	D ^r	159	775	696	493	91	455	earth work 50	Repaired about
									Stone 200	10 years ago
									Drine 30	
									280	
D ^r	Mottomaggaram	D ^r	8	26	16	16	4	9	earth work 100	
									Stone 200	D ^r
									300	
D ^r	Akaram	D ^r	15	90	26	28	14	88	earth work 50	
									Stone 70	D ^r
									Drine 100	
									220	220
D ^r	Skorai	D ^r	133	985	889	787	96	695	earth work 50	
									Stone 100	D ^r
									Drine 100	
									250	
D ^r	D ^r	Ancient	29	187	86	79	15	88	Stone work 400	Repaired
									Drine 200	20 years ago
									600	
D ^r	Songorhalli	Tank	173	1228	802	856	118	949	earth work 50	Repaired 10
									Stone 150	years ago
									Drine 150	
									350	
D ^r	Nakkudahalli	D ^r	28	148	19	126	17	99	earth work 20	Repaired
									Stone 30	8 years ago
									Drine 30	
									110	
D ^r	Sacirihalli	D ^r	25	116	96	98	25	116	earth work 100	Repaired 20
									Stone 90	years ago
									Drine 50	
									240	
D ^r	Songisetto	D ^r	9	58	56				earth work 50	Repaired
									Stone 50	in July 1255
									Drine 50	
									150	

Salem Collector's Office }
9th May 1867 }
3

Comp
B. L. L. L.
E. C. L. L.

263

L

The Secretary to the Board of Revenue
Madras

Charles Osborn
Collector

630242

1807

1807

Ordered that the
statement recd. with
this letter be forwarded
to the Supy Engineer of the
S.D., for communication to
the Works Officer concerned.

The works should be
planned for placing as many
of the irrigation works as
possible in a proper state
of repair from the budget
provision of Rs 26000 for "minor
works & channels" in
the Salween etc.

Grant St. George
15th June 1807