Proceedings of the Madras Government, Public Works Department,
11th December 1874.

No. 216. Read the following endorsement of the Chief Engineer for Irrigation, dated Quilon, 16th November 1874:—

From W. A. GOODCHAP, Esq., District Engineer, Kurnool, to Lieutenant-Colonel J. MULLINS, R.E., Chief Engineer for Irrigation, dated Camp at Bugga, Nundial Taluq, 30th October 1874, No. 26.

I HAVE the honor to enclose a list of tanks reported breached owing to the unusual heavy rainfall this year in the district, and to report that Range Officers have commenced emergent repairs in nearly every case in anticipation of sanction.

2. I beg to observe that the grant under head "Agricultural Repairs" for 1874-75 for this district will have to be supplemented, but as I have not yet received all the estimates for emergent work, I am not in a position to state correctly at present the actual addition required. I beg to inform you that the surplus weir to the Cumbum tank has been discharging freely this year, and it is reported that no water has passed over it for the last twenty years.

List of Tanks reported breached in the Kurnool District owing to the unusual heavy rainfall between July and October 1874.

No.	Taluq.	Name of Tank.	Remarks.
		Kurnool Range.	
1.	Ravalkota	Ratnapalle Tank	Breached.
2.	Do.	A small Cuntu at Lovingundla.	Do.
3.	Do.	Gudur Tanks (large and small).	Do.
4.	Do.	Narasapuram Tank	Just on the point of being breached, but repaired in time.
5.	Do.	Sarfarajapuram Tank... ...	Do. do.
6.	Nandikotkur	Motkur Tank	Breached.
7.	Do.	Dandagatla Tank	Do.
		Nundial Range.	
8.	Nundial	Chinna Devalapuram Tumma Tanks.	Breached in five places.
9.	Do.	Pedda do. Erra Tank ...	Do. in three do.
10.	Do.	Santajutur Santanapu Tank ..	Do. in two do.
11.	Do.	Kadamala Calva Tank ...	Do. in one place.
12.	Sirwell	Chinna Kambalur kotta chervu Tank.	Do. in one do.
13.	Do.	Do. Peddireddi Tank	Do. in one do.
14.	Do.	Gowtavaram Tank	Do. in one do.
15.	Do.	Kondamayapalle Chinna Raju Tank.	Do. in two places.
16.	Do.	Kotakonda kola Irjuna Tank...	Do. in one place.
17.	Do.	Nagalavaram Vengamapalle Tank.	Do. in one do.
18.	Do.	Rudravaram Rangareddi Tank.	Do. in one do.
19.	Do.	Thallalingamdinne Chintala Tank.	Do. in one do.
20.	Do.	Mutialpad Erra Tank ...	Do. in one do.
21.	Do.	Gangavaram Doku Tank ...	Just on the point of being breached, but repaired in time.
22.	Do.	Velagalapalle Gungama Tank.	Do. do. do.
23.	Do.	Chennur Iskapalle Dova Tank.	Do. do. do.
24.	Do.	Sirwell Nagala Tank	Do. do. do.

Proceedings of the Madras Government, Public Works Department,
11th December 1874.

No.	Taluq.	Name of Tank.	Remarks.
		Cumbum Rouge.	
25.	Cumbum	Gudimitta Tank	Just on the point of being breached, but repaired in time.
26.	Markapur	Madapi Annajeri large tank sluices.	Do. do. do.
27.	Do.	Thumbalapalle Tank Sluice ...	Do. do. do.
28.	Cumbum	Damara Tank	Do. do. do.
29.	Do.	Rangareddi Tank	Do. do. do.
30.	Markapur	Kakerla Tank...	Do. do. do.
31.	Do.	Budweed Tank	Do. do. do.
32.	Do.	Sunkasala Tank	Do do. do.
33.	Do.	Markapur Tank	Do. do. do.

CAMP AT PANIEM,
30th October 1874.

(Signed) W. A. GOODCHAP,
District Engineer, Kurnool.

SUBMITTED for the information of Government.

(Signed) JOHN MULLINS, Lieut.-Colonel, R.E.,
Chief Engineer for Irrigation.

No. 217. ORDER THEREON, 11th December 1874, No. 3,479.

IRRIGATION, No. 15.

RECORDED with the remark that early measures must be taken to prevent similar accidents in the future.

(True Extract.)

Colonel, R.E.,
Secretary to Government.

To the District Engineer, Kurnool.
„ Chief Engineer for Irrigation.

Exd. S. T. Austin.

Spare Copies

Heavy rain fall between July and October 1874.

The Kurnool District Engg to the Board

Remarks.

No	Taluq	Name of Tank	
		Kurnool Rouge	
1	Pauelkotta	Rachapalle Tank	Breached
2	do	Mamall Cuppa at Lingamalla	do
3	do	Pudur Tanks (Large & Small)	do
4	do	Narapuram Tank	Just on the point of being, breached, but repaired in time
5	do	Satyanjapuram Tank	do
6	Nandikotkur	Mottur Tank	Breached
7	do	Dunagarka Tank	do
		Nandial Rouge	
8	Nandial	Pinna Devalapuram Tanks	4 Breached
		Tanks	do
9	do	Poda Gra Tank	do

Contd

10	Naudial	Santajutiri Santanapu Tauk	Breached in 2 places		
11	do	Kadamala Calva Tauk	do	1	do
12	Cirwell	Chinna Kambalur Kotta cheruvu Tauk	do	1	do
13	do	do Peddireddi Tauk	do	1	do
14	do	Gowtavaram Tauk	do	1	do
15	do	Kondantayapalle Chenna Raju Tauk	do	2	do
16	do	Kotakonda Kola Dynna Tauk	do	1	do
17	do	Nagalavaram Pungana palle Tauk	do	1	do
18	do	Pudivavaram Ranyareddi Tauk	do	1	do
19	do	Kallalingamdinne Chintala Tauk	do	1	do
20	do	Innialpad Erra Tauk	do	1	do
21	do	Gangavaram Doki Tauk	Just on the point of being breached, but repaired in time.		
22	do	Velagalapalle Gungana Tauk	do		do
23	do	Chennur Ikkapalle Dora Tauk	do		do
24	do	Cirwell Nagula Tauk	do		do
		Kumbaum (Range			
25	Kumbaum	Gudimitta Tauk	do		do
26	Markapur	Madapi Annajeri large tank Sluices	do		do
27	do	Thimbalapalle Tauk Sluice	do		do
28	Kumbaum	Damara Tauk	do		do
29	do	Rangareddi Tauk	do		do
30	Markapur	Kakerla Tauk	do		do
31	do	Bidwad Tauk	do		do
32	do	Sunkasala Tauk	do		do
33	do	Markapur Tauk	do		do

District Engineer's Office
Camp Ponnem 30 October 1874.

L. A. Goodchap
District Engineer.

2

No. 26

District Engineer's Office,

Camp Bugga, Sandial Taluk

The 30 October 1874,

4

From,

The District Engineer,

Kurnool,

To,

The Chief Engineer

for Irrigation

Madras.

Enclosures, nil.

Subject. Tank Breached in the Kurnool District

Sir,

I have the honor to enclose a list of tanks reported breached owing to the unusual heavy rain fall this year in the District, and to report that -

Range Officers have commenced emergent repairs in nearly every case, in anticipation of sanction.

I beg to observe that the grant under head "Agricultural repairs" for 1874-75 for this District, will have to be supplemented, but as I have not yet received all the estimates for emergent work

Ry. 3.9.6/74.

No. 3719-11-12-74.

dt. 13 Nov. 1874.

I am not in a position to state correctly at present, the actual addition required.

I beeg to inform you that, the Surplus weir to the Kumbum tank has been discharging freely this year, and it is reported, that no water has passed over it, for the last 20 years.

I have the honor to be

Sir,

Your most Obedt Servt.

H. Goodchap

District Engineer.

5

P. W. [illegible] Dec. 1874
Pers. of Govt for Dec. 1874-75

From,

No: 7376

The District Engineer

Kurnool.

To,

The Chief Engineer
for Irrigation
Madras

No. 26

Dated 30th October
Despatched 4th November
Received 10th
-1874.

Recd: 23rd November 1874.

ENCLOSURES. IV

Subject. Regarding Tank Breaches in the Kurnool District.

Submitted for the information of Government

Colombakonis Lt Col RE
Quilon
16 November 1874

Recorded, with the remark that early measures to be taken to prevent similar accidents in future.

Dec. 16/11/74

3479

216-217.

7376

Govt. of 1874 Madras.

PUBLIC WORKS.

To The Dist. Supt. Kurnool

Dated

Read. Encl. 1

G. O., 11th Dec. 1874, No. 3479

Nos. 216-217.

Tanks - Letter from the Dist. Engr. Kurnool reporting the breaching of certain Tanks by the late heavy rains in excess of ordinary