(1) பக்கங்களின் எண்ணிக்கை 64

(2) புதுக்கித் திருப்பிய நாள் June 89

(3) ஆதாரங்குறிப்பவர் சுருக்கொப்பம்

தமிழ்நாடு ஆவணக் காப்பகம்.

தமிழ்நாடு அரசு

(73)

PWD துறை

அரசாணை எண். மு. கோப்புத் தாள் எண்.	1544 1545	அச்சகம் பலவகை
நாள் :	10-6 1889	~~198~~.

மடிக்கவோ கண்டபடி கையாளவோ கூடாது

32 Sheets [illegible]

Brief Sheet 1 Statement 1524.
(ex 8)

ஆவண, எ-1—18,000—15-6-87.

1544-45

Additions and alterations to be made in the Register of Military Buildings Bangalore Sub-Division for 1888-89.

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
	Page 19 Insert the following as item No. 105 ...														
105	Saddle and Store Room ...	...	...	Brick in mortar.	Stone slab.	Tiled and terraced.	Panelled.	44½	46	2,047	2 2 2	4,373	4,373	1888—89	European Cavalry Agram Barracks.
	Page 29 Agram Fortified Post. Substitute the following as items 13 and 14 ...														
13	Guard Room ...	...	...	Stone in mortar.	Do	Terrace.	Panelled & glazed.	52	34½	1,794	...	...			
14	Cook House. Fire Engine shed and latrine ...	...	...	Do	Do	Do	Panelled.	32	19	608 2,402	2 8 0	6,005	6,005	1888—89	...
	Page 27. Commissariat slaughter House ...														
	Insert the following as item No. 9 ...														
9	Quarters for the Station Butcher ...	I. W. O.	... I. W. O. with family.	Brick in chunam.	Granite ...	Mangalore tiled.	Teak.	42 17¾ 8½	30½ 14½ 8½	1,281 257 72 1,610	2 6 7	3,886	3,886	1888—89	Commissariat Department.
	Page 27. Colum 2. Item 5. For "Butchers Quarters" substitute the words ...														
	Store Rooms ...														
	Insert the accompanying form as the last sheet on the return as page 67 and 68 ...														

2

Additions and alterations to be made in the Register of *ilitary Buildings Bangalore Sub-Division for* 1888-89.

1	2	3	4	5	6	7
	Page 1 insert as item 7 A					
	Covered Gymnasium for European Infantry.	The Garrison of Fort St. George.	Wing British Infantry.	Brick in mortar.	Part loose coir, part planked and part port land cement.	Iron trusses teak rafters reepers and ceiling planked covered with Mangalore tiles.
	Page 3 Insert as item No. 39 A					
	R.A. Sergeants Mess and adjacent godowns Converting—into latrine and lavatory for-do ...	...	For single men.	Brick in Chunam.	As phalte.	Arched.
	Page 21 Substitute the following as item No. 1.					
1	Guard Room *Reconstruction of* ...	...	12	Brick in chunam.	As phalte.	Terraced.
	Insert at the bottom of pages 25 and 26					
	OLD VEPERY LINES.					
	LAND AND BUILDINGS PURCHASED FOR A COAL STORE.					
1	Staff Sergeants quarters ...	...	3	Brick in clay.	Square Bricks.	Tiled.
2	Place of arms ...	...	...	Brick in chunam.	Laterite stone.	Tiled.
3	Out Houses ...	...	3	Brick in clay.	Square Bricks.	do
4	Armourer Shop ...	...	...	do	do	do
	Page 55 insert as item 17					
17	Wheat Godown ...	...	...	Brick in chunam.	As phalte.	do

6

1544-45

8	9	10	11	12	13	14	15	16
Panelled.	44½	46	2,047	2 2 2	4,373	4,373	1888—89	European Cavalry Agram Barracks.
Panelled & glazed.	52	34½	1,794	...	...			
					6,005	6,005	1888—89	...
Panelled.	32	19	608 2,402	2 8 0				
Teak.	42 17¾ 8½	30½ 14½ 8½	1,281 257 72 1,610	2 6 7	3,886	3,886	1888—89	Commissariat Department.

4

1544-45

HUNSUR.

Public Cattle Depôt.

1	Warrant Officer's Quarters ...	1	1	Burnt brick in mud	Concrete.	Tiled.		Teak wood.	530	180	2244	0 8 0	1122	1385	Exact date not known but it would seem from enquiry that these buildings were constructed some 40 years ago.	Occupied by Medical Subordinate.
2	Out houses to do.	...	...	Mud walls.	Mud.	...		Jungle wood.	70	20	1400	0 3 0	263			
3	Farm Hospital	For 22 beds ...	12 beds	Brick in mortar.	Teak wood except verandah which has a concrete floor.	do		Teak wood.	$\frac{204+71}{2}$	162	3830	0 8 0	1940	2570		Patients.
	Out houses to do.															
4	Cholera shed	For 4		Brick in mud.	Side rooms concreted but centre portion of floor consists of mud	do		do	108	21	2268	0 3 0	425			
5	Cook house	...	...	Mud walls.	Mud.	do		...	29	23	667	0 3 0	125			
6	Latrine	...	...	Brick in mortar.	Concrete and tarred.	do		Teak wood.	16	16	256	0 5 0	80			

7

6

~~7~~

~~58~~

Statement of alterations and additions to be made in the Annual Return of Public Buildings, at the Station of Ranipet, for the Year ending 31st March 1889.

Number.				Name of Regiment in occupation.
1				16
	One Guard Room (item 8 of out buildings of European Barracks.)			Demolished

J. J. [illegible]
Executive Engr [illegible]
19-3-89

1544-65

Statement of alterations and additions to be made in the Annual Return of Public Buildings at the Station of Vellore, for the Year ending 31st March 1889.

Number.		Name of Regiment in occupation.
1		16
34	NO ALTERATIONS IN THESE COLUMNS.	Upper story used as a Combined Post and Telegraph Office and Lower story used as Post and Telegraph Masters quarters.
35		Pension Pay Office.

10

Executive Engineer

19-3-89

1844-45

1544-45

Correction Slip for the Return of Public Military Buildings at St. Thomas' Mount.

Number of Buildings.	After the words "West Barracks" insert the following below the line 7, column 2.			Insert the following below the line 7, column 5:—	Insert the following below the line 7, column 6:—	Insert the following below the line 7, column 7:—	Insert the following below the line 7, column 8:—
2	Coffee shop	....	....	Do. ..	Square bricks	Terrace and Tiles.	P. and V. ..
	Kitchen	....	....	Do. ..	Do. ..	Tiles ..	Batten-Door
	Score out the word "Station Female Hospital" in the 19th line, column 2, and insert the following:—						
88	Station Hospital for Soldiers' Wives and Children.						
84							

Insert the following below the line 7, column 9:—	Insert the following below the line 7, column 10:	Insert the following below the line 7, column 11:	Substitute the following for the line 1, column 12, 3 7 0:—	Substitute the following for the line 1, column 13, 2,17,670:—	Substitute the following for the line 1, column 14, 2,17,670:—	In column 15, below 7th line, insert the following:—	
58	52	3,016	3 6 10	2,24,540	2,24,540	1887	
15	13	195 }				Do.	
						Alter the word "Do." in the 8th line into	
2	7	14 }				1876	
		In column 11 for 62,221·75 substitute:					
		65,446·75					
							Insert the following in the 3rd line above "Commissariat Department" in column 16:—
							Demolished in December 1888.

Executive Engineer, Chingleput Division.

12

1544

Additions and alterations to be made in the Register of Military Buildings Madras Sub-Division for 1888-89.

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
	Page 1 insert as item 7 A														
	Covered Gymnasium for European Infantry.	The Garrison of Fort St. George.	Wing British Infantry.	Brick in mortar.	Part loose coir, part planked and part port land cement.	Iron trusses teak rafters reepers and ceiling planked covered with Mangalore tiles.	Teak-wood.	87′-6″	48′-9″	4,266	3 8 3	15,000	15,000	1888—89	Garrison British Infantry.
	Page 3 Insert as item No. 39 A														
	R.A. Sergeants Mess and adjacent godowns Converting—into latrine and lavatory for—do	...	For single men.	Brick in Chunam.	Asphalte.	Arched.	Teak.	52 36¼ 31	29¼ 29 26	3,378	1 0 5	3,480	3,480	1888—89	For single men:
	Page 21 Substitute the following as item No. 1.														
1	Guard Room *Reconstruction* of		12	Brick in chunam.	Asphalte.	Terraced.	Teak.	35¼	23	817	2 15 5	2,420	2,420	1888—89	Ordnance Department.
	Insert at the bottom of pages 25 and 26														
	OLD VEPERY LINES.														
	LAND AND BUILDINGS PURCHASED FOR A COAL STORE.														
1	Staff Sergeants quarters	...	3	Brick in clay.	Square Bricks.	Tiled.	Teak.	3×49′	43	6,321	1 3 5⅝	19,000	19,000	Oct. 1888	do
2	Place of arms	...	...	Brick in chunam.	Laterite stone.	Tiled.	Teak.	195	40	7,800					
3	Out Houses	...	3	Brick in clay.	Square Bricks.	do	do	75	13	975					
4	Armourer Shop	...	...	do	do	do	do	40	13	520					
	Page 55 insert as item 17														
17	Wheat Godown	...	...	Brick in chunam.	Asphalte.	do	do	38¾	23	891	1 12 5	1,583	1,533	1888—89	Commissariat Department.

14

18

Additions and alterations to be made in the Register of Military Buildings Madras Sub-Division for 1888-89.

1544-65

1	2	3	4	5	6	7
	Page 19 Insert the following as item No. 105 ...					
105	Saddle and Store Room ...	...	...	Brick in mortar.	Stone slab.	Tiled and terraced.
	Page 29 Agram Fortified Post. Substitute the following as items 13 and 14					
13	Guard Room ...	...	...	Stone in mortar.	Do	Terrace.
14	Cook House. Fire Engine shed and latrine ...	...	...	Do	Do	Do
	Page 27. Commissariat slaughter House ...					
	Insert the following as item No. 9 ...					
9	Quarters for the Station Butcher ...	I. W. O.	... I. W. O. with family.	Brick in chunam.	Granite ...	Mangalore tiled.
	Page 27. Colum 2. Item 6. For "Butchers Quarters" substitute the words ...					
	Store Rooms ...					
	Insert the accompanying form as the last sheet on the return as page 67 and 68 ...					

8	9	10	11	12	13	14	15	16
Teak-wood.	87'-6"	48'-9"	4,266	3 8 3	15,000	15,000	1888—89	Garrison British Infantry.
Teak.	52 36¼ 31	29¼ 29 26	3,378	1 0 5	3,480	3,480	1888—89	For single men.
Teak.	35¼	23	817	2 15 5	2,420	2,420	1888—89	Ordnance Department.
Teak.	3×49'	43	6,321	1 3 5⅜	19,000	19,000	Oct. 1888	do
Teak.	195	40	7,800					
do	75	13	975					
do	40	13	520					
do	88½	23	891	1 12 5	1,583	1,583	1888—89	Commissariat Department.

1544-65

HUNSUR.

Public Cattle Depôt.

1 Warrant Officer's Quarters ...	1	1	Burnt brick in mud	Concrete.	Tiled.	Teak wood.	530	180	2244	0 8 0	1122	1385	Exact date not known but it would seem from enquiry that these buildings were constructed some 40 years ago.	Occupied by Medical Subordinate.
2 Out houses to do.	...	...	Mud walls.	Mud.	...	Jungle wood.	70	20	1400	0 3 0	263			
3 Farm Hospital	For 22 beds ...	12 beds	Brick in mortar.	Teak wood except verandah which has a concrete floor.	do	Teak wood.	$\frac{204+74}{2}$	162	3880	0 8 0	1940	2570		Patients.
Out houses to do.														
4 Cholera shed	For 4 ...	...	Brick in mud.	Side rooms concreted but centre portion of floor consists of mud	do	do	108	21	2268	0 3 0	425			
5 Cook house	...	...	Mud walls.	Mud.	do	...	29	23	667	0 3 0	125			
6 Latrine	...	...	Brick in mortar.	Concrete and tarred	do	Teak wood.	16	16	256	0 5 0	80			

1564-65

Statement of alterations and additions to be made in the A ua Return of Public Buildings, at the Station of Ranipet, for the Year endin 31s March 1889.

Number.					Name of Regiment in occupation
1					16
	One Guard Room (item 8 of out buildings of European Barracks.)				Demolished

1564-65
21

20

Offg Executive Engineer
19-3-89

1544-45

Statement of alterations and additions to be made in the Annual Return of Public Buildings at the Station of Vellore, for the Year ending 31st March 1889.

Number.		Name of Regiment in occupation.
1		16
34	NO ALTERATIONS IN THESE COLUMNS.	Upper story used as a Combined Post and Telegraph Office and Lower story used as Post and Telegraph Masters quarters.
35		Pension Pay Office.

1544-45
~~H/173~~

27

6
~~15~~

J. J. [illegible]
Executive Engr. [illegible]
19-3-89

1546-45

Correction Slip for the Return of Public Military Buildings at St. Thomas' Mount.

Number of Buildings.	After the words "West Barracks" insert the following below the line 7, column 2.			Insert the following below the line 7, column 5:—	Insert the following below the line 7, column 6:—	Insert the following below the line 7, column 7:—	Insert the following below the line 7, column 8:—	Insert the following below the line 7, column 9:—	Insert the following below the line 7, column 10:	Insert the following below the line 7, column 11:	Substitute the following for the line 1, column 12, 5 7 0:—	Substitute the following for the line 1, column 13, 2,17,670:—	Substitute the following for the line 1, column 14, 2,17,670:—	In column 15, below 7th line, insert the following:—	
2	Coffee shop	....	....	Do. ..	Square bricks	Terrace and Tiles.	P. and V...	58	52	3,016	3 6 10	2,24,540	2,24,540	1887	
	Kitchen	....	....	Do. ..	Do. ..	Tiles ..	Batten-Door.	15	13	195 }				Do.	
														Alter the word "Do." in the 8th line into	
								2	7	14 }				1876	
										In column 11 for 62,221·75 substitute: 65,446·75					
	Score out the word "Station Female Hospital" in the 19th line, column 2, and insert the following:—														
66	Station Hospital for Soldiers' Wives and Children.														
84															Insert the following in the 3rd line above "Commissariat Department" in column 16:— Demolished in December 1888.

C. A. Burlton

Executive Engineer, Chingleput Division.

9

1544/75

From
The Executive Engineer
Chingleput Dn.

To,
The Superintg Engineer
Fifth Circle

Dated
Received } May 1859.

Statement showing the alterations and additions in the annual return of Military buildings at the Station of Poonamallee.

Nil

Executive Engr
Chd Dn

25

From 1-49-185

The Ex. Engineer
Chingleput Dn

To,

The Suptg Engineer
V Circle

Dated
Received } May/89

Statement showing
the alterations and
additions in the
annual return of
military buildings
at the station of
Poonamallee.

Nil

C A Muller
Ex: Engr
Chdn

26

AW
17-89

1574-45

From,

The Executive Engineer,
North Arcot Divn.

To

The Superintendg. Engr.
— 5th Circle —

Dated 19th March 1859 —

No.

Statement shewing alterations and additions to be made in the Return of Military Buildings at Arkonam for the year ending 31st March 1859 —

— Nil —

J. J. [illegible]
Executive Engineer
— North Arcot Div

27

1564-65

From The Executive Engineer
North Arcot Divn.

To
The Superintendg. Engr.
5th Circle

Dated 19th March 1859

No.

Statement shewing alterations and additions to be made in the Return of Military Buildings at Arkonam for the year ending 31st March 1859.

— Nil —

J. J. Whaley
Executive Engineer
North Arcot Divn.

78

544-65

From
The Ex: Engineer
Chingleput Dn

To,
The Supt. Engineer
4th Circle

Dated } May 1889
Received }

Statement shewing the alterations and additions in the annual return of military buildings at the station of Pallavaram.

Nil

C. D. Burlin
Ex: Engr. Chgt Dn.

17.5.89

87

From
1544-45
The Ex: Engineer
Chingleput Div.n

To,
The Supt.g Engineer
V Circle

Dated
Received } May/89

Statement shewing the alterations and additions in the annual return of Military buildings at the Station of Pallavaram.

Nil

C.G.W. Wheeler
Ex: Engr.
17.5.89 Ch. Div.n

30

MU
16.5.89

1544-65

SUPERINTENDING ENGINEER'S OFFICE,
V Circle, Madras,

No. 1476.

Chepâk, 3 June 1887.

From
Colonel W. H. Burton R.E.
SUPERINTENDING ENGINEER, V CIRCLE,

To
THE Chief Engineer
Public Works Deptt.

48 Enclosures.
30 statements
18 Nil Returns

SIR,

With reference to G. O. No. 2213 W. dated 19th August 1887, I have the honor to forward 6 copies, each, of the statements showing alterations and additions to be made in the Returns of Public Military Buildings at

Madras
Bangalore
Mount
Vellore &
Ranipett

for the year ending 31st March 1887. Nil Returns are sent for Poonamallee, Pallavaram and

31

and Arkonam in the Returns of which no changes have taken place during the year.. Copies of these statements & Nil Returns have been forwarded to the Quarter Master General and the Inspector General of Ordnance with reference to G.O. No. 2169 W dated 16th Septr/85 and G.O. No 17 W dated 5th Jany 1888.

I have the honor to be
Sir
Your most obedt Servant

Col. R.E.
Superintending Engineer
V Circle

5

PWC No: 50

From

THE SUPERINTENDING ENGINEER,
V CIRCLE,

(1)

To

THE Chief Engineer
P. W. Department

Dated 3? } June 1889
Recd. 5 }

Enclosures. 48.

No. 1476.

Returns of Public Buildings

Forwards 6 Copies

Each of the Statements

shewing alterations & addi-
-tions in –

(32)

Witteades

J.o. Bns 1847-49 W of 21-6-89.

No. 1544 W d/10 June

B

Ordered ~~that~~ four
Ordered that four
copies of each returns
Copies of each return
and the nil statement
and the nil statement
be forwarded to the
be forwarded to the
Govt of India
Govt of India.

A.G. No. 1545 W d/10 June 89

Forwarded
Forwarded

WWB
6.6.89

Phil
8.6.89

Cw
10/6/89

DaW
10/6

To the S. to the G of I.
To the S. to the G. of I.
Military Deptt
Military Deptt
with 4 enclos
with 4 enclos

Note. Enclos file
need not go to Dobe

O. I. Aysll 1576 .. 9 D 31/6